

AMACON

LIVE WELL

**Warranty Services
Work Order**

Phone: (905) 848-2069 Fax: (905) 848-2827

Location	<u>Eve - Tower: 1 - Unit: 2701</u> <u>2701 - 3515 Kariya</u>
Closing Date	0000
Date	02Feb09
Contact Name(s)	<u>Nam Ma</u>
Contact Telephone#	
Company:	<u>Amacon Service</u>
Attention:	<u>Carlos Bravo</u>
Telephone:	
Fax:	(905) 848-2827
From:	<u>Warranty Services Department - Head Office</u>

Please complete the following items:


Deficiency Number	Issue		Appointment Date/Time	Notes
8361	FOYER / ENTRY- WALLS-leftside facing entry door corner edge dented see tape	✓		
8362	FOYER / ENTRY- WALLS: 1-rightside of entry door paint touchup needed- see tape	✓		
8363	FOYER / ENTRY- WALLS: 2-rightside by bathroom entry dented - see tape	✓		
8368	LIVING/DINING ROOM- ELECTRICAL/LIGHTING: 1-telephone jack right wall needs to be straightened - see tape	✓		
8369	LIVING/DINING ROOM- WINDOWS-centre windowframe scratched left edge see tape	✓		
8370	LIVING/DINING ROOM- WALLS-wall surrounding balcony doors caulking messy -- in several spots - see tape	✓		
8371	LIVING/DINING ROOM- WALLS: 1-jmould surrounding balcony door needs touchups - see tape	✓		
8372	LIVING/DINING ROOM- WALLS: 2-baseboard to left of fancoil -- scratched see tape	✓		
8373	MASTER BEDROOM- WALLS-jmould by right bottom edge stained - see tape	✓		
8374	MASTER BEDROOM- WALLS: 1-jmould left bottom edge needs touchup - see tape	✓		
8375	MASTER BEDROOM- WALLS: 2-left edge by window above window ledge scratched see tape	✓		
8376	MASTER BEDROOM- WALLS: 3-hairline crack rightside by light switch floor to ceiling see tape	✓		
8377	MASTER BEDROOM- WALLS: 4-rightside by window above baseboard crack in wall see tape	✓		
8378	MASTER BEDROOM- DOORS-bedroom door not staying closed -- see tape	✓		
8379	MASTER BEDROOM- DOORS: 1-doorframe entering master dented rightside see tape	✓		
8380	MASTER BEDROOM- FLOORING-carpet needs to be steam cleaned - several spots	✓		
8383	MASTER BEDROOM- WINDOWS-leftside of master bedroom window frame scratched - see tape	✓		

8384	MASTER BEDROOM- WINDOWS: 1-rightside of master bedroom window frame scratched - see tape	✓		
8385	MASTER BEDROOM- WINDOWS: 2-centre of master bedroom window frame scratched - see tape	✓		
8386	MAIN BATHROOM- ELECTRICAL/LIGHTING-access panel below sink needs to closed -- see tape	✓		
8387	KITCHEN- CABINETS-left cabinet door below sink handle loose - see tape	✓		
8388	KITCHEN- ELECTRICAL/LIGHTING-light bulb burnt out in track lighting	✓		
8389	KITCHEN- WALLS-large crack on wall above fridge by right gable see tape	✓		
8390	LAUNDRY CLOSET- DOORS-door not closing properly - see tape	✓		
8477	MASTER BEDROOM- FLOORING-carpet needs to be steam cleaned - several spots	✓		

Date Completed:

FEBRUARY 21 09 8

Amacon Customer Care Signature:



Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative **must** have this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Back -
Forms
Menu

ID#

8361/8362/8363/8368/8369/8370/8371/8372/8373/8374/8375/8376/8377/8378/8379/8380/8383/8384/8385/8386/8387/8388/8389/8390/8477
Eve Ph 1 Lot 2701