

AMACON

LIVE WELL

Warranty Services
Work Order

Phone: (905) 848-2069 Fax: (905) 848-2827

| | |
|--------------------|---|
| Location | Eve - Tower; 1 - Unit; 708 708 - 3515 Kariya |
| Closing Date | 0000 |
| Date | 13Feb09 |
| Contact Name(s) | Robert Spiteri |
| Contact Telephone# | |
| Company: | Amacon Service |
| Attention: | Carlos Bravo |
| Telephone: | |
| Fax: | (905) 848-2827 |
| From: | Warranty Services Department - Head Office |

Please complete the following items:

| Deficiency Number | Issue | Appointment Date/Time | Notes |
|-------------------|---|-----------------------|--------------|
| 10826 | FOYER / ENTRY- WALLS-DRYWALL DENTED left of door, see tape | ✓ | |
| 10827 | FOYER / ENTRY- WALLS: 1-DRYWALL rough around security rough-in, see tape | ✓ | |
| 10828 | FOYER / ENTRY- WALLS: 2-DRYWALL DENTED top left corner of closet, see tape | ✓ | |
| 10829 | FOYER / ENTRY- WALLS: 3-DRYWALL DENTED to left of closet above baseboard, see tape | ✓ | |
| 10831 | FOYER / ENTRY- DOORS: 1-frame scratched, see tape | ✓ | |
| 10832 | FOYER / ENTRY- DOORS: 2-frame to right of door is rough, see tape | ✓ | |
| 10834 | FOYER / ENTRY- FLOORING-grout 2nd tile from closet, see tape | ✓ | |
| 10836 | LIVING/DINING ROOM- FLOORING-baseboard marked below balcony door, see tape | ✓ | |
| 10840 | LIVING/DINING ROOM- ELECTRICAL/LIGHTING: 1-plastic dented tri-light switch, see tape | ✓ | |
| 10841 | LIVING/DINING ROOM- WINDOWS-caulking rough along bottom and sides balcony, see tape | X | SDC electric |
| 10842 | LIVING/DINING ROOM- WINDOWS: 1-ALUMINUM marked above balcony door, see tape | ✓ | |
| 10844 | LIVING/DINING ROOM- CEILING-stiple rough above balcony, see tape | ✓ | |
| 10846 | LIVING/DINING ROOM- CEILING: 1-stiple not finished properly along right wall | ✓ | |
| 10848 | LIVING/DINING ROOM- WALLS-paint patchy below cable outlet, see tape | X | |
| 10849 | LIVING/DINING ROOM- WALLS: 1-seams showing and paint patchy, drywall dented, see tape | ✓ | |
| 10850 | LIVING/DINING ROOM- WALLS: 2-baseboard not joined properly, right wall, see tape | ✓ | |
| 10851 | LIVING/DINING ROOM- WALLS: 3-paint chipped to left of bathroom door, see tape | ✓ | |
| 10852 | LIVING/DINING ROOM- WALLS: 4-DRYWALL DENTED to left of bathroom, see tape | ✓ | |
| 10853 | LIVING/DINING ROOM- WALLS: 5-DRYWALL rough below thermostat, see tape | ✓ | |
| 10854 | LIVING/DINING ROOM- WALLS: 6-DRYWALL DENTED to left of bedroom door, see tape | ✓ | |
| 10855 | LIVING/DINING ROOM- WALLS: 7-drywall missing to right of balcony door, see tape | ✓ | |
| 10856 | MASTER BEDROOM- WALLS-J-mold marked, right side of window, see tape | ✓ | |
| 10857 | MASTER BEDROOM- WALLS: 1-J-mold painted top of left window, see tape | ✓ | |
| 10858 | MASTER BEDROOM- WALLS: 2-seam showing left wall, see tape | ✓ | |
| 10859 | MASTER BEDROOM- WALLS: 3-marks/scratches left wall see tape | ✓ | |
| 10860 | MASTER BEDROOM- WALLS: 4-drywall scratched/patchy back wall, see tape | ✓ | |
| 10861 | MASTER BEDROOM- WALLS: 5-right corner at closet paint chipped, see tape | ✓ | |
| 10862 | MASTER BEDROOM- WALLS: 6-nailpop in baseboard to right of window, see tape | ✓ | |
| 10863 | MASTER BEDROOM- WALLS: 7-chip in baseboard to right of window, see tape | ✓ | |
| 10864 | MASTER BEDROOM- WALLS: 8-paint chipped corner to right of window, see tape | ✓ | |
| 10865 | MASTER BEDROOM- FLOORING-CLEAN CARPET | ✓ | |
| 10867 | MASTER BEDROOM- CEILING-top corner right window stiple missing, see tape | ✓ | |
| 10869 | MASTER BEDROOM- CLOSET-scratches inside door, left side, see tape | ✓ | |
| 10870 | MASTER BEDROOM- ELECTRICAL/LIGHTING-telephone jack crooked, see tape | ✓ | |
| 10871 | DEN- WALLS-DRYWALL DENTED at entrance, left side, see tape | ✓ | |
| 10872 | DEN- WALLS: 1-DRYWALL chipped at cable outlet, see tape | ✓ | |
| 10873 | DEN- WALLS: 2-marks on walls, see tape | ✓ | |
| 10874 | DEN- WALLS: 3-DRYWALL DENTED to right of telephone jack, see tape | ✓ | |
| 10875 | DEN- FLOORING-scratches on boards, see tape | ✓ | |
| 10878 | DEN- ELECTRICAL/LIGHTING-air vent not flush, left side | ✓ | |
| 10879 | MAIN BATHROOM- WALLS-discoloration to left of towel bar, see tape | ✓ | |
| 10880 | MAIN BATHROOM- WALLS: 1-crack behind toilet at plumbing, see tape | ✓ | |
| 10881 | MAIN BATHROOM- WALLS: 2-DRYWALL DENTED to right of mirror, see tape | ✓ | |
| 10882 | MAIN BATHROOM- DOORS-marks on inside casing, see tape | ✓ | |
| 10883 | MAIN BATHROOM- DOORS: 1-frame rough, right side, see tape | ✓ | |
| 10884 | MAIN BATHROOM- DOORS: 2-gap top right outside corner, see tape | ✓ | |
| 10885 | MAIN BATHROOM- TUB-silicone around showerhead, faucet and tap, see tape | ✓ | |