AMACON

LIVE WELL

Warranty Services Work Order Phone: (905) 848-2069 Fax:(905) 848-2827

| Location | Eve - Tower: 1 - Unit: 908 |
|--------------------|--|
| | 908 - 3515 Kariya |
| Closing Date | 0000 |
| Date | <u>13Feb09</u> |
| Contact Name(s) | Leah Maio |
| Contact Telephone# | |
| Company: | Amacon Service |
| Attention: | Carlos Bravo |
| Telephone: | |
| Fax: | (905) 848-2827 |
| From: | Warranty Services Department - Head Office |

| Please complete the following items: | | | |
|---|-----------|---------------|---|
| Deficiency Issue | | Appointmen | r Notes |
| | | Date/Time | |
| 11685 V FOYER / ENTRY- WALLS-marks on wall top right corner of door, see tape | | | |
| 11686 - EOYER / ENTRY-WALLS: 1-mark to left of closet, see tape | 1/ | | |
| 11687 FOXER / ENTRY- WALLS: 2-DRYWALL DENTED right side of closet, see tape | V | | |
| 11688 FOYER / ENTRY- DOORS-scratches around door frame, see tape | | | |
| 1689 FOYER / ENTRY- DOORS: 1-door doesn't latch properly | ·/ | | |
| OYER / ENTRY- CEILING-touch up stiple bulkhead above entrance and above closet | _X | | |
| 1692 V FOYER / ENTRY- CLOSET-access panel not flush | | | |
| 1693 FOYER / ENTRY- CLOSET: 1-valance above closet scratched, see tape | ركا | 1 | |
| 1697 VING/DINING ROOM- ELECTRICAL/LIGHTING: 1-scratches and paint on air vent, see tape | | | |
| 1698 LIVING/DINING ROOM-ELECTRICAL/LIGHTING: 2-fancoil unit door scratched, see tape | | II | |
| 1690- LIVING/DINING ROOM- ELECTRICAL/LIGHTING: 3-filter missing inside fancoil unit | X | | |
| LIVING/DINING ROOM- WINDOWS-ALUMINUM frame scratched around balcony door and window aboye balcony door | | | |
| LIVING/DINING ROOM- WINDOWS: 2-screws missing, balcony door hinges | X | | |
| 1703 LIVING/DINING ROOM-WINDOWS: 3-ALUMINUM panel right of balcony door scrATCHED, see tape | V | | |
| LIVING/DINING ROOM- WINDOWS: 4-panel to right of balcony door gap along top, excessive silicone along/right edge and at bottom of panel, see tape | √ | | |
| LIVING/DINING ROOM- WINDOWS: 5-ALUMINUM THRESHOLD dented, see tape | X | | |
| 1786-4 LIVING/DINING ROOM- CEILING-stiple edges rough around all walls | Į Ž | | |
| 1707 LAYING/DINING ROOM- WALLS-marks to right of laundry closet, see tape | | | |
| 1708 / VIVING/DINING ROOM- WALLS: 1-corner chipped bottom left of bedroom door, see tape | | | |
| 1709 LIVING/DINING ROOM- WALLS: 2-DRYWALL DENTED right wall, are tape | 1 | | |
| LIVING/DINING ROOM- WALLS: 3-seams showing and paint patchy, right wall, see tape | | | , a |
| LIVING/DINING ROOM- WALLS: 4-seams showing and paint patchy left wall | | | Painter to real |
| 1712 LYING/DINING ROOM- WALLS: 5-DRYWALL DENTED to right of window, see tape | 1 | | To tente |
| 713 / IVING/DINING ROOM- WALLS: 6-wall below sill at balcony door dented, see tape | V | | |
| 714 V LIVING/DINING ROOM- WALLS: 7-baseboard chipped, right wall, see tape | V | | |
| MASTER BEDROOM- WALLS-seams showing, left wall | <u> Y</u> | | printers to reper |
| MASTER BEDROOM- WALLS: 1-DRYWALL DENTED, bottom corner, left wall, in front of window, see tape | V | | 100000000000000000000000000000000000000 |
| 717 MASTER BEDROOM- WALLS: 2-DRYWALL DENTED/rough right wall, bottom corner in front of window, see tape | V | | |
| 718 MASTER BEDROOM- WALLS: 3-marks on left wall in front of closet, see tape | 1 | | |
| MASTER BEDROOM- WALLS: 4-J-mold discolored top left window, see tape | | | |
| 720 MASTER BEDROOM- WALLS: 5-paint on electrical panel, see tape | | | |
| 721 MASTER BEDROOM- WALLS: 6-marks to left of closet, see tape | | | |
| MASTER BEDROOM- WALLS: 7-baseboard below cable scrATCHED, see tape | | | |
| 723 MASTER BEDROOM- WALLS: 8-gap at baseboard behind door, see tape | | | |
| MASTER BEDROOM- DOORS-bottom and top edge of door chipped, see tape | V | | |
| MASTER BEDROOM- DOORS: 1-dent centre front panel, see tape | | | |
| 726 MASTER BEDROOM- CEILING-stiple rough uneven alOng all walls | X | - | |
| DEN- WALLS-DRYWALL DENTED to right of telephone jack, see tape | | | |
| 729 DEN- WALLS: 1-DRYWALL DENTED back wall, see tape | | | |
| DEN- WALLS: 2-baaeboard chipped, ack wall, see tape | | - | |
| 731 DEN- CEILING-stiple rough along all sides | × | | |
| MAIN BATHROOM- WALLS-access panel inside vanity scratched, see tape | | | |
| MAIN BATHROOM- WALLS: 1-mark to right of outlet, see tape | | | |
| MAIN BATHROOM- WALLS: 2-baseboard in front of vanity, right side, see tape | | - | |
| Tamey, right orac, see upo | <u> </u> | | |

| 1. | | . / | . . | | ., |
|-------|--|------|--------------|----------|----|
| 11736 | MAIN BATHROOM- WALLS: 3-wall behind toilet not painted, see tape | | ļ | | |
| 11737 | MAIN BATHROOM- WALLS: 4-gap at quarter round behind door at casing, see tape | | | | |
| 11738 | 38 MAIN BATHROOM- DOORS-handle pitted, inside, see tape | | | | |
| 11739 | MAIN BATHROOM- DOORS: 1-interior casing dented, left side, see tape | | | | |
| 11740 | MAIN BATHROOM- DOORS: 2-crack under upper hinge, see tape | | | | |
| 11741 | MAIN BATHROOM- TUB-silicone around showerhead, tap and faucet, see tape | | | | |
| 11742 | MAIN BATHROOM- TUB: 1-grout cracked, see tape | V | | | |
| 11744 | MAIN BATHROOM- TUB: 2-mark on front panel centre near bottom, see tape | ·/ | | | |
| 11745 | MAIN BATHROOM- TUB: 3-caulk top of tiles, at wall, rear of tub, see tape | | | | |
| 11746 | MAIN BATHROOM- TUB: 4-caulking needed rear of tub at tile, see tape | | | | |
| 11747 | MAIN BATHROOM- TOILET-flange for plumbing at wall not attached, see tape | / يا | | | |
| 11748 | MAIN BATHROOM- TOILET: 1-scratches on top lip, see tape | a | | Risi | |
| 11753 | MAIN BATHROOM- FLOORING-paint on tile, right side of vanity, see tape | V | | | |
| 11754 | MAIN BATHROOM- FLOORING: 1-paint on tile in front of and behind toilet, see tape | | | | |
| 11755 | KITCHEN- FLOORING-clean grout | V | | | |
| 11759 | KITCHEN- CABINETS: 3-paint top of caSING to left of microwave, see tape | | | | |
| 11768 | LAUNDRY CLOSET- DOORS-jamb at upper hinge dented see tape | | | <u> </u> | |
| 11769 | LAUNDRY CLOSET- DOORS: 1-jamb, left side bubbled/rough, see tape | | | ł | |
| 11770 | LAUNDRY CLOSET- DOORS: 2-casing chipped above door, see tape | | | | |
| 11790 | DEN- WALLS: 3-DRYWALL DENTED at entrance to den, both sides, see tape | | | / | |

Date Completed: FEB 14 2009

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Back -Forms 11685/11686/11687/11688/11699/11692/11693/11697/11698/11699/11700/11702/11703/11704/11705/11706/11707/11708/11709/11710/11711/11712/11713/11714/11715/11716/11717/11718/ Menu