

AMACON DEVELOPMENT

AMACON SERVICE REQUEST FORM

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5J3B1

TEL: 416-369-9069 FAX: 416-369-9068

ATTENTION CUSTOMER CARE: 3515 KARIYA DR.

TEL: 905-848-2069 FAX: 905-848-2827
(905) 232-4636 (416) 369-9068

NAME: PU PU SHAW SUITE # 3505

DEVELOPMENT NAME: _____ ADDRESS: 3515 KARIYA DR.

RES. TEL: 647-889-1778 BUS. TEL: _____ CELL: _____

FAX: 905-232-8584 EMAIL: _____

DATE OF REQUEST: _____

SERVICE REQUEST:

1. entrance door scratch is on
2. the door, near box
3. _____
4. some floor pop up
5. _____
6. _____
7. _____
8. _____
9. you have my permission to enter the
10. suite at any time

Communication
x 1st level co
POD: 6/23/2011
- ON POD
x 1st level agent
original copy for
1st level sub
entry
AW
03/01/2011

Deficiency History Lot:3505 EVE - Phase: 1

<u>Work Order Date</u>	<u>Type</u>	<u>Deficiency Description</u>	<u>Trade</u>	<u>Close Date or Status</u>	<u>Days Open</u>
<u>25Feb10</u>	1 Year	Kitchen- dish washer control panel damaged	Whirlpool Canada	04Jun10	99
<u>25Feb10</u>	1 Year	Laundry Room- washer scratched on front panel	Whirlpool Canada	04Jun10	99
<u>25Feb10</u>	1 Year	Kitchen- fridge door dented, dishwahr control panel is damaged, W/D front panel is scratched, all this items from PDI	Whirlpool Canada	07Jun10	102
<u>25Feb10</u>	1 Year	Main Hall- big gap in the hardwood	Barwood Flooring	31Mar10	34
<u>25Feb10</u>	1 Year	Master Bedroom- bedroom door will not close	Amacon Service	30Mar10	33
<u>25Feb10</u>	1 Year	Foyer- floor is not even	Barwood Flooring	31Mar10	34
<u>25Feb10</u>	1 Year	Dining Room- one board is sticking out near the dinning room	Barwood Flooring	31Mar10	34
<u>25Feb10</u>	1 Year	Foyer- entrance door scratched	Amacon Service	31Mar10	34
<u>25Feb10</u>	1 Year	Foyer- gaps in front door	Amacon Service	08Mar10	11
<u>11Nov09</u>	Customer Service Request	Bedroom #3- window screen missing	Allan Windows	20Apr10	160
<u>11Nov09</u>	Customer Service Request	Living Room- gap in floor between second bedroom and main bath	Barwood Flooring	16Dec09	35
<u>19Feb09</u>	PDI	FOYER / ENTRY- WALLS-inside closet door right corner paint touchup needed - see tape	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	FOYER / ENTRY- WALLS: 1-left wall on entering by light switch black marks - see tape	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	FOYER / ENTRY- DOORS-O.K.	Amacon - PDI - OK	20Feb09	1
<u>19Feb09</u>	PDI	FOYER / ENTRY- FLOORING-O.K.	Amacon - PDI - OK	20Feb09	1
<u>19Feb09</u>	PDI	FOYER / ENTRY- CEILING-O.K.	Amacon - PDI - OK	20Feb09	1
<u>19Feb09</u>	PDI	FOYER / ENTRY- CLOSET-O.K.	Amacon - PDI - OK	20Feb09	1
<u>19Feb09</u>	PDI	FOYER / ENTRY- ELECTRICAL/LIGHTING-O.K.	Amacon - PDI - OK	20Feb09	1
<u>19Feb09</u>	PDI	LIVING/DINING ROOM- FLOORING-marks on floor centre by entry - see tape	Amacon Service	18Aug09	180
<u>19Feb09</u>	PDI	LIVING/DINING ROOM- FLOORING-marks on floor centre by entry - see tape	Barwood Flooring	18Aug09	180
<u>19Feb09</u>	PDI	LIVING/DINING ROOM- FLOORING: 1-flooring entering bedrooms moves - see tape	Barwood Flooring	04Mar09	13
<u>19Feb09</u>	PDI	LIVING/DINING ROOM- FLOORING: 2-gaps in flooring by kitchen entry - see tape	Barwood Flooring	04Mar09	13
			Barwood		

<u>19Feb09</u>	PDI	LIVING/DINING ROOM- FLOORING: 3-scratched boards by centre window - see tape	Flooring	04Mar09	13
<u>19Feb09</u>	PDI	LIVING/DINING ROOM- FLOORING: 4-marks on floor by window - see tape	Barwood Flooring	04Mar09	13
<u>19Feb09</u>	PDI	LIVING/DINING ROOM- ELECTRICAL/LIGHTING-O.K.	Amacon - PDI - OK	20Feb09	1
<u>19Feb09</u>	PDI	LIVING/DINING ROOM- WINDOWS-window sill nail pop and excessive caulking - see tape	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	LIVING/DINING ROOM- WINDOWS: 1-window aluminum casing scratched corner rightside of balcony door - see tape	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	LIVING/DINING ROOM- CEILING-ceiling hallway by heat sensor airholes - see tape	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	LIVING/DINING ROOM- CEILING-ceiling hallway by heat sensor airholes - see tape	Gem King	13Apr09	53
<u>19Feb09</u>	PDI	LIVING/DINING ROOM- CEILING: 1-2ft from left wall airhole and stipple missing	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	LIVING/DINING ROOM- CEILING: 1-2ft from left wall airhole and stipple missing	Gem King	13Apr09	53
<u>19Feb09</u>	PDI	LIVING/DINING ROOM- CEILING: 2-centre of ceiling stipple damaged	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	LIVING/DINING ROOM- CEILING: 2-centre of ceiling stipple damaged	Gem King	13Apr09	53
<u>19Feb09</u>	PDI	LIVING/DINING ROOM- CEILING: 3-hallway by master bath airhole see tape	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	LIVING/DINING ROOM- CEILING: 3-hallway by master bath airhole see tape	Gem King	13Apr09	53
<u>19Feb09</u>	PDI	LIVING/DINING ROOM- WALLS-left corner wall by dishwasher black marks	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	LIVING/DINING ROOM- WALLS: 1-dented wall between sink and stove by upper cabinet - see tape	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	LIVING/DINING ROOM- WALLS: 2-left wall by guest bedroom wall rough - see tape	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	LIVING/DINING ROOM- WALLS: 3-entering livingroom from hall right corner edge dented - see tape	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	LIVING/DINING ROOM- WALLS: 4-left wall paint rough - see tape	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	GUEST BEDROOM 1- WALLS-hole in wall by left window sill - see tape	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	GUEST BEDROOM 1- WALLS: 1-baseboard chipped right wall below outlet - see tape	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	GUEST BEDROOM 1- WALLS: 2-bulkhead cracked above right window - see tape	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	GUEST BEDROOM 1- WALLS: 3-hole in wall by double window top left corner - see tape	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	GUEST BEDROOM 1- WALLS: 4-cracked by j mould left short window - see tape	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	GUEST BEDROOM 1- WALLS: 5-wall by left small window paint rough - see tape	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	GUEST BEDROOM 1- WALLS: 6-baseboard inside closet chipped - see tape	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	GUEST BEDROOM 1- WALLS: 7-wall above cable outlet black marks - see tape	Amacon Service	13Apr09	53

<u>19Feb09</u>	PDI	GUEST BEDROOM 1- DOORS-O.K.	Amacon - PDI - OK	20Feb09	1
<u>19Feb09</u>	PDI	GUEST BEDROOM 1- FLOORING-carpet stained need cleaning	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	GUEST BEDROOM 1- FLOORING-carpet stained need cleaning	T & A Cleaning	13Apr09	53
<u>19Feb09</u>	PDI	GUEST BEDROOM 1- CEILING-airholes in ceiling by entry and light recepticle	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	GUEST BEDROOM 1- CEILING-airholes in ceiling by entry and light recepticle	Gem King	13Apr09	53
<u>19Feb09</u>	PDI	GUEST BEDROOM 1- CLOSET-O.K.	Amacon - PDI - OK	20Feb09	1
<u>19Feb09</u>	PDI	GUEST BEDROOM 1- ELECTRICAL/LIGHTING-O.K.	Amacon - PDI - OK	20Feb09	1
<u>19Feb09</u>	PDI	GUEST BEDROOM 1- WINDOWS-O.K.	Amacon - PDI - OK	20Feb09	1
<u>19Feb09</u>	PDI	GUEST BEDROOM 2- WALLS-small left wall by closet cracked - see tape	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	GUEST BEDROOM 2- WALLS: 1-nail inside closet top right - see tape	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	GUEST BEDROOM 2- WALLS: 2-water damage by bottom left of window sill - see tape	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	GUEST BEDROOM 2- WALLS: 3-baseboard chipped far right corner by closet door - see tape	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	GUEST BEDROOM 2- WALLS: 4-black marks right wall entering - see tape	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	GUEST BEDROOM 2- WALLS: 5-baseboard chipped right wall behind door - see tape	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	GUEST BEDROOM 2- DOORS-door chipped bottom left - see tape	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	GUEST BEDROOM 2- FLOORING-carpet stained needs cleaning - see tape	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	GUEST BEDROOM 2- FLOORING-carpet stained needs cleaning - see tape	T & A Cleaning	13Apr09	53
<u>19Feb09</u>	PDI	GUEST BEDROOM 2- CEILING-airholes in ceiling by light recepticle	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	GUEST BEDROOM 2- CEILING-airholes in ceiling by light recepticle	Gem King	13Apr09	53
<u>19Feb09</u>	PDI	GUEST BEDROOM 2- CLOSET-O.K.	Amacon - PDI - OK	20Feb09	1
<u>19Feb09</u>	PDI	GUEST BEDROOM 2- ELECTRICAL/LIGHTING-O.K.	Amacon - PDI - OK	20Feb09	1
<u>19Feb09</u>	PDI	GUEST BEDROOM 2- WINDOWS-aluminum frame -leftside excessive caulking and metal sticking out - see tape	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	MASTER BEDROOM- WALLS-below window small hole needs caulking - see tape	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	MASTER BEDROOM- WALLS: 1-bulkhead centre dented - see tape	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	MASTER BEDROOM- DOORS-O.K.	Amacon - PDI - OK	20Feb09	1
<u>19Feb09</u>	PDI	MASTER BEDROOM- FLOORING-carpet needs to be cleaned - see tape	Amacon Service	13Apr09	53

<u>19Feb09</u>	PDI	MASTER BEDROOM- FLOORING-carpet needs to be cleaned - see tape	T & A Cleaning	13Apr09	53
<u>19Feb09</u>	PDI	MASTER BEDROOM- CEILING-O.K.	Amacon - PDI - OK	20Feb09	1
<u>19Feb09</u>	PDI	MASTER BEDROOM- CLOSET-O.K.	Amacon - PDI - OK	20Feb09	1
<u>19Feb09</u>	PDI	MASTER BEDROOM- ELECTRICAL/LIGHTING-O.K.	Amacon - PDI - OK	20Feb09	1
<u>19Feb09</u>	PDI	MASTER BEDROOM- WINDOWS-O.K.	Amacon - PDI - OK	20Feb09	1
<u>19Feb09</u>	PDI	DEN- WALLS-O.K.	Amacon - PDI - OK	20Feb09	1
<u>19Feb09</u>	PDI	DEN- FLOORING-O.K.	Amacon - PDI - OK	20Feb09	1
<u>19Feb09</u>	PDI	DEN- CEILING-O.K.	Amacon - PDI - OK	20Feb09	1
<u>19Feb09</u>	PDI	DEN- ELECTRICAL/LIGHTING-O.K.	Amacon - PDI - OK	20Feb09	1
<u>19Feb09</u>	PDI	MAIN BATHROOM- WALLS-O.K.	Amacon - PDI - OK	20Feb09	1
<u>19Feb09</u>	PDI	MAIN BATHROOM- DOORS-O.K.	Amacon - PDI - OK	20Feb09	1
<u>19Feb09</u>	PDI	MAIN BATHROOM- TUB-O.K.	Amacon - PDI - OK	20Feb09	1
<u>19Feb09</u>	PDI	MAIN BATHROOM- TOILET-O.K.	Amacon - PDI - OK	20Feb09	1
<u>19Feb09</u>	PDI	MAIN BATHROOM- CEILING-dent on ceiling by fan - see tape	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	MAIN BATHROOM- CEILING-dent on ceiling by fan - see tape	N/A	13Apr09	53
<u>19Feb09</u>	PDI	MAIN BATHROOM- SINK-O.K.	Amacon - PDI - OK	20Feb09	1
<u>19Feb09</u>	PDI	MAIN BATHROOM- COUNTERTOPS-banjo countertop left corner big chip - see tape	Cartier Kitchens	17Mar09	26
<u>19Feb09</u>	PDI	MAIN BATHROOM- VANITY CABINETS-O.K.	Amacon - PDI - OK	20Feb09	1
<u>19Feb09</u>	PDI	MAIN BATHROOM- FLOORING-O.K.	Amacon - PDI - OK	20Feb09	1
<u>19Feb09</u>	PDI	MAIN BATHROOM- ELECTRICAL/LIGHTING-O.K.	Amacon - PDI - OK	20Feb09	1
<u>19Feb09</u>	PDI	ENSUITE BATHROOM- WALLS-top left of inside door paint touchup needed - see tape	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	ENSUITE BATHROOM- DOORS-O.K.	Amacon - PDI - OK	20Feb09	1
<u>19Feb09</u>	PDI	ENSUITE BATHROOM- TUB-silicon needed on temperature , spout and showerhead - see tape	Amacon Service	13Apr09	53
<u>19Feb09</u>	PDI	ENSUITE BATHROOM- TUB: 1-toe kick missing - see tape	Cartier Kitchens	17Mar09	26
<u>19Feb09</u>	PDI	ENSUITE BATHROOM- TOILET-O.K.	Amacon - PDI - OK	20Feb09	1
<u>19Feb09</u>	PDI	ENSUITE BATHROOM- SINK-O.K.	Amacon - PDI -	20Feb09	1

			OK			
<u>19Feb09</u>	PDI	ENSUITE BATHROOM- COUNTERTOPS-banjo countertop chipped leftside - see tape	Cartier Kitchens	30Mar10	404	
<u>19Feb09</u>	PDI	ENSUITE BATHROOM- COUNTERTOPS-banjo countertop chipped leftside - see tape	Amacon Service	30Mar10	404	
<u>19Feb09</u>	PDI	ENSUITE BATHROOM- CEILING-O.K.	Amacon - PDI - OK	20Feb09	1	
<u>19Feb09</u>	PDI	ENSUITE BATHROOM- VANITY CABINETS-O.K.	Amacon - PDI - OK	20Feb09	1	
<u>19Feb09</u>	PDI	ENSUITE BATHROOM- FLOORING-O.K.	Amacon - PDI - OK	20Feb09	1	
<u>19Feb09</u>	PDI	ENSUITE BATHROOM- ELECTRICAL/LIGHTING-access panel needs to be sealed	Amacon Service	13Apr09	53	
<u>19Feb09</u>	PDI	KITCHEN- FLOORING-O.K.	Amacon - PDI - OK	20Feb09	1	
<u>19Feb09</u>	PDI	KITCHEN- CABINETS-O.K.	Amacon - PDI - OK	20Feb09	1	
<u>19Feb09</u>	PDI	KITCHEN- COUNTERTOPS-O.K.	Amacon - PDI - OK	20Feb09	1	
<u>19Feb09</u>	PDI	KITCHEN- SINK-silicon needed around sink - see tape	Amacon Service	13Apr09	53	
<u>19Feb09</u>	PDI	KITCHEN- APPLIANCE-fridge dented see tape	Canadian Whirlpool Services	30Mar10	404	
<u>19Feb09</u>	PDI	KITCHEN- APPLIANCE: 1-dishwasher does not close	Amacon Service	30Nov09	284	
<u>19Feb09</u>	PDI	KITCHEN- ELECTRICAL/LIGHTING-O.K.	Amacon - PDI - OK	20Feb09	1	
<u>19Feb09</u>	PDI	KITCHEN- CEILING-light recepticle dented needs more stipple	Amacon Service	13Apr09	53	
<u>19Feb09</u>	PDI	KITCHEN- WINDOWS-O.K.	Amacon - PDI - OK	20Feb09	1	
<u>19Feb09</u>	PDI	KITCHEN- BACKSPLASH-O.K.	Amacon - PDI - OK	20Feb09	1	
<u>19Feb09</u>	PDI	KITCHEN- WALLS-wall above balcony step paint touchup - see tape AROUND	Amacon Service	13Apr09	53	
<u>19Feb09</u>	PDI	KITCHEN- WALLS: 1-baseboard nail pop in eating area - see tape	Amacon Service	13Apr09	53	
<u>19Feb09</u>	PDI	LAUNDRY CLOSET- NOTE-washer dented and large scratched - see tape	Canadian Whirlpool Services	30Mar10	404	
<u>19Feb09</u>	PDI	LAUNDRY CLOSET- DOORS-O.K.	Amacon - PDI - OK	20Feb09	1	
<u>19Feb09</u>	PDI	LAUNDRY CLOSET- WALLS-left wall black marks - see tape	Amacon Service	13Apr09	53	
<u>12Jan09</u>	Quality Control	Main Bathroom- cut out shelf for access panel	Cartier Kitchens	17Mar09	64	

Total Reported Deficiencies: 122 / Average Days Open: 49

Customer Info