

Suite 3603

Homeowner is complaining of water penetration upon heavy driving rain. This caulking deficiency has been noted as observed from the 35th floor balcony. This is not a weep hole. Weep holes are as designed. This could be a contributing factor in the homeowners reported leak.

July 3rd, 2012



Suite 3603

Homeowner is complaining of water penetration upon heavy driving rain. This caulking deficiency has been noted as observed from the 35th floor balcony. This is not a weep hole. Weep holes are as designed. This could be a contributing factor in the homeowners reported leak.


July 3rd, 2012



Eve 3515
Suite:3603

Homeowner is complaining of water penetration upon heavy driving rain. This caulking deficiency has been noted as observed from the 35th floor balcony, This is not a weep hole. Weep holes are as designed. This could be a contributing factor in the homeowners reported leak.


July 3rd.2012



Eve 3515
Suite:3603

Homeowner is complaining of water penetration upon heavy driving rain. This caulking deficiency has been noted as observed from the 35th floor balcony, This is not a weep hole. Weep holes are as designed. This could be a contributing factor in the homeowners reported leak.


July 3rd.2012



Eve 3515
Suite:3603

Homeowner is complaining of water penetration upon heavy driving rain. This caulking deficiency has been noted as observed from the 35th floor balcony, This is not a weep hole. Weep holes are as designed. This could be a contributing factor in the homeowners reported leak.


July 3rd.2012



Eve 3515
Suite:3603

Homeowner is complaining of water penetration upon heavy driving rain. This caulking deficiency has been noted as observed from the 35th floor balcony. This is not a weep hole. Weep holes are as designed. This could be a contributing factor in the homeowners reported leak.


July 3rd.2012



Suite 3603

Homeowner is complaining of water penetration upon heavy driving rain. This caulking deficiency has been noted as observed from the 35th floor balcony. This is not a weep hole. Weep holes are as designed. This could be a contributing factor in the homeowners reported leak.


July 3rd 2012



Suite 3603

Homeowner is complaining of water penetration upon heavy driving rain. This caulking deficiency has been noted as observed from the 35th floor balcony. This is not a weep hole. Weep holes are as designed. This could be a contributing factor in the homeowners reported leak.

July 3rd 2012



Eve 3513
Suite:3603

Homeowner is complaining of water penetration upon heavy driving rain. This caulking deficiency has been noted as observed from the 35th floor balcony. This is not a weep hole. Weep holes are as designed. This could be a contributing factor in the homeowners reported leak.

July 3rd, 2012



Eve 3513
Suite:3603

Homeowner is complaining of water penetration upon heavy driving rain. This caulking deficiency has been noted as observed from the 35th floor balcony. This is not a weep hole. Weep holes are as designed. This could be a contributing factor in the homeowners reported leak.

July 3rd, 2012



File:3513
Suite:3603

Homeowner is complaining of water penetration upon heavy driving rain. This caulking deficiency has been noted as observed from the 35th floor balcony. This is not a weep hole. Weep holes are as designed. This could be a contributing factor in the homeowners reported leak.

July 3rd 2012



File:3513
Suite:3603

Homeowner is complaining of water penetration upon heavy driving rain. This caulking deficiency has been noted as observed from the 35th floor balcony. This is not a weep hole. Weep holes are as designed. This could be a contributing factor in the homeowners reported leak.

July 3rd 2012



Eve 3515
Suite:3603

Homeowner is complaining of water penetration upon heavy driving rain. This caulking deficiency has been noted as observed from the 35th floor balcony. This is not a weep hole. Weep holes are as designed. This could be a contributing factor in the homeowners reported leak.

July 3rd 2017



Eve 3515
Suite: 3603

Homeowner is complaining of water penetration upon heavy driving rain. This caulking deficiency has been noted as observed from the 35th floor balcony. This is not a weep hole. Weep holes are as designed. This could be a contributing factor in the homeowners reported leak.


July 3rd 2017



File 3311
Suite 3603

Homeowner is complaining of water penetration upon heavy driving rain. This caulking deficiency has been noted as observed from the 35th floor balcony. This is not a weep hole. Weep holes are as designed. This could be a contributing factor in the homeowners reported leak.

July 3rd 2012



File 3311
Suite 3603

Homeowner is complaining of water penetration upon heavy driving rain. This caulking deficiency has been noted as observed from the 35th floor balcony. This is not a weep hole. Weep holes are as designed. This could be a contributing factor in the homeowners reported leak.

July 3rd 2012

