

TECHNICAL MEMORANDUM

Project No. 13-1121-0083 (1046)

DATE May 30, 2018

Erin O'Connor, MCIP, RPP
Leitrim South Holdings Inc.

0

FROM Christine Ko, P.Eng

EMAIL Christine_Ko@golder.com

GEOTECHNICAL REVIEW OF PROPOSED SITE GRADING PATHWAYS RESIDENTIAL DEVELOPMENT – PHASE 1 4800 BANK STREET OTTAWA, ONTARIO

intended purpose of a detailed table for each lot/block. geotechnical recommendations pertaining to the grading of this site, and as described below fulfills the same residential development located at 4800 Bank Street in Ottawa, Ontario. This memo provides our review and the proposed site grading, including a summary table for each individual lot/block, for Phase 1 of the Pathways It is understood that Leitrim South Holdings Inc. has been requested to provide a detailed geotechnical review of

Subsurface Conditions

dated January 2017 (report number 13-1121-0083 (1046)). titled "Geotechnical Investigation, Proposed Residential Development, Remer and Idone Lands, Ottawa, Ontario" Golder Associates previously carried out a geotechnical investigation for this proposed development and the results of that investigation were provided in a report to Leitrim South Holdings Inc. and 4840 Bank Street Ltd.

two of the test holes (i.e., TP16-15 and TP 1). is in turn underlain by bedrock. Localized thin layers of silty clay were encountered below the peat or topsoil at topsoil or peat (at the western portion of the site) overlying sands, silts, and followed by bouldery glacial till, which Based on the results of the geotechnical investigation, in general, the subsurface conditions on this site consist of

generally increasing in depth from east to west The depth to the bedrock surface varies from about 2 to greater than 7 metres below the ground surface

Grading Plan Review

Pathways site. It is the presence and strength of a silty clay deposit that typically imposes grade raise restrictions In other words, silty clay soils were not encountered in areas where structures are being proposed on the corner of the site, which is designated as a "No Touch Zone" (i.e., no structures will be constructed in this area). located just outside of the northwest boundary of the site, whereas TP 1 is located within the extreme southwest on a development site As mentioned above, localized layers of silty clay soils were encountered only in TP 16-15 and TP 1. TP 16-5 is

Golder Associates Ltd. 1931 Robertson Road, Ottawa, Ontario, K2H 5B7, Canada

Canada

T: +1 613 592 9600 F: +1 613 592 9601

practical restrictions for the thickness of grade raise fill that may be placed within the proposed residential Based on the above and as noted in the geotechnical report, from a foundation design perspective there is no development area.

Golder Associates has reviewed the following grading plans prepared by IBI Group for this site

Grading Plan, Project No. 33956, Drawing Nos. 200 to 205, Revision 8, Revised April 13, 2018

preparation of a summary table for each individual lot/block is deemed not necessary. basis for Phase 1 is not relevant in view of the subsurface conditions at the Pathways site and therefore point of view. As such, detailed grading and underside of footing elevation review on a lot-by-lot or block-by-block Golder Associates' report from a grading perspective and therefore considered acceptable from a geotechnical Upon review, the grading plans were found to be in general accordance with the recommendations provided in

Closure

We trust that this memo provides sufficient information for your present requirements. If you have any questions concerning this memo, please don't hesitate to contact the undersigned

Yours truly,

GOLDER ASSOCIATES LTD

Geotechnical Engineer Christine Ko, P.Eng. P.F.C.KO STANSON SON 1108/mm 00103970

Paul Smolkin, P.Eng

CK/PAS/mvrd

n:lactive\2013\1121 - geotechnica\13-1121-0083 remer and idone lands\phase 1046 remer detailed design\07-memos\techmem-002 detailed grading review\final_rev1\13-1121-0083-m-rev1-grading relivew-30may2018.docx

