PDI Print Form



PDĬ Page 1 of 1

III TARION Z45586

Inspection Date: 21 Apr 2013

Vendor/Bailder#

Purchaser Name : Phone Res : Phone Bos : Closing Date:

Darren Caston (705) 322-0101 (705) 322-2092 2013-04-25 Bruno Tidd

Enrollment# Legal Address: Project: Plan#:

DLS[19] Pratt Hansen Group

Let / Phase #: Meniclaplity: 43208 / Building43

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition.

Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS).

Please initial all changes and deletions As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

Windows, side lights and other glazing. Window and door screens

Bathtub sinks and toilors

· Bathroom accessories if provided

Mirrors, counter tops and cabinetry
Flooring (hardwood, vinyl, ceramic tites, carpeting)
Interior finished and trun carpentry
Furnace

Hot water heater, if provided (not rental)
 Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

 Windows, interior and exterior doors including garage overhead doors, door **Jocks**

· Faucets: Kitchen, bathroom, laundry room

Exhaust fans (kitchen, bathrooms) if provided
 Electrical outlets and fixtures

 Gas fireplaces, incl. circulation fans, if provided Heat Recovery Ventilation system, if provided

· Heating system

Hot water heater, if provided (not rental)

· Air conditioning system, if provided and if conditions permit

Also list here anything that can't be assessed because for example is duty or inaccessible. GENERAL COMMENTS INSPECTION STARTED AT 11:00 A.M. ** PURCHASER HAS A INSPECTION START TIME NEW PHONE NUMBER -705-322-2092

TOUCH UPS REQUIRED THROUGH OUT AS INDICATED NOTE:

MASTER ENSUITE BATH VANITY CABINETS LEFT OCOR CHIPPED RIGHT DOOR SCRATCHED.

KITCHEN LOWER CABINETS UNDER SINK NOT FLOSH. SHELF NOT LOWER CABINETS UNDER SINK NOT FLOSH. SHELF NOT INSTALLED IN NLOWER NEXT TO BANK OF DRAWERS. UPPER CABINET THIRD TO LEFT OF FRIDGE OPENING HAS SCREW IKSIDE THAT IS NOT SKEWED IN PROPERLY. UPPER CABINET 2ND TO RIGHT OF STOVE CHIPPED RICK PLATE NOT INSTALLED UNDER BANK OF DRAWERS. CABENETS

GRANITE EDGE IN FRONT OF SINK SCRATCHED. SERM TO RIGHT OF STOVE NOT FLUSH.

EXTERIOR

NOTE:

COUNTERTOPS

SOFFIT AT TOP LEFT SIDE OF BALCONY NOT SCREWED IN.

RECEIVED APR 2 2 2013

S
ilder

31001-PDIF-01.01