1434 RANKIN

ONHW-PDIF-01.01





Pre-Delivery Inspection Form

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any "substitutions" of items referred to in, or to be selected under, the Agreement of Purchase and Sale (APS), Please initial all changes and deletions, As a minimum check the following:

DAMAGED, INCOMPLETE OR MISSING	OPERATING CONDITION	
Windows, side lights and other glazing. Window and door screens Bathtubs, sinks and toilets Bathroom accessories, it provided Mirrors, countertops and cabinetry Flooring (hardwood, vinyl, ceramic tiles, carpeting) Interior finishes and trim carpentry Furnace Hot water heater, if provided (not a rental) Exterior finishes, driveways, walkways, decks and landscaping are complete	 Windows, interior and exterior doors (including garage overhead door). Door locks Faucets: kitchen, bathroom, laundry room Exhaust fans (kitchen, bathrooms), if provided Electrical outlets and fixtures Gas fireplaces, incl. circulation fans, if provided Heat Recovery Ventilation system, if provided Heating system Hot water heater, if provided (not a rental) Air conditioning system, if provided and if conditions permit 	

	ents AUTUMS YMMO	K 1/4M1//
	# Room/Location	Description
1	EXTERIOR	MAXING/CAUCIENG ON 200 FLOOR WINDOW
2	EXPERION	BRILL & UNIONAL TOURY UP ON ANNO SINE OF HOME
3	EXTERIUR	TOTHERES POST AT MISSISHE - CONSISTING BONN
3	ESTERIOR	STORE & MURAL DUCH UP ON PIWE LANT
4	ENERIOR	METURE FREDE MISSIM SHORIE
5	EXERIN	IDUE IN FOUNDATION FOR MAIN CONDUST'
		(MEEDS MILINA)
6	ENERTOR	OSB SPRING CONDUT FROM WALL - OSB NEEDS
_		TO DE TRIMMED
<u>7.</u>	EXPERIOR	DXY BRUK LEDGE TO BE REMINED.
8.	EXECUSE	ORADING, SUD, STANES OFF NORK, ANDED
-	1.000	WINDEWAY TO BE COMPLETED
9_	BARAGE,	USHT DOESN'T WORK (LEGG SIDE)
10.	FACIASUFFIT	SCREW HALF WAY INSORDED
		BONING ON LEFT SIDE OF AUX
	Kan a Char A	NOT LEVEL ASONE MAIN KEDR
4.	FROM PORUA.	MORDAN NEEDED POSVE SILL (FRONG WINDOW).
12	IMPLIOR	CARPED NOT UNIPLEDED.
13	Williams	PATELA MEDODO ARIVAD ATTIL HATCH.
14	INTERTOR	CLEANING NOT COMPLET.
 	IMPRIOR.	MIRRORS MILSTAG TAROUTHOUT.
LD_	PNEWIE	SUBUBIT NEEDS TRAM, CAVULING & PART
	MAIN BASH	GAP BETWEEN TILE & BISEDICARD
18	BED \$3 ENDIE	LEAST FOOTURE NOT SEVEE TO WORL,
10	OMB CO	TRUM TO BE TO MADO UP & PAINED.
19	STOTIL COSE	UNDAMED & MIGHT CARPET RUMPOR.
U	STATILITY TO BY	SEMBING -UNDOL-STAPPE ACCESS DEMAN FOR
71	monara -	MODES SANOING, PRIMAL & STIPPLE
17	BUNKAN C	WINKUM WISHNE POL HINGE
12	INFONTA	AL COUNTY TO BE CHANGED.
4	INTERLION	THE CUIDITO HER NO INSTALLED.
P	MARNA	TOUM TO BE TOURISH UP & PRIMED THROUGHOUS
1 2	NYTHIN	AMISHED END MISSING ON PANTLY
		. Whi 100 3 40R1!
	0.4	

VOK #SWWI PARILING,



OCT 1 4 2008
PAGE #2

Pre-Delivery Inspection Form

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any "substitutions" of items referred to in, or to be selected under, the Agreement of Purchase and Sale (APS), Please initial all changes and deletions, As a minimum check the following:

DAMAGED, INCOMPLETE OR MISSING **OPERATING CONDITION** • Windows, side lights and other glazing. Window and door screens • Windows, interior and exterior doors (including garage overhead · Bathtubs, sinks and toilets door). Door locks • Bathroom accessories, it provided • Faucets: kitchen, bathroom, laundry room · Mirrors, countertops and cabinetry · Exhaust fans (kitchen, bathrooms), if provided · Flooring (hardwood, vinyl, ceramic tiles, carpeting) · Electrical outlets and fixtures · Interior finishes and trim carpentry · Gas fireplaces, incl. circulation fans, if provided • Furnace Heat Recovery Ventilation system, if provided • Hot water heater, if provided (not a rental) Heating system Exterior finishes, driveways, walkways, decks and landscaping are · Hot water heater, if provided (not a rental) complete · Air conditioning system, if provided and if conditions permit

OUBLAS TOLMOSLE Description KUK NPEDS MOJUSTNAM