DAMAGED, INCOMPLETE OR MISSING



## **Pre-Delivery Inspection Form**

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any "substitutions" of items referred to in, or to be selected under, the Agreement of Purchase and Sale (APS), Please initial all changes and deletions, As a minimum

**OPERATING CONDITION** 

• Bat • Bat • Mire • Floe • Inte • Fur • Hot	htubs, sinks and toilets hroom accessories, it provided rors, countertops and cabinetry oring (hardwood, vinyl, ceramic erior finishes and trim carpentry nace	Exhaust fans (kitchen, bathrooms), if provided     Electrical outlets and fixtures     Gas fireplaces, incl. circulation fans, if provided     Heat Recovery Ventilation system, if provided     Heating system	
	erior finishes, driveways, walkw nplete 	<ul> <li>Hot water heater, if provided (not a rental)</li> <li>Air conditioning system, if provided and if conditions permit</li> </ul>	
Commen	ats NOUBLAS TRI	IMBLE. / JOHNS	
Item #	Room/Location	Description	
_/_	BEORISM	SCREEN MISSING /MIRRICOD SUPER MISSING	
2	BISEMENT BAY	SCREEN MISSING/VANITY & MIRREN MISSING	_
3_	BATTAKAM	SHOWER POUR NEEDS ADJUSTMENT	
		BLACK MANCHES ON SHOWER FRAME	
		CAULLING ON TRIM @ YOP.	
4	LOWER ENTRY	DARIC STANN/OULY ON CALPET.	
5_	IMERYUR	# TO UCH - UPS, TAROUSH-OUT.	
6_	IMERIUR	VANITY, CASIMOS & SCREENS MISSING	
1	BOORDOM #2	CRANK MISSING THROUGH-OUT.	
B	EXTERIOR	DRITEWAY PARED	
9'	ROBUN	MACIA, SIGHTE TO RE COMPLETED. (PAVESTRUBHS).	
10	EXTERLUNC	PATUL MESTED ON KNINGATUNG BOTTOM OF	
1.		6 KRAGE KONA	
11	ETERION	BRULLIOGI NEEDED @ PEAK	
12	EXPORTAL	HOUSE NUMBER PLATE MISSING.	
			_
			_
			_
			_
			_
1			_