STATUTORY WARRANTY FORM



Year-End Form

TO NOTIFY TARION OF OUTSTANDING WARRANTY ITEMS, COMPLETE AND SUBMIT THIS FORM IN THE FINAL 30 DAYS OF THE FIRST YEAR OF POSSESSION OF YOUR HOME.

YOU MAY SUBMIT ONLY ONE YEAR-END FORM.

Send a copy of the completed Form to your Builder and keep a copy for yourself

Home Identification Information (Refer to your Certificate of Completion and Possession to complete this box.)

Check this box if you are not the original registered homeowner.		he r.	Check this box if you are not the original registered homeowner.
Email Address	Email /		Email Address
84.lima.nuno@gmail.com	84.lim		caroline.jv.lima@gmail.com
mber	Fax Number		Fax Number
Evening Phone Number	Evenin		Evening Phone Number
4169933307	41699		4168562276
Daytime Phone Number	Daytim		Daytime Phone Number
4169933307	41699		(416)856-2276
Homeowner's Name (if applicable)	Homeo		Homeowner's Name
Lima	Nuno Lima		Caroline Lima
		vner(s):	Contact Information of Homeowner(s):
Project/Subdivision Name	Lot#	Postal Code	City/Town
51M-1149	36N	L9S 0N4	INNISFIL
Condo Suite # (if applicable)			Street Number Street Name
			1767 Emberton Way
		e under warranty):	Civic Address (address of your home under warranty):
Enrolment #	uilder#	Vendor/Builder#	Date of Possession (YYYY/MM/DD)
H2324446	528	B44528	2020-08-11

Mailing Address for Correspondence to Homeowner (if different from Civic Address above)

1767	Emberton Way			
Street Number	Street Name			Condo Suite # (if applicable)
INNISFIL		ON	L9S 0N4	
City/Town		Province	Postal Code	
	The second secon		Charles of the last of the las	THE REAL PROPERTY AND PERSONS NAMED IN COLUMN TWO IS NOT THE OWNER, THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TRANSPORT NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TRANSPORT NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TRANSPORT NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TRANSPORT NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TRANSPORT NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TRANSPORT NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TRANSPORT NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TRANSPORT NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TRANSPORT NAMED I

TARN-YRND-04.02

You may submit only one Year-End Form, so be sure it is complete.

Tarion will only accept and act on the first Year-End Form that has been properly submitted on time.

Outstanding Items

List all outstanding items covered by the statutory warranty in the table below. If you require more space, please make copies of this page, number them and attach them to this Statutory Warranty Form.

Enrolment #

H2324446

1 Floor 01 2 Floor 01	Bathroom	Bathtub	MAIN BATH: Silicone/sealer missing along shower and bathtub.
	Bathroom	Toilet	MAIN BATH: Loose toilets will eventually leak. >>Refer to home inspection report pg 44 - item #15
() toilet.pdf			home inspection pg 44 - item #15
3 Floor 01	Bathroom	Toilet	ENSUITE: Loose toilet will eventually leak. >>Refer to home inspection report pg 43 - Item #14
0 toilet.pdf			home inspection pg 43 - item #14
4 Floor 01	Bathroom	Floor	ENSUITE: noise on floor - can hear basement ductwork when we step on the tiles - "oil canning". (Article # 2.4, 8.12)
5 Floor 01	Kitchen	Floor	Multiple uneven pockets/sagging floor & knocking sounds due to weather damaged subfloor used. No subfloor upgrade option was provided at time of decor appt. (Article # 2.2, 2.3, 2.4, 2.6, 12.2) >>Refer to home inspection report pg 46 - item #17
0 subflooring.pdf			home inspection pg 46 – item #17
6 Floor 01	Hallway	Floor	Multiple uneven pockets/sagging floor & knocking sounds due to weather damaged subfloor used. No subfloor upgrade option was provided at time of decor appt. (Article # 2.2, 2.3, 2.4, 2.6, 12.2) >>Refer to home inspection report pg 25 - item #8 home inspection pg 25 - item #8
7 Floor 01	Living Room	Floor	Multiple uneven pockets/sagging floor & knocking sounds due to weather damaged subfloor used. No subfloor upgrade option was provided at time of decor appt. (Article # 2.2, 2.3, 2.4, 2.6, 12.2) >>Refer to home inspection report pg 46 - item #17
0 subflooring.pdf			home inspection pg 46 - item #17
8 Floor 01	Living Room	Floor	Upgraded vinyl floor planks has multiple dents around living room as a result of furniture placed on top of uneven floor due to sagging weather damaged subfloor. (Article number 2.2, 2.3, 2.4, 2.6, 12.2, 12.39)
() vinyl1.jpg () vinyl2.jpg			vinyl plank flooring dents 1 vinyl plank flooring dents 2
9 Floor 01	Bathroom	Plumbing Fixtures	ENSUITE: Caulking missing around the faucet to reduce the risk of water damage. >>Refer to home inspection report pg 41 - item #12
∫ faucets.pdf			home inspection pg 41 - item #12
10 Floor 01	Bathroom	Plumbing Fixtures	MAIN BATH: Caulking missing around the bathtub faucet to reduce the risk of water damage. >>Refer to home inspection report pg 42 item #13
() faucets.pdf			home inspection pg 41 - item #13
11 Floor 01	Bathroom	Floor	MAIN BATH: High floor transition from tile to vinyl poses a trip hazard. (Article # 12.1) >>Refer to home inspection report pg 46 - item #16
(i) trip hazard.pdf (j) bathroom.jpg			home inspection pg 46 - item #16 transistion

Full home inspection report hyperlink	Full home ins		Full Home Inspection report link.pdf	Full Ho
	Description	HMENTS	FORM ATTACHMENTS	File Name
Chainlink fence missing along the side of the property and the proposed walkway as per plan.	Fence	Yard - Side	Lot/Property/Yard	19
Chainlink fence missing along the back of the property and the forest as per plan.	Fence	Yard - Back	Lot/Property/Yard	18
Crack in home foundation - front right corner of home (southeast corner). >>Refer to home inspection report pg 21 - item #6 home inspection pg 21 - item #6	Foundation (Footings, etc.)	Building Face/Exterior	Not Applicable (Choose your next selection) (i) foundation.pdf	17
Downspout missing on right-side of porch and re-adjust eavestroughs. Water not draining properly & caused shingle damage in winter. Other Cobble Elev A models have this downspout. (Article 5.22) >>Refer to home inspection report pg 14 - item #2 home inspection pg 14 - item #2-3	Other (Please describe)	Roof Top	Roof (Exterior)	1 6
			EXTERIOR	EXT
slope with level slope with level and measurement			() floor1.jpg () floor2.jpg	
Floor is sloped between living room and dinning room from the beam. (Article # 2.5, 2.6, 12.2)	Floor	Living Room	Floor 01	15
2nd BEDROOM: Multiple uneven pockets/sagging floor & knocking sounds due to weather damaged subfloor used. No subfloor upgrade option was provided at time of decor appt. (Article # 2.2, 2.3, 2.4, 2.6, 12.2)	Floor	Bedroom	Floor 01	14
Electrical panel doorbell breaker tapped with another branch circuit. >>Refer to home inspection report pg 29 - item #9 home inspection pg 29 - item #9	Electrical	Unfinished Area	Basement () panel.pdf	13
Need installation of GFCI outlet to replace existing outlet as this poses an electric shock hazard since being close to water. >>Refer to home inspection report pg 30 - item #10 home inspection pg 30 - item #10	Electrical	Laundry Room	Floor 01	12

The items specified on this Statutory Warranty Form constitute a complete list of all known warranty items which are outstanding and have not been resolved by my Builder to date.

Submitted online by Caroline Lima

Nuno Lima

Homeowner's Signature

2021-08-11

Homeowner's Signature (if applicable)

Remember to send a copy of this completed Form to your Builder.

Date of Signature (YYYY/MM/DD)

Please note that you should allow your Builder's representatives or subcontractors access to your home during regular business hours, at a mutually acceptable time arranged in advance, in order to complete the necessary work. Failure to do so may jeopardize your warranty rights.

TARN-YRND-04.02