Enrollment:

Purchaser Name: Charanya Muthurajalingam Muthurajalingam Subramaniam

Closing Date: Phone Bus: inspector: July 14, 2022 Gisella Fiore (647) 527-5929

> HOMES NO D

> > Vendor / Builder:

Project: Lot / Phase: Zancor Homes (Parkview) Ltd. Unit 6 (Block 1) / 1

Address: Plan:

Inspection Date: July 12, 2022 Municiapilty:

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

Page 1 of 2

## DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens Bathtub sinks and toilets
  Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
  Flooring (hardwood, vinyl, ceramic tiles, carpeting)
  Interior finished and trim carpentry

- Hot water heater, if provided (not rental)

  Exterior finished, driveways, walkways, decks and landscaping

## OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
   Faucets: Kitchen, bathroom, laundry room
   Exhaust fans (kitchen, bathrooms) if provided
   Electrical outlets and fixtures
   Gas fireplaces, incl.circulation fans, if provided
   Heat Recovery Ventilation system, if provided

- Heating system

  Hot water heater, if provided (not rental)

  Air conditioning system, if provided and if conditions permit

AC NOT INSTALLED	AC NOT INSTALLED	DOWNSPOUT NOT INSTALLED	RAILING NOT INSTALLED AT REAR OF HOME	EXTERIOR	WALLS BACKSPLASH NOT INSTALLED	CHIP ON LEFT GABLE LEFT OF STOVE	SMALL CHIP INSIDE UPPER CABINET ABOVE FRIDGE	CABINETS SMALL CHIPS ON BACK ISLAND FACING BREAKFAST	SINK/FAUCET/PLUMBING PLUMBING AT ISLAND NOT INSTALLED	KITCHEN	EXPOSED SCREW BELOW N	CHIP ON RISER BELOW NOS	STAIRS CHIP ON STRINGER POST A	FOYER/HALL	WINDOWS WINDOW INSERTS BROKEN IN BETWEEN PANES	BEDROOM #3	VANITY CABINETS INSPECT MARKS ON LEFT GABLE LEFT OF SINK	BEDROOM 2 ENSUITE	FLOORING CARPET NOT INSTALLED THROUGHOUT BED ROOMS	MASTER BEDROOM	MIRROR THROUGHOUT NOT INSTALLED	MASTER ENSUITE BATH	e movement immitted and analysis maintained by account and analysis analysis and analysis and analysis and analysis and analysis and an
											EXPOSED SCREW BELOW NOSING AT RISER AT STAIRS TO BASEMENT	CHIP ON RISER BELOW NOSING AT LANDING AT STAIRS FROM MAIN FLOOR TOO 3RD FLOOR	CHIP ON STRINGER POST AT LANDING AT STAIRS FROM MAIN FLOOR TO 3RD FLOOR										
	***************************************				K				~	1									7	-			
					C.8				L.IV.										( -   V				