

Oct. 24/22
24.

MEDI GROUP

BLK 1- UNIT 1

NORTHSIDE:

- Replace window sill at garage side where window is close to jogged wall revealing styrofoam inside sill

BLK 1- UNIT 4

REAR:

- Repair 3 courses of stove below steel I-BEAM reveals masonry not level at right side & add mortar under steel I-BEAM L/S

BLK 9- UNIT 52

REAR:

- Add mortar under steel I-BEAM at L/S

BLK 9- UNIT 54

- Add mortar under steel I-BEAM at R/S (NO INDICATION OF WHERE)

BLK 9- UNIT 55

FRONT:

- Pressure wash required for stone and bricks

REAR:

- Add mortar under steel I-BEAM at left side


BLK 9- UNIT 56

REAR:

- Add mortar under steel I-BEAM at R/S

***NOTE: ALL UNITS MUST BE PRESSURE WASHED**

OCT-24/22
PM



Blk#9 Unit#52 front column remove 1 course of stone:



MEDI GROUP Service

WO Number : **W-084203**

WO Date : **20-Oct-2022**

Issued To : **ROBERT ULJASZ**

Builder : Zancor

ZAN11

Lot No : **B9-52**

Project : **ZANCOR-BROOKLIN TOWNS-3-21**

Model :

Directions : Brooklin /Whitby

Intersection of Thickson Road and
Carnwith Drive (east of Thickson, north of

Address :

Contact :

Main Brick : Tahoe

Main Stone :

Accent Brick :

Accent Stone : Champagne (Chamfer Walling)

INIT	Item	Work Description	PO	Builder Ref #
<input checked="" type="checkbox"/>	1	ADD MORTAR UNDER STEEL I-BEAM AT L/S		ALLAUG0922
<input checked="" type="checkbox"/>	2	FRONT COLUMN REMOVE 1 COURSE OF STONE - SEE PHOTO		S-065541
				08M101541
				S-065545

21 Oct/22

Homeowner Signature

Date Completed

Site Super Signature

Date Completed

Special Notes :

COMPLETED OCT 24 2022