# ZANCOR

Phone Res:

#### **Quality Control-WEB**



Vendor / Builder # Enrollment #

Purchaser Name: Vishal Govindbhai Patel - Bhumika

Patel

**Phone Bus:** 6474035199

Closing Date: 2023-02-23

**Inspector:** Gisella Fiore

Legal Address:

Project: Zancor Homes (Caledon) Ltd.

Plan #:

Lot / Phase #: 146A / 1

Municiaplity:

Inspection Date: Date undefined, undefined

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

#### DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- · Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- · Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

#### **OPERATING CONDITION**

- Windows, interior and exterior doors including garage overhead doors, door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

#### **EXTERIOR**

## NOTE:

**Deficiency:**ADJUST LENTIL ABOVE FRONT PORCH AND GARAGE WOOD EXPOSE

#### Pictures:



#### PAINT

## PAINTING NOT COMPLETE AT HARDY BOARD AND FRONT PORCH COLUMNS



## LIVING ROOM

## FLOORING

**Deficiency:**OVER CUT AT AIR RETURN RIGHT OF FIREPLACE

#### Pictures:



**Deficiency:**DENT ON 8TH AND 15TH PLANK AT ENTRANCE TO LIVING FROM KITCHEN











## FOYER/HALL

#### **STAIRS**

Deficiency:

OVER CUT AT FIRST LANDING BY NEWEL POST

Pictures:



**Deficiency:**CRACK AT STRINGER AT FIRST LANDING AT STAIRS TO 2ND LANDING

Pictures:





#### WALLS

Deficiency:

DENTS ON STIPPLE CEILING LEFT OF DOOR BELL CHIME

Pictures:





#### FRONT DOORS

Deficiency: CHIPS ON ASTRICAL

Pictures:





#### **FLOORING**

INSPECT GAPS AT 7TH AND 8TH PLANK FROM WINDOW AT DEN AT ENTRANCE FROM FOYER CAN SEE SUB FLOOR FROM BELOW







## MASTER ENSUITE BATH COUNTERTOPS **Deficiency:**SCRATCH ON COUNTER TOP RIGHT SINK Pictures: **VANITY CABINETS** Deficiency: DENT ON LEFT GABLE LEFT OF SINK Pictures: WALLS Deficiency: MARBLE JAMB NOT SITTING FLUSH AT WALL Pictures: MASTER BEDROOM WALLS Deficiency: SECURE ATTIC HATCH Pictures: **FLOORING** Deficiency: FLOOR SQUEAK AT ENTRANCE TO RIGHT CLOSET

## **UPPER HALL**

## WALLS

**Deficiency:**BLACK MARK ON STIPPLE CEILING AT ENTRANCE TO MASTER

#### Pictures:



#### **RAILING**

#### Deficiency:

HO REQUESTING TO FILL GAP AT HARDWOOD AND NOSING 2) CRACK ON NEWEL POST CRACK AT FIRST LANDING AT STAIRS TO 2ND FLOOR







## SHARED ENSUITE

## **VANITY CABINETS**

**Deficiency:**SCRATCH INSIDE LEFT AND RIGHT CABINET BELOW RIGHT SINK AND AT BOTTOM GABLE BELOW SINK AND BACK GABLE BELOW LEFT SINK CRACKED

#### Pictures:









#### COUNTERTOPS

**Deficiency:** CHIP ON RIGHT SIDE COUNTER TOP

#### Pictures:



#### **WALLS**

WINDOW SCREEN NOT INSTALLED AT OPERATING WINDOW

#### Pictures:





#### BEDROOM #4

#### **FLOORING**

ADJUST CARPET SHIM AT ENTRANCE TO BATH

#### Pictures:



CLEAN CARPET INFRONT OF LEFT FIXED WINDOW







## **BEDROOM 4 ENSUITE**

## **VANITY CABINETS**

#### Deficiency:

CHIP AT BOTTOM RIGHT GABLE RIGHT OF SINK AT FLOOR LINE

#### Pictures:





#### **LAUNDRY ROOM**

#### **FLOORING**

#### Deficiency:

FILL GROUT AT TILE BY NOISING AT LANDING AT MUD ROOM

#### Pictures:





## **CABINETS**

Deficiency: CHIP AT BOTTOM GABLE

#### Pictures:





## KITCHEN

#### **CABINETS**

**Deficiency:**CROWN MOULDING AT UPPER RIGHT SIDE OF HOOD FAN JOINTS LARGE

#### Pictures:



#### **BASEMENT**

#### **FURNACE**

FURNACE FILTER COVER NOT INSTALLED



THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS

\* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.

to the vendor/builder authorizing the designate to sign this form on their behalf.			
	J. Port		
Builder Representative	Purchaser		
Designate's Name(please print)	 Designate's Signature		
I the homeowner, confirm that all repair v			
J. Port			
Purchaser	Date		