Enrollment:

Purchaser Name: ?????

Mandeep Singh Sidhu

Phone Res:

Phone Bus: (416) 829-1957
Closing Date: June 12, 2023
Inspector: Gisella Fiore

ZANCOR HOMES PDI Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: Block 149 Unit 2 / 1

Plan: Address: Municiaplity:

Inspection Date: March 07, 2023

Gisella Fiore Page 1 of 2

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

EXTERIOR		
RAILING	EXTERIOR RAILING NOT INSTALLED	
PAINT	EXTERIOR PAINT NOT COMPLETE	
NOTE:	DOWNSPOUTS AND EAVESTROUGH NOT INSTALLED	
KITCHEN		
WALLS	CRACKED TILE AT ELECTRICAL OUTLET ON BACKSPLASH RIGHT OF SINK	
	MISSING GROUT AT TILE BY NEWEL POST AT ENTRANCE TO HALLWAY	
CABINETS	FILL NAIL HOLES AT FRIDGE GABLE LEFT SIDE 2) TOUCH UP GABLE ABOVE FRIDGE 3)FILLER	
	PIECE MISSING AT UPPER CORNER LEFT OF SINK 4) FILL SEAM AT UPPER VALANCE ABOVE	
	CABINET RIGHT OF HOODFAN	
COUNTERTOPS	INSPECT SAW CUT ON LEFT SIDE OF COUNTER TOP AT ISLAND AT EDGE	
TRIM	HOMEOWNER REQUESTING TO EXTEND TRIM LEFT OF FRIDGE	
LIVING ROOM		
FLOORING	SCRATCH ON 10TH HARDWOOD PLANK FROM AIR RETURN ON FLOOR IN FRONT OF HRV UNIT	
	2)CHIP ON 19TH AND 26TH HARDWOOD PLANK INFRONT OF AIR RETURN 3)SCRATCH ON 1ST	
	HARDWOOD PLANK FROM RIGHT SIDE OF FIRE PLACE CORNER WALL INFRONT OF INTERNET	
	ROUGH IN 4)CHIP ON 4RTH HARDWOOD PLANK INFRONT OF FIRE PLACE 5) INSPECT FILLER USED AT HARDWOOD INFRONT OF WINDOW	
UPPER HALL	GOLD AT THE MOOD IN TION OF WINDOW	
FLOORING	CHIP ON FIFTH HARDWOOD PLANK FROM CENTRAL VAC ROUGH IN 2) FILLER BETWEEN	
	HARDWOOD PLANK AT 1ST PLANK FROM TRIM AT ENTRANCE TO MAIN BATH 3) CRACK AT	
	HARDWOOD PLANK AT ENTRANCE TO BEDROOM 3 4) GAP BETWEEN HARDWOOD AND NOISING	
	AT 3RD FLOOR	
WALLS	BLACK MARKS ON STIPPLE CEILING	
MASTER ENSUITE BATH		
FLOORING	ADJUST CARPET SHIM AT ENTRANCE TO BATH	
SINK	SINK STOPPER NOT HOLDING WATER	
VANITY CABINETS	CHIP AT BOTTOM GABLE LEFT SINK UNDER SINK 2) SCRATCH ON RIGHT DOOR	
FOYER/HALL		
STAIRS	WRONG COLOUR COMPLETED AT NAIL HOLES AT FIRST LANDING AT STAIRS TO THIRD FLOOR	
	SAW CUT ON OUTSIDE STRINGER BY NOSING AT LANDING TO THIRD-FLOOR 2) GAP BETWEEN	
	TRIM AND OUTSIDE STRINGER AT STAIRS TO 3RD FLOOR BY CEILING 3) CHIP ON INSIDE	
	STRINGER BELOW NOSING AT 1ST LANDING TO MAIN FLOOR	
	APPLY VARNISH TO 9TH TREAD BELOW NOISING TO FIRST LANDING TO 3RD FLOOR 2) INSPECT	
	VARNISH AT OUTSIDE STRINGER BY NOISING AT LANDING TO 3RD FLOOR OVERLAY 3)	
	VARNISH REQUIRED AT TREAD BY POST AT 1ST LANDING AT STAIRS TO MAIN FLOOR AND BETWEEN OUTSIDE STRINGER AND TREAD AT FIRST LANDING 4) VARNISH REQUIRED AT 5TH	
	AND 6TH TREAD BY PICKETS AT STAIRS FROM MAIN FLOOR TO FIRST LANDING TO 3RD FLOOR	
WINDOWS	DENTS ON GARAGE MAN DOOR 2) ADJUST DOOR	
	22 3 3 3 3 3 3 3.	

Enrollment: Purchaser Name: ?????

Mandeep Singh Sidhu

Phone Res: Phone Bus: (416) 829-1957 Closing Date: June 12, 2023 Inspector: Gisella Fiore

ZANCOR

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: Block 149 Unit 2 / 1

Plan: Address: Municiaplity:

Page 2 of 2 Inspection Date: March 07, 2023

MAIN BATHROOM		
VANITY CABINETS	CHIP AT BOTTOM RIGHT GABLE RIGHT OF SINK	
BEDROOM #2		
WINDOWS	ADJUST WINDOW HARD TO OPEN	
WALLS	STIPPLE CEILING RIGHT OF WINDOW PEELING	
BEDROOM #3		
FLOORING	OVER CUT AT RIGHT HEAT REGISTER BELOW OPERATING WINDOW	
LAUNDRY ROOM		
NOTE:	ADJUST LEFT LIP AT COUNTERTOP	

A REFERENCE FOR FUTURE WARRA	NTY REQUESTS. designate someone to conduct the PDI in th	E HOME'S CONDITION BEFORE THE PURCHASE neir place should ensure they provide written authors.	
I have inspected my new home and I a	agree that the description of the items listed	on this form are accurate.	
	Mond 82		
?????		Mandeep Singh Sidhu	
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature
			Θ
		Gisella Fiore	
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature
Date (YYYY/MM/DD)	2023/03/07	March 07, 2023	