



Zancor Homes (Caledon) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Closing Date: 12Jun23
Address: [REDACTED]
Location: [REDACTED]
Today's Date: 08Mar23
Contact(s): [REDACTED]
Email: [REDACTED]

Caledon Club - Phase: 1 - Lot: Block 149 Unit 2

Company: First Canadian Hardwood
Attention: Nicholas
Telephone: (905) 850-7220
Fax: (905) 850-2641

Please Complete the following items:

DAI	Type	Issue	Appt. Date/Time	Notes
155007	PDI	FOYER/HALL-STAIRS-WRONG COLOUR COMPLETED AT NAIL HOLES AT FIRST LANDING AT STAIRS TO THIRD FLOOR	✓	
155012	PDI	UPPER HALL-FLOORING~CHIP ON FIFTH HARDWOOD PLANK FROM CENTRAL VAC ROUGH IN 2) FILLER BETWEEN HARDWOOD PLANK AT 1ST PLANK FROM TRIM AT ENTRANCE TO MAIN BATH 3) CRACK AT HARDWOOD PLANK AT ENTRANCE TO BEDROOM 3 4) GAP BETWEEN HARDWOOD AND NOISING AT 3RD	✓	

		FLOOR			
155013	PDI	LIVING ROOM- FLOOR RING~SCRATCH ON 10TH HARDWOOD PLANK FROM AIR RETURN ON FLOOR IN FRONT OF HRV UNIT 2)CHIP ON 19TH AND 26TH HARDWOOD PLANK INFRONT OF AIR RETURN 3)SCRATCH ON 1ST HARDWOOD PLANK FROM RIGHT SIDE OF FIRE PLACE CORNER WALL INFRONT OF INTERNET ROUGH IN 4)CHIP ON 4RTH HARDWOOD PLANK INFRONT OF FIRE PLACE 5) INSPECT FILLER USED AT HARDWOOD INFRONT OF WINDOW			

Date Completed: Nov 21/23

Homeowner Signature: [Signature]
The Homeowner acknowledges and accepts all work
has been completed in a workman like manner.

Date Completed: _____


Trade &/or Service Tech.
Signature: [Signature]
Print Name: _____

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.


Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Caledon Club - Phase: 1 - Lot: Block 149 Unit 2

155007 - 1 - STAIRS~WRONG COLOUR
COMPLETED AT NAIL HOLES AT FIRST LANDING
AT STAIRS TO THIRD FLOOR



155007 - 2 - STAIRS~WRONG COLOUR
COMPLETED AT NAIL HOLES AT FIRST LANDING
AT STAIRS TO THIRD FLOOR



155012 - 1 - FLOORING~CHIP ON FIFTH
HARDWOOD PLANK FROM CENTRAL VAC
ROUGH IN 2) FILLER BETWEEN HARDWOOD
PLANK AT 1ST PLANK FROM TRIM AT
ENTRANCE TO MAIN BATH 3) CRACK AT
HARDWOOD PLANK AT ENTRANCE TO
BEDROOM 3 4) GAP BETWEEN HARDWOOD AND
NOISING AT 3RD FLOOR




155012 - 2 - FLOORING~CHIP ON FIFTH
HARDWOOD PLANK FROM CENTRAL VAC
ROUGH IN 2) FILLER BETWEEN HARDWOOD
PLANK AT 1ST PLANK FROM TRIM AT
ENTRANCE TO MAIN BATH 3) CRACK AT
HARDWOOD PLANK AT ENTRANCE TO
BEDROOM 3 4) GAP BETWEEN HARDWOOD AND
NOISING AT 3RD FLOOR



155012 - 3 - FLOORING~CHIP ON FIFTH
HARDWOOD PLANK FROM CENTRAL VAC
ROUGH IN 2) FILLER BETWEEN HARDWOOD
PLANK AT 1ST PLANK FROM TRIM AT
ENTRANCE TO MAIN BATH 3) CRACK AT
HARDWOOD PLANK AT ENTRANCE TO
BEDROOM 3 4) GAP BETWEEN HARDWOOD AND
NOISING AT 3RD FLOOR


155012 - 4 - FLOORING~CHIP ON FIFTH
HARDWOOD PLANK FROM CENTRAL VAC
ROUGH IN 2) FILLER BETWEEN HARDWOOD
PLANK AT 1ST PLANK FROM TRIM AT
ENTRANCE TO MAIN BATH 3) CRACK AT
HARDWOOD PLANK AT ENTRANCE TO
BEDROOM 3 4) GAP BETWEEN HARDWOOD AND
NOISING AT 3RD FLOOR




155012 - 5 - FLOORING~CHIP ON FIFTH
HARDWOOD PLANK FROM CENTRAL VAC
ROUGH IN 2) FILLER BETWEEN HARDWOOD
PLANK AT 1ST PLANK FROM TRIM AT ENTRANCE
TO MAIN BATH 3) CRACK AT HARDWOOD PLANK
AT ENTRANCE TO BEDROOM 3 4) GAP BETWEEN
HARDWOOD AND NOISING AT 3RD FLOOR




155012 - 6 - FLOORING~CHIP ON FIFTH
HARDWOOD PLANK FROM CENTRAL VAC
ROUGH IN 2) FILLER BETWEEN HARDWOOD
PLANK AT 1ST PLANK FROM TRIM AT ENTRANCE
TO MAIN BATH 3) CRACK AT HARDWOOD PLANK
AT ENTRANCE TO BEDROOM 3 4) GAP BETWEEN
HARDWOOD AND NOISING AT 3RD FLOOR



155012 - 7 - FLOORING~CHIP ON FIFTH
HARDWOOD PLANK FROM CENTRAL VAC
ROUGH IN 2) FILLER BETWEEN HARDWOOD
PLANK AT 1ST PLANK FROM TRIM AT
ENTRANCE TO MAIN BATH 3) CRACK AT
HARDWOOD PLANK AT ENTRANCE TO
BEDROOM 3 4) GAP BETWEEN HARDWOOD AND
NOISING AT 3RD FLOOR



155013 - 1 - FLOORING~SCRATCH ON 10TH
HARDWOOD PLANK FROM AIR RETURN ON
FLOOR IN FRONT OF HRV UNIT 2)CHIP ON 19TH
AND 26TH HARDWOOD PLANK INFRONT OF AIR
RETURN 3)SCRATCH ON 1ST HARDWOOD
PLANK FROM RIGHT SIDE OF FIRE PLACE
CORNER WALL INFRONT OF INTERNET ROUGH
IN 4)CHIP ON 4RTH HARDWOOD PLANK INFRONT
OF FIRE PLACE 5) INSPECT FILLER USED AT
HARDWOOD INFRONT OF WINDOW



155013 - 2 - FLOORING~SCRATCH ON 10TH
HARDWOOD PLANK FROM AIR RETURN ON
FLOOR IN FRONT OF HRV UNIT 2)CHIP ON 19TH
AND 26TH HARDWOOD PLANK INFRONT OF AIR
RETURN 3)SCRATCH ON 1ST HARDWOOD
PLANK FROM RIGHT SIDE OF FIRE PLACE

155013 - 3 - FLOORING~SCRATCH ON 10TH
HARDWOOD PLANK FROM AIR RETURN ON
FLOOR IN FRONT OF HRV UNIT 2)CHIP ON 19TH
AND 26TH HARDWOOD PLANK INFRONT OF AIR
RETURN 3)SCRATCH ON 1ST HARDWOOD
PLANK FROM RIGHT SIDE OF FIRE PLACE

CORNER WALL INFRONT OF INTERNET ROUGH
IN 4)CHIP ON 4RTH HARDWOOD PLANK
INFRONT OF FIRE PLACE 5) INSPECT FILLER
USED AT HARDWOOD INFRONT OF WINDOW




CORNER WALL INFRONT OF INTERNET ROUGH
IN 4)CHIP ON 4RTH HARDWOOD PLANK
INFRONT OF FIRE PLACE 5) INSPECT FILLER
USED AT HARDWOOD INFRONT OF WINDOW



155013 - 4 - FLOORING~SCRATCH ON 10TH
HARDWOOD PLANK FROM AIR RETURN ON
FLOOR IN FRONT OF HRV UNIT 2)CHIP ON 19TH
AND 26TH HARDWOOD PLANK INFRONT OF AIR
RETURN 3)SCRATCH ON 1ST HARDWOOD PLANK
FROM RIGHT SIDE OF FIRE PLACE CORNER
WALL INFRONT OF INTERNET ROUGH IN 4)CHIP
ON 4RTH HARDWOOD PLANK INFRONT OF FIRE
PLACE 5) INSPECT FILLER USED AT HARDWOOD
INFRONT OF WINDOW



155013 - 5 - FLOORING~SCRATCH ON 10TH
HARDWOOD PLANK FROM AIR RETURN ON
FLOOR IN FRONT OF HRV UNIT 2)CHIP ON 19TH
AND 26TH HARDWOOD PLANK INFRONT OF AIR
RETURN 3)SCRATCH ON 1ST HARDWOOD PLANK
FROM RIGHT SIDE OF FIRE PLACE CORNER
WALL INFRONT OF INTERNET ROUGH IN 4)CHIP
ON 4RTH HARDWOOD PLANK INFRONT OF FIRE
PLACE 5) INSPECT FILLER USED AT HARDWOOD
INFRONT OF WINDOW



155013 - 6 - FLOORING~SCRATCH ON 10TH
HARDWOOD PLANK FROM AIR RETURN ON
FLOOR IN FRONT OF HRV UNIT 2)CHIP ON 19TH
AND 26TH HARDWOOD PLANK INFRONT OF AIR
RETURN 3)SCRATCH ON 1ST HARDWOOD
PLANK FROM RIGHT SIDE OF FIRE PLACE
CORNER WALL INFRONT OF INTERNET ROUGH
IN 4)CHIP ON 4RTH HARDWOOD PLANK INFRONT
OF FIRE PLACE 5) INSPECT FILLER USED AT
HARDWOOD INFRONT OF WINDOW




155013 - 7 - FLOORING~SCRATCH ON 10TH
HARDWOOD PLANK FROM AIR RETURN ON
FLOOR IN FRONT OF HRV UNIT 2)CHIP ON 19TH
AND 26TH HARDWOOD PLANK INFRONT OF AIR
RETURN 3)SCRATCH ON 1ST HARDWOOD
PLANK FROM RIGHT SIDE OF FIRE PLACE
CORNER WALL INFRONT OF INTERNET ROUGH
IN 4)CHIP ON 4RTH HARDWOOD PLANK INFRONT
OF FIRE PLACE 5) INSPECT FILLER USED AT
HARDWOOD INFRONT OF WINDOW



155013 - 8 - FLOORING~SCRATCH ON 10TH
HARDWOOD PLANK FROM AIR RETURN ON
FLOOR IN FRONT OF HRV UNIT 2)CHIP ON 19TH

155013 - 9 - FLOORING~SCRATCH ON 10TH
HARDWOOD PLANK FROM AIR RETURN ON
FLOOR IN FRONT OF HRV UNIT 2)CHIP ON 19TH

AND 26TH HARDWOOD PLANK INFRONT OF AIR
RETURN 3)SCRATCH ON 1ST HARDWOOD
PLANK FROM RIGHT SIDE OF FIRE PLACE
CORNER WALL INFRONT OF INTERNET ROUGH
IN 4)CHIP ON 4RTH HARDWOOD PLANK
INFRONT OF FIRE PLACE 5) INSPECT FILLER
USED AT HARDWOOD INFRONT OF WINDOW



AND 26TH HARDWOOD PLANK INFRONT OF AIR
RETURN 3)SCRATCH ON 1ST HARDWOOD
PLANK FROM RIGHT SIDE OF FIRE PLACE
CORNER WALL INFRONT OF INTERNET ROUGH
IN 4)CHIP ON 4RTH HARDWOOD PLANK
INFRONT OF FIRE PLACE 5) INSPECT FILLER
USED AT HARDWOOD INFRONT OF WINDOW



155013 - 10 - FLOORING~SCRATCH ON 10TH
HARDWOOD PLANK FROM AIR RETURN ON
FLOOR IN FRONT OF HRV UNIT 2)CHIP ON 19TH
AND 26TH HARDWOOD PLANK INFRONT OF AIR
RETURN 3)SCRATCH ON 1ST HARDWOOD PLANK
FROM RIGHT SIDE OF FIRE PLACE CORNER
WALL INFRONT OF INTERNET ROUGH IN 4)CHIP
ON 4RTH HARDWOOD PLANK INFRONT OF FIRE
PLACE 5) INSPECT FILLER USED AT HARDWOOD
INFRONT OF WINDOW



155013 - 11 - FLOORING~SCRATCH ON 10TH
HARDWOOD PLANK FROM AIR RETURN ON
FLOOR IN FRONT OF HRV UNIT 2)CHIP ON 19TH
AND 26TH HARDWOOD PLANK INFRONT OF AIR
RETURN 3)SCRATCH ON 1ST HARDWOOD PLANK
FROM RIGHT SIDE OF FIRE PLACE CORNER
WALL INFRONT OF INTERNET ROUGH IN 4)CHIP
ON 4RTH HARDWOOD PLANK INFRONT OF FIRE
PLACE 5) INSPECT FILLER USED AT HARDWOOD
INFRONT OF WINDOW



155013 - 12 - FLOORING~SCRATCH ON 10TH
HARDWOOD PLANK FROM AIR RETURN ON
FLOOR IN FRONT OF HRV UNIT 2)CHIP ON 19TH
AND 26TH HARDWOOD PLANK INFRONT OF AIR
RETURN 3)SCRATCH ON 1ST HARDWOOD
PLANK FROM RIGHT SIDE OF FIRE PLACE
CORNER WALL INFRONT OF INTERNET ROUGH
IN 4)CHIP ON 4RTH HARDWOOD PLANK INFRONT
OF FIRE PLACE 5) INSPECT FILLER USED AT
HARDWOOD INFRONT OF WINDOW

