

NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6 TEL (905) 672-1233 FAX (905) 672-1076 WO # W176588 Pack Slip:230943

Service Date: May 26, 2023

BUILDER							
Customer: N000531	Priority:	Normal		Status	SCHEDULEI	D	
Name: ZANCOR CALEDON CLUB Service Phone(s): Time: PM	BUILDER						
Service Fax: Lot#: 127B	Customer:				CALEDON	Received: Jan 2	20, 2023
Site Fax:	Name:	ZANCOR CALEDON CLUB		Service Phone(s):		Time: PM	
RESIDENT INFORMATION				Site Phone:	5/	Order: D390	0007-1
Home Owner Name: Address: Work Phone(s): Email(s):				Lot#:	127B	Phase: 1B	
Home Phone(s):	RESIDENT	INFORMATION					
Cell Phone(s):	Home Owner	Name:		Address:			
Linked Order Information (D390007-1) Customer: N000531 ZANCOR CALEDON CLUB	Home Phone	(s):		Work Phor	ne(s):		
Customer: N000531 ZANCOR CALEDON CLUB	Cell Phone(s)	:		Email(s):			
Model: 38-06 FAIRMONT/LOT 127B (BLK) SERVICE INSTRUCTIONS THE OPERATING FRONT DOOR SLAB ON LINE 30 IS MISSING THE EXECUTIVE PANEL AND DOORLITE "*THIS IS MUST DO"* ADD: BOWED WINDOW IN BED#4 BED#2 MB WINDOW BOWED LOCK MISSING FOR CENTRE OPEN SASH PARTS REQUIRED 1 Location Specification Size Options Qiy 31 ELTON VINYL EXECUTIVE PANEL ENT COMPLETE 22 X 20.75 VINEXPANEL 1 po 81667 COMPLETED 32 E620C_STYLE DOORLITE CUSTOM ENT DOORLITES 22 X 48 E620C_STYLE DOORLITE CUSTOM AG AG22 BK/WH ACID_ETCH_LOW_E_ARG 3T/19/3T 192 NEWMAR VINYL CASEMENT B4 OTHER RPLCMNT 30 X 60 BK 61316 FJ LEFT 1 lock missing for centre PARTS 222 E620C_STYLE DOORLITE CUSTOM ENT FRAME ONLY 22 X 48 2 Problem Description: Warranty	LINKED OR	DER INFORMATION (D390	0007-1)				
SERVICE INSTRUCTIONS THE OPERATING FRONT DOOR SLAB ON LINE 30 IS MISSING THE EXECUTIVE PANEL AND DOORLITE **THIS IS MUST DO** ADD: BOWED WINDOW IN BED#4 BED#2 MB WINDOW BOWED LOCK MISSING FOR CENTRE OPEN SASH PARTS REQUIRED 13 I ELTON VINYL EXECUTIVE PANEL ENT COMPLETE 22 X 20.75 VINEXPANEL 1 po 81667 COMPLETED 32 E620C STYLE DOORLITE CUSTOM ENT DOORLITES 22 X 48 E620C STYLE DOORLITE CUSTOM AG AG22 BK/WH ACID_ETCH_LOW_E_ARG 3T/19/3T 192 NEWMAR VINYL CASEMENT B4 OTHER RPLCMNT 30 X 60 BK 61316 FJ LEFT 1 lock missing for centre PARTS 222 E620C_STYLE DOORLITE CUSTOM ENT FRAME ONLY 22 X 48 Problem Description: Warranty	Customer:	N000531 ZANCOR CALEDON	CLUB		Lot #:	127B	
THE OPERATING FRONT DOOR SLAB ON LINE 30 IS MISSING THE EXECUTIVE PANEL AND DOORLITE **THIS IS MUST DO** ADD: BOWED WINDOW IN BED#4 BED#2 MB WINDOW BOWED LOCK MISSING FOR CENTRE OPEN SASH PARTS REQUIRED Lin Item Description 11 Lecalion Specification Size Options Qty 12 LETON VINYL EXECUTIVE PANEL ENT COMPLETE 22 X 20.75 VINEXPANEL 1 12 DO 81667 COMPLETED 32 E620C_STYLE DOORLITE CUSTOM ENT DOORLITES 22 X 48 E620C_STYLE DOORLITE CUSTOM AG AG22 BK/WH 12 ACCUMPLETED ACCUMPLETE ACCUM	Model:	38-06 FAIRMONT/LOT 127B (BLK)		Phase:	1B	
THIS IS MUST DO ADD: BOWED WINDOW IN BED#4 BED#2 MB WINDOW BOWED LOCK MISSING FOR CENTRE OPEN SASH PARTS REQUIRED LN Item Description Location Specification Size Options Qty 31 ELTON VINYL EXECUTIVE PANEL ENT COMPLETE 32 E620C_STYLE DOORLITE CUSTOM COMPLETED 32 E620C_STYLE DOORLITE CUSTOM COMPLETED DOORLITES 22 X 48 E620C_STYLE DOORLITE CUSTOM AG AG22 BK/WH ACID_ETCH_LOW_E ARG 3T/19/3T 192 NEWMAR VINYL CASEMENT lock missing for centre PARTS 222 E620C_STYLE DOORLITE CUSTOM ENT PARTS PARTS 222 E620C_STYLE DOORLITE CUSTOM ENT PARTS COMPLETED DOORLITES 22 X 48 E620C_STYLE DOORLITE 1 CUSTOM AG AG22 BK/WH ACID_ETCH_LOW_E ARG 3T/19/3T 1 POBLICE PARTS CUSTOM AG AG22 BK/WH ACID_ETCH_LOW_E ARG 3T/19/3T 1 CHARGEABLES Material \$ Labour \$ Labour \$ P.O.#: Cause:	SERVICE IN	ISTRUCTIONS					
ADD: BOWED WINDOW IN BED#4 BED#2 MB WINDOW BOWED LOCK MISSING FOR CENTRE OPEN SASH PARTS REQUIRED LN Item Description Location Specification Size Options Qty 31 ELTON VINYL EXECUTIVE PANEL ENT COMPLETE 32 E620C_STYLE DOORLITE CUSTOM ENT COMPLETED 32 E620C_STYLE DOORLITE CUSTOM ENT COMPLETED DOORLITES 22 X 48 E620C_STYLE DOORLITE CUSTOM AG AG222 BK/WH ACID_ETCH_LOW_E_ARG 371/19/3T 192 NEWMAR VINYL CASEMENT lock missing for centre PARTS 222 E620C_STYLE DOORLITE CUSTOM ENT FRAME ONLY 22 X 48 2 Problem Description: Marranty CHARGEABLES Material \$ Labour \$ Labour \$ P.O.#: Cause:	THE OPERAT	TING FRONT DOOR SLAB ON	LINE 30 IS	MISSING THE EXEC	UTIVE PANE	L AND DOORLITE	
LIN Item Description Location Specification Size Options Qty 31 ELTON VINYL EXECUTIVE PANEL ENT COMPLETE 22 X 20.75 VINEXPANEL 1 po 81667 COMPLETED 32 E620C_STYLE DOORLITE CUSTOM ENT DOORLITES 22 X 48 E620C_STYLE DOORLITE CUSTOM AG AG22 BK/WH ACID_ETCH_LOW_E_ARG 3T/19/3T 192 NEWMAR VINYL CASEMENT B4 OTHER RPLCMNT 30 X 60 BK 61316 FJ LEFT 1 lock missing for centre PARTS 222 E620C_STYLE DOORLITE CUSTOM ENT FRAME ONLY 22 X 48 2 Problem Description: Warranty	ADD: BOWED WIN MB WINDOW	DOW IN BED#4 BED#2 ' BOWED			(1	of t	
LIN Item Description Location Specification Size Options Qty 31 ELTON VINYL EXECUTIVE PANEL ENT COMPLETE 22 X 20.75 VINEXPANEL 1 po 81667 COMPLETED 32 E620C_STYLE DOORLITE CUSTOM ENT DOORLITES 22 X 48 E620C_STYLE DOORLITE CUSTOM AG AG22 BK/WH ACID_ETCH_LOW_E_ARG 3T/19/3T 192 NEWMAR VINYL CASEMENT B4 OTHER RPLCMNT 30 X 60 BK 61316 FJ LEFT 1 lock missing for centre PARTS 222 E620C_STYLE DOORLITE CUSTOM ENT FRAME ONLY 22 X 48 2 Problem Description: Warranty	LOCK MISSIN	NG FOR CENTRE OPEN SASI	+		Cony	lale	
31 ELTON VINYL EXECUTIVE PANEL ENT COMPLETE 22 X 20.75 VINEXPANEL 1 po 81667 COMPLETED 32 E620C_STYLE DOORLITE CUSTOM ENT DOORLITES 22 X 48 E620C_STYLE DOORLITE 1 CUSTOM AG AG22 BK/WH ACID_ETCH_LOW_E_ARG 3T/19/3T 192 NEWMAR VINYL CASEMENT B4 OTHER RPLCMNT 30 X 60 BK 61316 FJ LEFT 1 lock missing for centre PARTS 222 E620C_STYLE DOORLITE CUSTOM ENT FRAME ONLY 22 X 48 2 Problem Description: CHARGEABLES Material \$ Labour \$ P.O.#: Cause:	PARTS REC	QUIRED			,		
po 81667 COMPLETED 32 E620C_STYLE DOORLITE CUSTOM ENT DOORLITES 22 X 48 E620C_STYLE DOORLITE CUSTOM AG A622 BK/WH ACID_ETCH_LOW_E_ARG 3T/19/3T 192 NEWMAR VINYL CASEMENT B4 OTHER RPLCMNT 30 X 60 BK 61316 FJ LEFT 1 lock missing for centre PARTS 222 E620C_STYLE DOORLITE CUSTOM ENT FRAME ONLY 22 X 48 2 Problem Description: Warranty CHARGEABLES Material \$ Labour \$ Labour \$ P.O.#: Cause:			Location	Specification	Size	Options	Qty
COMPLETED CUSTOM AG AG22 BK/WH ACID_ETCH_LOW_E_ARG 3T/19/3T 192 NEWMAR VINYL CASEMENT B4 OTHER RPLCMNT 30 X 60 BK 61316 FJ LEFT 1 lock missing for centre PARTS 222 E620C_STYLE DOORLITE CUSTOM ENT FRAME ONLY 22 X 48 2 Problem Description: Warranty Warranty CHARGEABLES Material \$ Labour \$ P.O.#: Cause:	po 8166	7	ENT	COMPLETE	22 X 20.75	VINEXPANEL	1
lock missing for centre PARTS 222 E620C_STYLE DOORLITE CUSTOM ENT FRAME ONLY 22 X 48 Problem Description: Marranty CHARGEABLES Material \$ Labour \$ Labour \$ PARTS 2 Cause:			ENT	DOORLITES	22 X 48	CUSTOM AG AG22 BK/W ACID_ETCH_LOW_E_AR	/H
Problem Description: Mora in Availar to Sign CHARGEABLES Material \$ Labour \$ Labour \$ P.O.#:			B4		Г 30 X 60	BK 61316 FJ LEFT	1
Problem Description: Material CHARGEABLES Material Labour Labour Couse:	222 E620C_	STYLE DOORLITE CUSTOM	ENT_	FRAME ONLY	22 X 48		2
Material \$ Material \$ Labour \$ P.O.#:	Problem Desc	cription: NB	ore	in tree	Hor	to Sign	
Material \$ Material \$ Labour \$ P.O.#:	☐ Warrantv			☐ CHARG	SEABLES	<u>`</u>	
Labour \$ Labour \$ P.O.#:	ld				1171		
P.O.#:					717	_	
Cause:					120		
	Cause:						
Solution:							
Solution:							
	Solution:						
			7				

Date Completed: Nuy 26/33	Approved:	
Time:	Service Signature:	STEVE



NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6 TEL (905) 672-1233 FAX (905) 672-1076

Pack Slip #248209

Page 1

-	*	-			1 400	-	_
Ы	Д	Œ	K	IN	ΙG	SI	ч

Ship To: ZANCOR CALEDON CLUB

CONCORD

Cust PO#

Plant:

Estimate:

SIsman:

0038

Customer#

N000531

Order

D390007-2

E325736

Name:

ZANCOR HOMES (CALEDON) LTD.

Model:

38-06 FAIRMONT/LOT 127B (BLK)

Plant:

Newmar Due Date: Apr 28, 2023

Project: Location:

Tags:

CALEDON PART 9

Elev/Gar: Lot/Phase:

A2/L 127B 1B

LOCK UP SERVICE

Brandon Silva | 04-25-2023 10:12 am

HOUSE READY FOR LOCK-UP INSTALL ALL SCREENS AND CRANK HANDLES CHECK OPERATION OF ALL WINDOWS AND DOORS. ADJUST AS NECESSARY INSTALL PATIO DOOR SCREEN, INSTALL LOCK, CHECK OPERATION SET SPRING LOADED HINGES ON GARAGE TO HOUSE DOORS REMOVE SILL COVER AND TAPE FROM ALL DOORS

	ISSUES COMPLETED, AT LOCK-UP
ROOM/LINE#	Jowed Dindow in BRHG BR#2 Mys 128 Bed Whiter Koroad
	LOCK missing for contre typens scook!
ROOM/LINE#	FOLLOW UP + ISSUES REPORTED IMAGE SENT
ECEIVED	PC'S IN GOOD ORDER REC. BY: **** CLAIMS OF SHORTAGES AND DAMAGE MUST BE MADE AT THE TIME OF DELIVERY.
ANUFACTURERS OF QUALITY	Y WINDOWS AND ENTRANCE DOOR SYSTEM SEBAICE CHARGE 2% PER MONTH ON OVERDUE ACCOUNTS



NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6 TEL (905) 672-1233 FAX (905) 672-1076 F

WO # W176588 Pack Slip:230943

Service Date: Apr 26, 2023

Priority:	Normal		Status:	SCHEDULED		RELEASED	
BUILDER							
Customer:	N000531		City:	CALEDON	Received:	Jan 20, 2023	
Name:	Name: ZANCOR CALEDON CLUB		Service Phone(s)	:	Time:	PM	
Service Fax:			Site Phone:		Order:	D390007-1	
Site Fax:			Lot#:	127B	Phase:	1B	
RESIDENT	INFORMATION						
Home Owner	Name;		Address	3:			
Home Phone	(s):		Work Pl	hone(s):			
Cell Phone(s):		Email(s):			
LINKED OF	RDER INFORMATION (D39)	0007-1)					
Customer:	N000531 ZANCOR CALEDON	CLUB		Lot #: 12	27B		
Model:	38-06 FAIRMONT/LOT 127B (BLK)		Phase: 18	3		
	NSTRUCTIONS						
THE OPERA	TING FRONT DOOR SLAB ON	LINE 30 IS	MISSING THE EXE	ECUTIVE PANEL A	AND DOORLITE		
			"	a st	-		
**THIS IS ML				onythel	<i>ڪ</i>		
PARTS REC							
LN Item Desc	'	Location	Specification	Size	Options	C	Qty
po 8166		ENT	COMPLETE	22 X 20.75	VINEXPANEL		1
32 E620C STYLE DOORLITE CUSTOM ENT			DOORLITES	22 X 48	E620C_STYLE DOORLITE 1 CUSTOM AG AG22 BK/WH ACID_ETCH_LOW_E_ARG 3T/19/3T		
Problem Des	cription: Fixed D	ook ne	reds new	REENER LO	match ope	rater Rook	lite
Warranty			☐ CHARGEABLES)	2×48	
Material \$			Materia	1\$	· ·		
Labour \$			Labour	\$			
			P.O.#:				
Cause:							
Solution:							-
		/					
Date Comp	oleted: April 261	23	Ap _l	proved:		9 7	
	Time: Norum		Service Sig	nature:	STEVE		



Manjot Singh <msingh@newmar.com>

D390007 / N000531 ZANCOR CALEDON CLUB / Lot 127B

1 message

Mathew Harant <mharant@newmar.com>
To: Manjot Singh <msingh@newmar.com>
Co: Christina Pellegrini <cpellegrini@newmar.com>

Fri, Jan 20, 2023 at 11:53 AM

Hi Manjot,

Can you please create a SWO for this lot. The operating front door slab on line 30 is missing the executive panel and doorlite. See attached picture.

Thank you,

Mathew Harant Sales Account Manager

Newmar Window Manufacturing Inc.

7630 Airport Road Mississauga, Ontario L4T 4G6

Tel: 905-672-1233 Fax: 905-672-1076 Toll Free: 1-800-263-5634

www.newmar.com

Click here for information on Newmar Aluminum Window Wall systems

Manufacturers of Quality Windows and Entrance Door Systems

Please consider the environment before printing this email.

This e-mail and any attachments may contain information that is privileged and/or confidential. If you are not the intended recipient and appear to have received this e-mail in error, please notify us immediately and then delete all copies from your computer system. Any unauthorized use, copying or further distribution is prohibited. "Please also note that if you send us e-mails containing time-sensitive or important instructions, you should ensure that receipt has been timely acknowledged in view of the potential for misdirection or inedvertent interception. Thank you.



IMG_0116.jpg