## Outstanding Deficiencies Belle Aire Shores - Phase: 3 - Lot: 246W

	19May23	19May23	19May <u>23</u>	19May23	19May23	19May23	19May23	<u>19May23</u>	19May <u>23</u>	<u>19May23</u>	19May23	
	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	
		12 F	10	9	∞	7	6	4	ω	2	-	
	MASTER ENSUITE BATH- VANITY CABINETS-CHIP AT BOTTOM GABLE BELOW RIGHT SINK 2) CHIP AT BOTTOM RIGHT CABINET SHELF 3) INSPECT YELLOW MARK AT COUNTER LEFT COUNTER TOP 4) CHIP AT BOTTOM RIGHT GABLE RIGHT OF SINK AT LEFT VANITY		TY BELOW D CABINET OTTOM ELOW ND ND T SINK AT	AIR AT DOW	BEDROOM #4- WINDOWS~CRACK AT MIDDLE FIXED GLASS		S CINE IN	FOYER/HALL- STAIRSDENT ON 2ND TREAD AT STAIRS FROM LANDING TO 2ND FLOOR 2) CHIP ON INSIDE STRINGER BELOW NOISING AT 2ND FLOOR 3) CHIP AT INSIDE STRINGER BY TRIM AND RISER AT STAIRS FROM LANDING TO 2ND FLOOR 4) DENT ON TREAD BELOW NOISING AT LANDING TO 2ND FLOOR 5) DENT ON2,3,4,5 TREAD AT STAIRS FROM MAIN TO LANDING TO 2ND FLOOR. 6) CHIP ON STRINGER BELOW NOISING AT STAIRS TO BSMT 7) SECURE VENEER AT INSIDE STRINGER LEFT OF NOISING AT STAIRS TO BSMT 8) CHIP ON 3 TREAD AT BSMT LANDING TO GARAGE LANDING 9) CHIP ON NOISING AT STAIRS TO BSMT STAIRS TO BSMT	LIBRARY/DEN- FLOORING~CHIP ON 17, 20, 27, 28, 35, 36 PLANK FROM LEFT WALL FROM ENTRANCE FROM FOYER 2) DINNING LARGE CHIP AT LEFT HARDWOOD PLANK AT HEAT REGISTER BELOW WINDOW		BASEMENT- NOTE:~DUCTS NOT CLEANED	I I
_	New Image Kitchens 157139	AV Classic 157138	New Image Kitchens 157136	Foremont Drywall 157135	Newmar 157134	New Image Kitchens 157133	Foremont Drywall 157132	Bolton Railings Inc. 157130	<u>First</u> <u>Canadian</u> <u>Hardwood</u> 157129	New Image Kitchens 157128	Canada Carpet Care 157127	Assigned
-	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Trade
	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	e <u>Date</u>
		<		7		<	<					Completed
				P		2	À					d Initial

0.0	<	NoAppoint.	Add	Promark Aluminum LTD. 157143	EXTERIOR- NOTE:~EAVESTROUGH AND DOWNSPOUT NOT INSTALLED.	17	PDI	19May23
		NoAppoint.	Add	River Valley Masonry Group LTD 157142	EXTERIOR- NOTE:~MISSING BRICK AT FRONT PORCH LEFT OF PORCH LIGHT AT SOFFIT CEILING	16	PDI	19May23
		NoAppoint.	Add	Trudel & Sons Roofing LTD. 157141	EXTERIOR- SHINGLES~TORN SHINGLES AT ROOF PEAK ABOVE GARAGE CAN SEE FROM BEDROOM 4	15	PDI	19May23
	<	NoAppoint.	Add	<u>Central</u> <u>Glass</u> 157140	MASTEK ENSUITE BATH- SHOWER ENCLOSURE-SHOWER GLASS NOT INSTALLED	14	PDI	19May23

Reale
trant
porch

_
-
0
=
_
CD.
0
>-
-
_
CD .
~
p-4 +
(TO
9 =
_
22
atu
=
=
eri.
2.5
110

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Date: \_\_\_\_\_\_\_
Zancor Service Technician: \_\_\_\_\_\_