Enrollment:

Purchaser Name:

Modupe, Bolanie Oluyomi

Phone Res:

Phone Bus: (905) 770-6426 Closing Date: September 18, 2023

Inspector: Gisella Fiore

Page 1 of 2

HOMES

Vendor / Builder: 44528

Project: Zancor Homes (Innisfil) Ltd.

Lot / Phase: 308W / 3

Plan: Address:

Municiaplity:

Inspection Date: August 18, 2023

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

CABINETS UPPER CORNER CABINET NOT INSTALLED. POT LIGHT NOT INSTALLED IN UPPER CORNER CABINET. CUT OUT AT ISLAND FOR 2ND ELECTRICAL QUTLET NOT COMPLETE CHIP INSIDE CABINET HUTCH LEFT OF MICROWAVE AT UPPER GABLE AND BACK PANEL. CHIP INSIDE BOTTOM PANEL LEFT OF MICROWAVE CUT OUT. FLOORING CHIP AT 3RD HARDWOOD PLANK INFRONT OF ISLAND. MASTER ENSUITE BATH FAUCETS/PLUMBING ADJUST WINDOW AND CRANK VERY HARD TO OPEN. BEDROOM #2 WALLS DENT IN STIPPLE LEFT OF LIGHT AND HALLWAY RIGHT OF SMOKE DETECTOR. BEDROOM 2 ENSUITE VANITY CABINETS CHIP AT RIGHT GABLE RIGHT OF SINK AND INSIDE BOTTOM E GABLE. WALLS OVER CUT AT CEILING FAN. SHARED ENSUITE VANITY CABINETS CHIP AT BOTTOM LEFT AND RIGHT CABINET BELOW RIGHT SINK AND RIGHT CABINET BELOW RIGHT SINK FOYER/HALL STAIRS DRYWALL REPAIR REQUIRED AT STAIRS TO MUDROOM LIBRARY/DEN			
POT LIGHT NOT INSTALLED IN UPPER CORNER CABINET. CUT OUT AT ISLAND FOR 2ND ELECTRICAL OUTLET NOT COMPLETE CHIP INSIDE CABINET HUTCH LEFT OF MICROWAVE AT UPPER GABLE AND BACK PANEL. CHIP INSIDE BOTTOM PANEL LEFT OF MICROWAVE CUT OUT. FLOORING CHIP AT 3RD HARDWOOD PLANK INFRONT OF ISLAND. MASTER ENSUITE BATH FAUCETS/PLUMBING CAPPED WALL LIGHTS NOT INSTALLED ABOVE VANITY. NOTE: ADJUST WINDOW AND CRANK VERY HARD TO OPEN. BEDROOM #2 WALLS DENT IN STIPPLE LEFT OF LIGHT AND HALLWAY RIGHT OF SMOKE DETECTOR. BEDROOM 2 ENSUITE VANITY CABINETS CHIP AT RIGHT GABLE RIGHT OF SINK AND INSIDE BOTTOM E GABLE. OVER CUT AT CEILING FAN. SHARED ENSUITE VANITY CABINETS CHIP AT BOTTOM LEFT AND RIGHT CABINET BELOW RIGHT SINK AND RIGHT CABINET BELOW RIGHT SINK FOYER/HALL STAIRS DRYWALL REPAIR REQUIRED AT STAIRS TO MUDROOM LIBRARY/DEN	KITCHEN		
CUT OUT AT ISLAND FOR 2ND ELECTRICAL OUTLET NOT COMPLETE CHIP INSIDE CABINET HUTCH LEFT OF MICROWAVE AT UPPER GABLE AND BACK PANEL. CHIP INSIDE BOTTOM PANEL LEFT OF MICROWAVE CUT OUT. ELOORING CHIP AT 3RD HARDWOOD PLANK INFRONT OF ISLAND. MASTER ENSUITE BATH FAUCETS/PLUMBING CAPPED WALL LIGHTS NOT INSTALLED ABOVE VANITY. NOTE: ADJUST WINDOW AND CRANK VERY HARD TO OPEN. BEDROOM #2 WALLS DENT IN STIPPLE LEFT OF LIGHT AND HALLWAY RIGHT OF SMOKE DETECTOR. BEDROOM 2 ENSUITE VANITY CABINETS CHIP AT RIGHT GABLE RIGHT OF SINK AND INSIDE BOTTOM E GABLE. VALLS OVER CUT AT CEILING FAN. SHARED ENSUITE VANITY CABINETS CHIP AT BOTTOM LEFT AND RIGHT CABINET BELOW RIGHT SINK AND RIGHT CABINET BELOW RIGHT SINK FOYER/HALL STAIRS DRYWALL REPAIR REQUIRED AT STAIRS TO MUDROOM LIBRARY/DEN	CABINETS	UPPER CORNER CABINET NOT INSTALLED.	
CHIP INSIDE CABINET HUTCH LEFT OF MICROWAVE AT UPPER GABLE AND BACK PANEL. CHIP INSIDE BOTTOM PANEL LEFT OF MICROWAVE CUT OUT. FLOORING CHIP AT 3RD HARDWOOD PLANK INFRONT OF ISLAND. MASTER ENSUITE BATH FAUCETS/PLUMBING CAPPED WALL LIGHTS NOT INSTALLED ABOVE VANITY. NOTE: ADJUST WINDOW AND CRANK VERY HARD TO OPEN. BEDROOM #2 WALLS DENT IN STIPPLE LEFT OF LIGHT AND HALLWAY RIGHT OF SMOKE DETECTOR. BEDROOM 2 ENSUITE VANITY CABINETS CHIP AT RIGHT GABLE RIGHT OF SINK AND INSIDE BOTTOM E GABLE. WALLS OVER CUT AT CEILING FAN. SHARED ENSUITE VANITY CABINETS CHIP AT BOTTOM LEFT AND RIGHT CABINET BELOW RIGHT SINK AND RIGHT CABINET BELOW RIGHT SINK RIGHT SINK FOYER/HALL STAIRS DRYWALL REPAIR REQUIRED AT STAIRS TO MUDROOM LIBRARY/DEN		POT LIGHT NOT INSTALLED IN UPPER CORNER CABINET.	
CHIP INSIDE BOTTOM PANEL LEFT OF MICROWAVE CUT OUT. FLOORING CHIP AT 3RD HARDWOOD PLANK INFRONT OF ISLAND. MASTER ENSUITE BATH FAUCETS/PLUMBING CAPPED WALL LIGHTS NOT INSTALLED ABOVE VANITY. NOTE: ADJUST WINDOW AND CRANK VERY HARD TO OPEN. BEDROOM #2 WALLS DENT IN STIPPLE LEFT OF LIGHT AND HALLWAY RIGHT OF SMOKE DETECTOR. BEDROOM 2 ENSUITE VANITY CABINETS CHIP AT RIGHT GABLE RIGHT OF SINK AND INSIDE BOTTOM E GABLE. WALLS OVER CUT AT CEILING FAN. SHARED ENSUITE VANITY CABINETS CHIP AT BOTTOM LEFT AND RIGHT CABINET BELOW RIGHT SINK AND RIGHT CABINET BELOW RIGHT SINK FOYER/HALL STAIRS DRYWALL REPAIR REQUIRED AT STAIRS TO MUDROOM LIBRARY/DEN		CUT OUT AT ISLAND FOR 2ND ELECTRICAL OUTLET NOT COMPLETE	
FLOORING CHIP AT 3RD HARDWOOD PLANK INFRONT OF ISLAND. MASTER ENSUITE BATH FAUCETS/PLUMBING CAPPED WALL LIGHTS NOT INSTALLED ABOVE VANITY. NOTE: ADJUST WINDOW AND CRANK VERY HARD TO OPEN. BEDROOM #2 WALLS DENT IN STIPPLE LEFT OF LIGHT AND HALLWAY RIGHT OF SMOKE DETECTOR. BEDROOM 2 ENSUITE VANITY CABINETS CHIP AT RIGHT GABLE RIGHT OF SINK AND INSIDE BOTTOM E GABLE. WALLS OVER CUT AT CEILING FAN. SHARED ENSUITE VANITY CABINETS CHIP AT BOTTOM LEFT AND RIGHT CABINET BELOW RIGHT SINK AND RIGHT CABINET BELOW RIGHT SINK FOYER/HALL STAIRS DRYWALL REPAIR REQUIRED AT STAIRS TO MUDROOM LIBRARY/DEN		CHIP INSIDE CABINET HUTCH LEFT OF MICROWAVE AT UPPER GABLE AND BACK PANEL.	
MASTER ENSUITE BATH FAUCETS/PLUMBING CAPPED WALL LIGHTS NOT INSTALLED ABOVE VANITY. NOTE: ADJUST WINDOW AND CRANK VERY HARD TO OPEN. BEDROOM #2 WALLS DENT IN STIPPLE LEFT OF LIGHT AND HALLWAY RIGHT OF SMOKE DETECTOR. BEDROOM 2 ENSUITE VANITY CABINETS CHIP AT RIGHT GABLE RIGHT OF SINK AND INSIDE BOTTOM E GABLE. WALLS OVER CUT AT CEILING FAN. SHARED ENSUITE VANITY CABINETS CHIP AT BOTTOM LEFT AND RIGHT CABINET BELOW RIGHT SINK AND RIGHT CABINET BELOW RIGHT SINK FOYERHALL STAIRS DRYWALL REPAIR REQUIRED AT STAIRS TO MUDROOM LIBRARY/DEN		CHIP INSIDE BOTTOM PANEL LEFT OF MICROWAVE CUT OUT.	
FAUCETS/PLUMBING CAPPED WALL LIGHTS NOT INSTALLED ABOVE VANITY. NOTE: ADJUST WINDOW AND CRANK VERY HARD TO OPEN. BEDROOM #2 WALLS DENT IN STIPPLE LEFT OF LIGHT AND HALLWAY RIGHT OF SMOKE DETECTOR. BEDROOM 2 ENSUITE VANITY CABINETS CHIP AT RIGHT GABLE RIGHT OF SINK AND INSIDE BOTTOM E GABLE. WALLS OVER CUT AT CEILING FAN. SHARED ENSUITE VANITY CABINETS CHIP AT BOTTOM LEFT AND RIGHT CABINET BELOW RIGHT SINK AND RIGHT CABINET BELOW RIGHT SINK FOYERHALL STAIRS DRYWALL REPAIR REQUIRED AT STAIRS TO MUDROOM LIBRARY/DEN	FLOORING	CHIP AT 3RD HARDWOOD PLANK INFRONT OF ISLAND.	
NOTE: ADJUST WINDOW AND CRANK VERY HARD TO OPEN. BEDROOM #2 WALLS DENT IN STIPPLE LEFT OF LIGHT AND HALLWAY RIGHT OF SMOKE DETECTOR. BEDROOM 2 ENSUITE VANITY CABINETS CHIP AT RIGHT GABLE RIGHT OF SINK AND INSIDE BOTTOM E GABLE. WALLS OVER CUT AT CEILING FAN. SHARED ENSUITE VANITY CABINETS CHIP AT BOTTOM LEFT AND RIGHT CABINET BELOW RIGHT SINK AND RIGHT CABINET BELOW RIGHT SINK FOYER/HALL STAIRS DRYWALL REPAIR REQUIRED AT STAIRS TO MUDROOM LIBRARY/DEN	MASTER ENSUITE BATH		
BEDROOM #2 WALLS DENT IN STIPPLE LEFT OF LIGHT AND HALLWAY RIGHT OF SMOKE DETECTOR. BEDROOM 2 ENSUITE VANITY CABINETS CHIP AT RIGHT GABLE RIGHT OF SINK AND INSIDE BOTTOM E GABLE. WALLS OVER CUT AT CEILING FAN. SHARED ENSUITE VANITY CABINETS CHIP AT BOTTOM LEFT AND RIGHT CABINET BELOW RIGHT SINK AND RIGHT CABINET BELOW RIGHT SINK FOYER/HALL STAIRS DRYWALL REPAIR REQUIRED AT STAIRS TO MUDROOM LIBRARY/DEN	FAUCETS/PLUMBING	CAPPED WALL LIGHTS NOT INSTALLED ABOVE VANITY.	
WALLS DENT IN STIPPLE LEFT OF LIGHT AND HALLWAY RIGHT OF SMOKE DETECTOR. BEDROOM 2 ENSUITE VANITY CABINETS CHIP AT RIGHT GABLE RIGHT OF SINK AND INSIDE BOTTOM E GABLE. WALLS OVER CUT AT CEILING FAN. SHARED ENSUITE VANITY CABINETS CHIP AT BOTTOM LEFT AND RIGHT CABINET BELOW RIGHT SINK AND RIGHT CABINET BELOW RIGHT SINK FOYER/HALL STAIRS DRYWALL REPAIR REQUIRED AT STAIRS TO MUDROOM LIBRARY/DEN	NOTE:	ADJUST WINDOW AND CRANK VERY HARD TO OPEN.	
BEDROOM 2 ENSUITE VANITY CABINETS CHIP AT RIGHT GABLE RIGHT OF SINK AND INSIDE BOTTOM E GABLE. WALLS OVER CUT AT CEILING FAN. SHARED ENSUITE VANITY CABINETS CHIP AT BOTTOM LEFT AND RIGHT CABINET BELOW RIGHT SINK AND RIGHT CABINET BELOW RIGHT SINK FOYER/HALL STAIRS DRYWALL REPAIR REQUIRED AT STAIRS TO MUDROOM LIBRARY/DEN	BEDROOM #2		
VANITY CABINETS CHIP AT RIGHT GABLE RIGHT OF SINK AND INSIDE BOTTOM E GABLE. WALLS OVER CUT AT CEILING FAN. SHARED ENSUITE VANITY CABINETS CHIP AT BOTTOM LEFT AND RIGHT CABINET BELOW RIGHT SINK AND RIGHT CABINET BELOW RIGHT SINK FOYER/HALL STAIRS DRYWALL REPAIR REQUIRED AT STAIRS TO MUDROOM LIBRARY/DEN	WALLS	DENT IN STIPPLE LEFT OF LIGHT AND HALLWAY RIGHT OF SMOKE DETECTOR.	
WALLS OVER CUT AT CEILING FAN. SHARED ENSUITE VANITY CABINETS CHIP AT BOTTOM LEFT AND RIGHT CABINET BELOW RIGHT SINK AND RIGHT CABINET BELOW RIGHT SINK FOYER/HALL STAIRS DRYWALL REPAIR REQUIRED AT STAIRS TO MUDROOM LIBRARY/DEN	BEDROOM 2 ENSUITE		
SHARED ENSUITE VANITY CABINETS CHIP AT BOTTOM LEFT AND RIGHT CABINET BELOW RIGHT SINK AND RIGHT CABINET BELOW RIGHT SINK FOYER/HALL STAIRS DRYWALL REPAIR REQUIRED AT STAIRS TO MUDROOM	VANITY CABINETS	CHIP AT RIGHT GABLE RIGHT OF SINK AND INSIDE BOTTOM E GABLE.	
VANITY CABINETS CHIP AT BOTTOM LEFT AND RIGHT CABINET BELOW RIGHT SINK AND RIGHT CABINET BELOW RIGHT SINK FOYER/HALL STAIRS DRYWALL REPAIR REQUIRED AT STAIRS TO MUDROOM LIBRARY/DEN	WALLS	OVER CUT AT CEILING FAN.	
RIGHT SINK FOYER/HALL STAIRS DRYWALL REPAIR REQUIRED AT STAIRS TO MUDROOM LIBRARY/DEN	SHARED ENSUITE		
STAIRS DRYWALL REPAIR REQUIRED AT STAIRS TO MUDROOM	VANITY CABINETS		
LIBRARY/DEN	FOYER/HALL		
	STAIRS	DRYWALL REPAIR REQUIRED AT STAIRS TO MUDROOM	
WALLS OVER CIT AT AIR RETURN ON WALL	LIBRARY/DEN		 <u> </u>
WALLO OVERTOOT AT AIRTHETORIN ON WALL.	WALLS	OVER CUT AT AIR RETURN ON WALL.	

Enrollment:
Purchaser Name: ??????

Modupe, Bolanie Oluyomi

Phone Res:

Phone Bus: (905) 770-6426
Closing Date: September 18, 2023
Inspector: Gisella Fiore

ZANCOR HOMES PDI Vendor / Builder: 44528

Project: Zancor Homes (Innisfil) Ltd.

Lot / Phase: 308W / 3

Plan: Address: Municiaplity:

Inspection Date: August 18, 2023

Date.	September 16, 2023	
ector:	Gisella Fiore	Page 2 of 2

A REFERENCE FOR FUTURE WARF	RANTY REQUESTS. o designate someone to conduct the PDI in the	E HOME'S CONDITION BEFORE THE PURCHASI	
I have inspected my new home and	I agree that the description of the items listed	on this form are accurate.	
??????	Selpomi	Modupe, Bolanie Oluyomi	
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature
		Gisella Fiore	All
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature
Date (YYYY/MM/DD)	2023/08/18	August 18, 2023	