Enrollment:

Purchaser Name: Tamir Hezkial

Phone Res: Phone Bus: (647) 231-3305 HOMES

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 108B / 1B

Plan: Address: Municiaplity:

Inspection Date: September 15, 2023

Closing Date: October 19, 2023 Inspector: Gisella Fiore

Page 1 of 3

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

MASTER ENSUITE BATH		
COUNTERTOPS	CHIP AT RIGHT SIDE OF COUNTERTOP. BELOW COUNTERTOP EDGE RIGHT OF SINK AND	
	BEHIND RIGHT FACUET LEFT SIDE. AND SCRATCHES INFRONT OF LEFT AND RIGHT SINK.	
WALLS	INSPECT WALL TILE INSIDE SHOWER HOMEOWNER UNHAPPY WITH CUTS ALL DIFFERENT	
	SIZES	
	AS PER HOMEOWNER TOP OF MARBLE JAMB CRACKED AT CORNER OF SHOWER. RIGHT AND	
	LEFT SIDE.	
	MISSING MEDAL EDGE AT SHOWER CORNER TILE.	
NOTE:	FLOOR REGISTER IN TOLIET ROOM NOT FITTING.	
-	INSPECT BOW IN WALL ABOVE TOLIET AT CEILING.	
LAUNDRY ROOM		
CABINETS	CRACK ON COUNTERTOP EDGE LEFT OF SINK	
WINDOWS	ADJUST WINDOW MAKING NOISE WHEN OPENING	
FOYER/HALL		
STAIRS	AS PER HOMEWONER PICKETS ARE NOT STRAIGHT.	
	SCRATCH ON NEWEL POST AT 2ND FLOOR CAP AND LANDING EDGE AT NEWEL. AND MAIN	
	LEVEL RIGHT SIDE.	
	LINE IN VARNISH AT TREAD AT STAIRS FROM MUD ROOM TO MAIN.	
	CHIP/ROUGH NOSING AT STAIRS FROM MUDROOM TO MAIN N	
FLOORING	MISSING TILE INSIDE FOYER CLOSET.	
	X3 TILES CHIPPED IN MUDROOM.	
SHARED ENSUITE		
COUNTERTOPS	DAMAGE ON RIGHT SIDE SPLASH RIGHT OF SINK	
NOTE:	HOMEOWNER REQUESTING TO HAVE REGISTER INFRONT OF DOOR LOCATION CHANGED.	
	SECURE BACK PANEL BELOW RIGHT SINK	
FAUCETS/PLUMBING	REMOVE PLASTIC FROM BEHIND TUB FILLER.	
BEDROOM #3		
WINDOWS	SCRATCH ON OPERATING WINDOW LEFT SIDE AND ADJUST WINDOW.	

Enrollment:

Purchaser Name: Tamir Hezkial

ZANCOR HOMES PDI

Page 2 of 3

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 108B / 1B

Plan: Address:

Municiaplity:
Inspection Date: September 15, 2023

Phone Res:
Phone Bus: (647) 231-3305
Closing Date: October 19, 2023

Inspector: Gisella Fiore

BEDROOM 4 ENSUITE VANITY CABINETS CHIP ON RIGHT SIDE OF COUNTERTOP AT EDGE. NOTE: ADJUST WINDOW NOT OPENING. BEDROOM #4 FLOORING SECURE CARPET AT SEAM BELOW SINK -SEAM OPENING DINING ROOM OVER CUT AT POT LIGHT. WALLS FLOORING INSPECT MARK ON HARDWOOD PLANK RIGHT OF ARCH WAY AT ENTRANCED FROM DINNING POWDER ROOM NOTE CHIP AT BOTTOM RIGHT AND LEFT CABINET BELOW SINK KITCHEN FLOORING OVER CUT AT HEAT REGISTER AND X2 TILE BESIDE CHIPPED. SCRATCH AT TILE BELOW ISLAND FACING LIVING AREAS. CABINETS SCRATCH ON GARBAGE DRAWER AT ISLAND LEFT SIDE AND FLOOR LINE OF LEFT SIDE GABLE CHIP ON BACK GABLE AT ISLAND AT FLOOR LINE AND BOTTOM RIGHT CABINET BELOW SINK. CHIP AT CORNER CABINET RIGHT OF FRIDGE X2. SECURE CROWN MOULDING THROUGHOUT GAP. CHIP AT CROWN MOULDING BOX RIGHT SIDE RIGHT OF FRIDGE. CHIP INSIDE UPPER CABINET LEFT OF HOODFAN INSIDE AT TOP GABLE. HOMEOWNER REQUESTING TO ADJUST CABINET THROUGHOUT. CHIP AT UPPER RIGHT AND LEFT GABLE AT HOODFAN. CHIP AT UPPER RIGHT CABINET RIGHT OF HOODFAN AND END OF VALANCE AT DRYWALL RIGHT SIDE. EXTERIOR NOTE: SCRATCH ON, RIGHT AND LEFT SIDE AT EXTERIOR DOORS AND BURLAP AT TRIM CAULKING NOT COMPLETE A COLD SELLER ROOM VENT BLACK TARP RIPPED OUT LEFT SIDE OF HOUSE, INSPECT CHIPPED BRICK I LEFT SIDE OF HOUSE BY SIDE ENTRANCE DOOR OPENER, REQUESTING MEETING FOR CHIPS BRICKS THROUGHOUT UNHAPPY WITH CHIPS AND MOTAR INSPECT HARDY, REAR OF HOME RIGHT SIDE OF AC AT TOP CORNER WHITE MAR MISSING BRICK BEHIND GAS, RIGHT SIDE OF HOUSE **BRICKS** INSPECT STONE , RIGHT OF RAILING, LEFT OF GARAGE DOOR FLAKING INSPECT BRICKS AT UPPER WALL ABOVE LEFT GARAGE DOOR RIGHT OF WINDOWS FOR CRACK CHIP ON LEFT GARAGE DOOR TRIM AND TRIM ABOVE. AND RIGHT TRIM RIGHT OF DOOR WEATHERSTRIP AT LEFT GARAGE DOOR RIPPED GARAGE DOORS ADJUSR WEATHERSTRIP I LEFT GARAGE DOOR

Enrollment:

Purchaser Name: Tamir Hezkial

Phone Res:

Phone Bus: (647) 231-3305
Closing Date: October 19, 2023
Inspector: Gisella Fiore



Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 108B / 1B

Plan: Address: Municiaplity:

Inspection Date: September 15, 2023

Page 3 of 3

A REFERENCE FOR FUTURE WARRANT	Y REQUESTS. signate someone to conduct the PDI in the	HOME'S CONDITION BEFORE THE PURCHASE oir place should ensure they provide written author	
I have inspected my new home and I agre	ee that the description of the items listed o	n this form are accurate.	
Tamir Hezkial	191		
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature
		Gisella Fiore	DAL.
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature
Date (YYYY/MM/DD)	2023/09/15	September 15, 2023	