Enrolment # H3608653

Outstanding Items

List all outstanding items covered by the statutory warranty in the table below. If you require more space, please make copies of this page, number them and attach them to this Statutory Warranty Form.

IMPORTANT: Outstanding items must be specifically listed and described in the table below. To make a claim for an item that is on your PDI Form or that was reported by a home inspector, engineer, or other consultant, list and describe the item in the table. Include in the item description where the item is identified in the PDI Form or consultant's report (e.g., page or item number). Include the PDI Form or consultant's report as an attachment when you submit this Statutory Warranty Form.

THE OVE GROUT C	RCJ1 BAS	T (0 C	MD CA.	+5 1001	TAIR	5 _	GRAN IN K	STECHE	N 50 .	-	TR	- ?M	OVE	ERCU	7	@	KITCA	HEN	AIRC	iu	
30	37	36	35	34	33	32	31	30	29	28	0	27	26	25	24	23	22	21	20	19	18	17
ataiweii needish.jpg staicweil need(2).jpg INTERIOR	INTERIOR	INTERIOR	INTERIOR	INTERIOR	INTERIOR	INTERIOR	INTERIOR	INTERIOR	INTERIOR	INTERIOR	kitchen islandket.jpg	INTERIOR	INTERIOR	SEAM IN	INTERIOR kitchen islandble.jpg	INTERIOR	INTERIOR	INTERIOR	INTERIOR	INTERIOR	INTERIOR	INTERIOR
Floor 02	Floor 01	Floor 01	Floor 01	Floor 01	Floor 01	Floor 01	Floor 01	Floor 01	Floor 01	Floor 01	AVAINT AVAINT STATEMENT ST	Floor 01	Floor 01	Floor 01	Floor 01 ABO	Floor 01	Floor 01	Floor 01	Floor 01	Floor 01	Floor 01	Floor 01
STAIN T/US + VARNISH Bedroom	Stairs	Bathroom	Bathroom	Bathroom ADWST	Hallway	Hallway J	Hallway NEEDS	Hallway	Hallway	Kitchen	O-RING	Kitchen	Kitchen	BUSE COUNTER	Ritchen PLATE TO 1	Kitchen	Kitchen	Kitchen	Living Room	Living Room	Living Room	Living Room
Wall	Staircase/Steps	2	8	Other (Please describe)	JAMB DAMACE	Floor N PGJ	Trim BUE	wall Ptp	Ceiling PtP	Other Please describ	MAR STICKING OUT	Sink	Cabinet(s) Due	Countertop PATCH	Countertop FACUE T	Electrical PART	Doors REPLACE	Wall STAIN PEN	Windows DAP?	Trim Cove		Floor STAN PEN
varnish stairwell excess varnish (2) PRIMARY ROOM:	• Scratches and dents are visible in many areas and throughout the stairwell. This needs a second coating and	 Visible gaps on the frames either need recaulking or repainting. 	Powder room – broken tile needs replacing	• Fan not secured – need to be flush with ceiling.	Gap below the door going to the garage.	 Gaps below the stairs, tile replacement. Gaps and scratches 	• Big gaps exposed below the baseboards, unattractive trims – need fixing.	 Visible dents, scratches, bumps, and cracks – needs touchup and second coat of paint 	 Visible dents, scratches, bumps, and cracks – needs touchup and second coat of paint 	Other (Please describe) Visible gaps on the frames either need recaulking or repainting.	kitohen island sink gasket	• Rubber gasket coming out of the faucet – needs fixing.	• Cabinet kickboard crack – needs to be replaced.	• Dark stain in and around the faucet – discoloured island face.	 Hole/Drill marks beside faucet – replace island kitchen island counter hole visible 	• Not centered (upgraded) – needs to be moved over	Damaged lock/hook – needs replacing	Visible dents, scratches, bumps, and cracks – needs touchup and second coat of paint	• Visible gaps on the frames either need recaulking or repainting	• Big gaps exposed below the baseboards, unattractive trims—need fixing NEO TO SE FILEO + PANT	• Visible dents, scratches, bumps, and cracks – needs touchup and second coat of paint	Scratches, dents, and uneven coating are visible - Floors need a second coat

F

- MISSING CLIPONE PIECE ON RICLIT FACUET

WALLS:
 Visible dents, scratches, bumps, and cracks – needs touchup and second coat of paint

BATHROOM 2 (PJ):	Bathtub	Bathroom	a distribution and	Floor 02	INTERIOR	52
BEDROOM 2 (PJ): 3. FLOOR: Burnt carpet – needs to be replaced.	Pain They To	Bedroom OR M	6.	Floor 02 CEMIAL	TERIOR W	SI IN IN
BEDROOM 2 (PJ): 2. WINDOWS: • Visible gaps on the frames either need recaulking or repainting.	Windows DAP	Bedroom	in the control of the	Floor 02	INTERIOR	50
BEDROOM 2 (PJ): 1. WALLS: • Visible dents, scratches, bumps, and cracks – needs touchup and second coat of paint.	Ptp Wall	Bedroom		Floor 02	INTERIOR	49
PRIMARY CLOSET: 1. WALLS: • Visible dents, scratches, bumps, and cracks – needs touchup and second coat of paint.	Closet P+P	Bedroom	NAV-(Albin- HARZAGARA)	Floor 02	INTERIOR	48
PRIMARY BATHROOM: 4. WINDOWS: • Visible gaps on the frames either need recaulking or repainting.	Windows	Bathroom OAP?		Floor 02	INTERIOR	47
PRIMARY BATHROOM: SINK: The right sink has hardened brown markings in the sink needs replacing.	Sink	Bathroom Bove	Mahawa (W. Waller Colonology	Floor 02	INTERIOR	46
PRIMARY BATHROOM: 2. DRAWER: • The drawer below the sink has dents.	Cabinet(s) Depute Flout	Bathroom	OFUT	Floor 02	INTERIOR	45
PRIMARY BATHROOM: 1. TILES: • Tiles with large gaps – need replacing.	Floor	Bathroom OVEROVI	001 02 6 RODT	Floor 02	INTERIOR FI	EAVE
 PRIMARY BATHROOM: TILES: Throughout the shower, flooring and tiles need grouting and caulking. 	Shower	Bathroom Ooue		Floor 02	INTERIOR	43
PRIMARY BATHROOM: 1. TILES: • Shower - Needs caulking and grouting.	Floor	Bathroom Dowe		Floor 02	INTERIOR	42
PRIMARY ROOM: 3. DOORS: • Cracked and bumpy - needs repainting primary door needs repainting primary door needs repainting (3)	BURLAP CRAINS	REPLACE WITH OF	- 2	Floor 02	INTERIOR primary door ning.jpg primary door n(3).jpg	41
2. WINDOW FRAMES;Visible gaps on the frames either need recaulking or repainting.	Windows OAR?	Bedroom	is special and	Floor 02	INTERIOR	40
2. WINDOW FRAMES: • Scratched frames need fixing.	Windows SCUFES	Bedroom CLEAN	Total and	Floor 01	INTERIOR	39
roughly and second coar of paint						

- Recaulking around the tub rough edges need to be softened.

WINDOWS: Visible gaps on the frames either need recaulking or repainting.	Windows	Bathroom	Floor 02	INTERIOR	66
2. BATHTUB: • Gaps between tub and tiles need regrouting.	Bathrub	Bathroom	Floor 02	INTERIOR	65
BATHROOM 3 & 4: 1. TILES:• More caulk in the bathtub.	Bathtub	Bathroom	Floor 02	INTERIOR	64
BATHROOM 3 & 4: 1. TILES: • Around the bathtub and the corners needs regrouting.	Wall	Bathroom	Floor 02	INTERIOR	63
BATHROOM 3 & 4: L TILES: Gaps on tiles exposed up and down the hathroom.	Bathtub	Bathroom	Floor 02	INTERIOR	0.2
BATHROOM 3 & 4: 1. TILES: • Gaps on tiles exposed up and down the bathroom. KM bath tile gap KM bath tile broken	7 4	Bathroom SILIGUE SILIGUE	Floor 02	INTERIOR KM bath tile gap.jpg KM bath tile broken.jpg	61
BEDROOM 4 (Kathleen): 2. WINDOWS: (throughout house) • Visible gaps on the frames either need recaulking or repainting.	Windows PAP	Bedroom	Floor 02	INTERIOR	60
BEDROOM 4 (Kathleen): 1. WALLS: • Visible dents, scratches, bumps, and cracks – needs touchup and second coat of paint.	PP 9	Bedroom	Floor 02	INTERIOR	59
BEDROOM 3 (Marieris): 2. WINDOWS: • Visible gaps on the frames either need recaulking or repainting.	$\mathcal{O}\mathcal{H}^{\mathcal{C}}$	Bedroom	Floor 02	INTERIOR	58
BEDROOM 3 (Maricris): 1. WALLS: • Visible dents, scratches, bumps, and cracks – needs touchup and second coat of paint.	PtP Wali	Bedroom	Floor 02	INTERIOR	57
CLOSET 2 (PJ): 1. WALLS: • Visible dents, scratches, bumps, and cracks – needs touchup and second coat of paint.	Pt9	Bedroom	Floor 02	INTERIOR	56
BATHROOM 2 (PJ): ** PIC ** 3. TILES: • Gaps between the tiles – needs replacing.	Floor T SOURCE	Bathroom The LOT	Floor 02	INTERIOR	55
BATHROOM 2 (PJ): 2. WINDOWS: • Visible gaps on the frames either need recaulking or repainting.	Windows	Bathroom	Floor 02	INTERIOR	54
BATHROOM 2 (PJ):• Blue mark in the bathtub – needs removing	Bathtub	Bathroom ObvE	Floor 02	INTERIOR	53
סטנואואטו.		And Self-Self-Self-Self-Self-Self-Self-Self-		DO FORGINATION IN THE PROPERTY OF THE PROPERTY	9040 ER 2

и на принципалний	JUNIO)/ck	STREEN CONTROL OF THE	fix.jpg	MEN WEIGH
laundry tile fix	Trim	Laundry Room	Floor 02	laundry tile	11
inemperatura in the control of the c	PORTUGE SENSOR STATEMENT OF STATEMENT SENSOR STATEMENT SENSOR SEN	evilletaring dans de reconstructures de la construction de la construc		screing.jpg	
stairwell secow showing			selection)	smirvell	
Other (Please describe) stairwell screw showing	Other (Please describ	Stairs	Other (Choose	INTERIOR	76
KM bath counter scratch KM bath counter scratch KM bath counter scratch (2)	Countertop	Bathroom	Floor 02	INTERIOR KM bath countereh.jpg KM bath counte(2).jpg	75
The district plate and the second consequence of the second consequenc		CUX4.12		f(2).jpg	MODEL NAMES OF THE PARTY OF THE
Tarion Innisfil Photos Tarion Innisfil Photos primary beta faucet cap missing (2)	M165/	Cllows		frimally bath fining jpg primary bath	
Primary bathroom faucet cap is missing and is leaking	Sink	Bathroom	Floor 02	INTERIOR	74
basement directrical panel incorrectly labeled	3000			basement electled.jpg	
 Switches on the panel board are not properly labeled according to their use – needs to be rewritten 		your next selection)			
2. ELECTRICAL PANEL	Electrical	Other (Choose	Basement	INTERIOR	73
basement windowsk3 need screens	1 3/6	NAMES OFFICE AND PARTY OF THE P		windoens.jpg	
	2 SMALL	selection)			
• Three screens are needed for the smaller windows.	Windows	Other (Choose	Basement	INTERIOR	72
Basement frame broken			C	Basement frame broken.jpg	
 Big window - completely broken frame, needs replacement. 	クポン	your next selection)			
1. WINDOWS:	Windows	Other (Choose	Basement	INTERIOR	71
 Big gaps exposed below the baseboards, unattractive trims – need fixing, upstairs trim gap needs repaint 	DAP			ns sain	
2. BASEBOARD and TRIMS:	Trim	Hallway	Floor 02	INTERIOR	70
to the wall needs repaireing	8+P			acuff on wall	
1. WALLS:	Wall	Hallway	Floor 02	INTERIOR	69
2. WINDOWS:Visible gaps on the frames either need recaulking or repainting.	Windows PAP	Laundry Room	Floor 02	INTERIOR	68
 WALLS: Visible dents, scratches, bumps, and cracks needs touchup and second coat of paint. 	P.P	Laundry Room	Floor U2	INTERIOR	0/
MATERIAL PROPERTY PRO			TI TO THE TANK	TATE TOP	200

STAIR WELL CANDING DENTS ON