



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2
TEL (905) 672-1233 FAX (905) 672-1076

WO # W20319
Pack Slip:5521

Service Date: Dec 08, 2023

Priority: Normal Status: **SCHEDULED** RELEASED

BUILDER

Customer: 8030030 City: OAKVILLE Received: Nov 08, 2023
Name: ZANCOR THE BRANCH CONDOS Service Phone(s):
Service Fax: Site Phone: (416) 566-2066 Order: H801163-1
Site Fax: Lot#: 2ND FLOOR Phase: 242

RESIDENT INFORMATION

Home Owner Name: ANNII ODINAKA OKONKWO Address:
Home Phone(s): Work Phone(s):
Cell Phone(s): 416-721-0769 Email(s): OKONKWOCHUKA@GMAIL.COM

LINKED ORDER INFORMATION (H801163-1)

Customer: 8030030 ZANCOR THE BRANCH CONDOS House Model: 2ND FLOOR
Lot #: 2ND FLOOR Phase: Elevation:

SERVICE INSTRUCTIONS

INVESTIGATE AND CORRECT

UNIT 242 - MISSING IT'S BOTTOM SIDE BEAUTY CAP. ALL OF THE SIDE TRIM WILL HAVE TO BE REDONE

SEE PICTURES ATTACHED

DAI #166973 - PDI - LIVING ROOM - WINDOWS - MULLIN TRIM CUT TOO SHORT RIGHT OF WINDOW

DAI #166974 - PDI - BEDROOM 2 - WINDOWS - MULLIN CUT TOO SHORT RIGHT OF FIXED WINDOW - DONE

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
10	84 - BEAUTY CAP 4 REQUIRE PROFILE #84 IN WHITE @ SOME LENGTHS COMPLETED	TBA	OTHER - REPLACEMENT PARTS	0 X 0	BONE WHITE UC113812 SOME LENGTHS	3
20	85 - BEAUTY CAP BRACKET REQUIRE PROFILE #85 - SMALL PIECES COMPLETED	TBA	OTHER - REPLACEMENT PARTS	0 X 0		15
30	51 - H BAR REQUIRE PROFILE #51 @ 13 3/4" LONG. ON MY DESK	LIVING ROOM	OTHER - REPLACEMENT PARTS	13 3/4	BONE WHITE UC113812	1

Problem Description:

☐ Warranty ☐ CHARGEABLES
Material \$ _____ Material \$ _____
Labour \$ _____ Labour \$ _____
P.O.#: _____

Cause:

Solution:

Date Completed: _____

Approved: _____

Time: _____

Service Signature: _____

BENNY