Zancor Homes (Innisfil) Ltd. Warranty Services

Fax: (905) 738-5948 Phone: (905) 738-7010

Work Order

Closing Date:
Address: 190ct23

1323 Stevens Road

Innisfil

Belle Aire Shores - Phase: 3 - Lot: 87W

Location;

Today's Date:

27Dec23 0 30

Email: Gary, Martins Dinis - Home: (416) 898-7514 - (gary.dinis18@hotmail.com) gary.dinis18@hotmail.com

Contact(s):

Company: Zancor - Innisfil Warranty Service

Attention: Telephone:

Fax:

	7
1	_
4	0
П	0)
П	CO
- 1	0
н	_
П	Ç,
-	
1	3
ı	\Rightarrow
-1	Q
4	e
1	-
ı	0
	-
1	\exists
1	<u>_</u>
1	735
л	ᅎ
1	=
П	7
4	Y
7	≥
1	-
1	_
у	S.
1	-
ł	~
-1	⋍
1	ᆿ
1	ίÑ
1	
i	
ş	

the same of the sa				
169029	169025	166426	166425	DAI
30-Day	30-Day	Interval	Interval	Туре
Exterior- General- Condition: Left side basement window frame is damaged Location: Left side	Exterior- General- Condition: At gas entrance pipe into the home, several bricks are stained with paint. Location: Left side (facing home) As per item 5 on Home Inspection report-svc to remove paint at brick at gas line	Exterior- General- svc to check all basement windows and clean around	Exterior- General- trim piece at window damaged - noted at key pick up	Issue
05Jan24 /am	05Jan24 /am	05Jan24 /am	05Jan24 /am	Appt. Date/Time
SAME FROM			NEED MATERIAL	Notes
1			/	

11-Mariford Marian American Street				
169049	169047	169046	169043	-
30-Day	30-Day	30-Day	30-Day	
Exterior- General- Condition: Exterior lights to be sealed around with caulking to prevent water and insect intrusion into electrical box. Location: Exterior As	Exterior- General- Exterior receptacle boxes to be sealed around with caulking to prevent water and insect intrusion into electrical box. Location: Exterior As per item 25 of home inspection report-WE DO NOT CAULK THERE	Basement- General-Condition: Inadequate service size Main home service is undersized 100 amps instead of 200amps as per building code: 9.34.4.1 3a Item 23 on home inspection report-NA	Basement- General-Condition: Notches or holes Above basement staircase wall the I joist has been illegally drilled through the bottom chord of the structural member. The hole was drilled to run electrical wiring. Location: Basement As per item 21 on home inspection re	(facing home) As per item 9 on Home Inspection report-damaged vinyl
05Jan24 /am	05Jan24 /am	05Jan24 /am	05Jan24 /am	
RE-TRADE TO C.J CAUCIUM	AT SARINGA RE-TRADE TO C.J CAUKING	NA	NA	

	DUE	/am		General- Master bathroom doorstop incorrectly installed behind the bathtub. Location: Master Bathroom As per item 42 of home inspection report-NA		
		05Jan24	accionac	repo-CAULK JAMB Main Bathroom-	30-Day	169065
		05Jan24 /am	SHONE	General- Condition: Gaps are present at threshold pieces throughout the master bathroom shower. Location: Master Bathroom As per item 39 of home inspection	30-Day	169062
3	Fram 15 SECURED	8	doctory)	Location: Attic As per item 36 of home inspection report		
*	FTER	05Jan24 /am		Master Bedroom- General- Attic hatch is poorly painted.	30-Day	169059
ATRIC HATCH	FOAM INSULATION SECURFO TO AT			attached to the attic hatch.		
	RE-TRACE	/am	•	General- ATTIC/ROOF \ Hatch/Door Condition: Not insulated Attic		
		05Jan24		Master Bedroom-	30-Day	169058
Ell	BLACK HILH-HIGHT SPRAY PAINT FROM NATIONAL			in various areas. Location: Family Room As per item 34 of home inspection report-REMOVE PAINT AT FIREPLACE		
	NEAD	05Jan24 /am	4	Family Room- General- Condition: Fireplace surround is damaged and painted	30-Day	169056
				per item 28 on home inspection report-NA		

Contraction of the Contraction o				
169094	169089	169087	169071	169068
30-Day	30-Day	30-Day	30-Day	30-Day
Garage- General- Condition: Threshold is poorly supported leaving half it floating in the air. Location: Garage Man Door As per item 61 of home	Bedroom 2- General- Condition: Poor finish on closet doorway jamb. Rough/orange peel texture. Location: Master Bedroom Closet As per item 59 of home inspection report	Condition: Damage Condition: Damage Door is minorly damaged or require minor paint touch ups: Master bedroom operable door Foyer linen closet Location: Master bedroom operable door, Foyer linen closet	Master Ensuite- General- Ceiling poorly finished above master bathroom shower top threshold piece. Location: Master Bathroom As per item 47 of home inspection report- @JAMB	Other- General-Condition: Localized paint defects on walls, ceilings, and trim marked with green tape and/or yellow filler Location: Throughout As per item 45 of home inspection report
ET BE IN	An and an			discontinuo de la constante de
05Jan24 /am	05Jan24 /am	05Jan24 /am	05Jan24 /am	05Jan24 /am
Done	Dave	Done	DONE	Donk

	1			
169126	169125	169109	169105	
30-Day	30-Day	30-Day	30-Day	
Exterior- General-Grounding conduit by electrical entrance to home needs to be set closer to the foundation of home, tripping hazard currently Location: Left side of home near	Exterior- General- Window wells in backyard are not centered with windows, additionally they are not level either (slanted or much higher than other wells) Location: Backyard (Facing back of home) Additional item not on home inspection report-na grading	Family Room- General- Trim around fireplace is poorly finished at right side. Location: Family Room As per item 74 of home inspection report	Kitchen- General- Insufficient space between island and builder provided (upgraded) fridge. Less than 30" of space is present due to the fridge sticking out too far. The builder did not inform the seller of this issue with builder upgraded fridge. Item 70 of report-na	inspection report- AS PER GRADE, MEASURE
		Bury		
05Jan24 /am	05Jan24 /am	05Jan24 /am	05Jan24 /am	
A SPRING ALL TO WALL	RE-TRADE TO VAL-GREE	Done		

Done	05Jan24 /am	Main Bathroom- General- Rough finish behind shower curb stone by shower door hinges Location: Master bathroom Additional item not on inspection rep	30-Day	33
DONE	05Jan24 /am	Main Bathroom- General- Shower curb by shower door hinges painted incorrectly (not masked properly) Location: Master Bathroom Additional item not on inspection rep	30-Day	87189
		electrical conduit entrance Additional item not on inspection report		

Date Completed:	Homeowner Signature:
	has been completed in a workman like manner.
Date Completed:	Trade &/or Service Tech.
	Signature:
	Print Name:
Dispose some since of the second seco	

appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367. Please schedule your Service Department to complete work on the above Lot. Should no

applied to the Company listed above. it's group of companies) the right to carry out any and all repairs. All costs incurred will be Failure to comply with this request within 10 business days will give Zancor Homes (and



Zancor Homes (Innisfil) Ltd. Warranty Services

Fax: (905) 738-5948 Phone: (905) 738-7010

Work Order

Address: Closing Date: 1323 Stevens Road 190ct23

Innisfil

Location: Belle Aire Shores - Phase: 3 - Lot: 87W

Today's Date: Contact(s): 27Dec23

Email: Gary, Martins Dinis - Home: (416) 898-7514 - (gary.dinis18@hotmail.com) gary.dinis18@hotmail.com

Company: Zancor Construction/Labour Innisfil

Attention:

Fax: Telephone:

Please Complete the following items:

DAI	Туре	Issue	Appt. Date/Time	Notes
164561	PDI	EXTERIOR- NOTE:~REMOVE NAILS AND GARBAGE FROM ROOF. CAN SEE FROM BEDROOM.	05Jan24 /am	SPRING
164567	PDI	MASTER ENSUITE BATH- SHOWER ENC LOSURE~REMOVE BLACK MARKS ON SHOWER BASEBOARD THROUGHOUT	05Jan24 /am	DWE
164579	PDI	FOYER/HALL- STAIRS~REMOVE PAINT FROM PICKETS THROUGHOUT	05Jan24 /am	RETRADE TO P.T.
169022	30-Day	Exterior- General- Lower Front Roof - To be cleaned of construction debris and dirt as per attached supporting	05Jan24 /am	SPAIN

Print Name:	Signature:	Date Completed: Trade &/or Service Tech.	Date Completed:Homeowner Signature:The Homeowner acknowledges and accepts all work has been completed in a workman like manner.	
de experimental de servicio de la constante de	Alternatives designation of the state of the		and accepts a	

signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367. adhere to the appointment you have scheduled. Your service representative must have this form Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and


applied to the Company listed above. it's group of companies) the right to carry out any and all repairs. All costs incurred will be Failure to comply with this request within 10 business days will give Zancor Homes (and

Belle Aire Shores - Phase: 3 - Lot: 87W


164561 - 1 - NOTE:~REMOVE NAILS AND GARBAGE FROM ROOF. CAN SEE FROM BEDROOM.




164567 - 1 - SHOWER ENCLOSURE~REMOVE BLACK MARKS ON SHOWER BASEBOARD THROUGHOUT




164579 - 2 - STAIRS~REMOVE PAINT FROM PICKETS THROUGHOUT



164561 - 2 - NOTE:~REMOVE NAILS AND GARBAGE FROM ROOF, CAN SEE FROM BEDROOM.



164579 - 1 - STAIRS~REMOVE PAINT FROM PICKETS THROUGHOUT



Belle Aire Shores - Phase: 3 - Lot: 87W

166425 - 1 - 1 - trim piece at window damaged - noted at key pick up



Outstanding Deficiencies Belle Aire Shores - Phase: 3 - Lot: 87W

07Dec23 30-Day	07Dec23 30-Day	07Dec23 30-Day	20Nov23 Interval	03Nov23 Interval	03Nov23 Interval	110ct23 PDI	110ct23 PDI	110ct23 PDI	110ct23 PDI	110ct23 PDI	110ct23 PDI	110ct23 PDI	Date Reported Type
ау 3	ау 2	ay 1	13	7al 10	/al 9	36	34	33	22	16	tu tu	ω	e Number
Exterior- General- WALLS \ Masonry (brick, stone) and	Exterior- General- ROOF DRAINAGE \ Downspouts - Condition: Loose Downspout strap is not attached. Location: Left side (facing home) Garage As per item 3 on supporting Home Inspection report	Exterior- General- Lower Front Roof - To be cleaned of construction debris and dirt as per attached supporting Home Inspection report Item 2-site	Stairs- General- stain touch ups required due to Bolton repair	Exterior- General- svc to check all basement windows and clean around	Exterior- General- trim piece at window damaged - noted at key pick up	FOYER/HALL- STAIRS~FIRST TREAD CORNER DAMAGED AT STAIRS AT MAIN FLOOR TO 2ND FLOOR	FOYERHALL- STAIRS~REMOVE PAINT FROM PICKETS THROUGHOUT	FOYER/HALL- STAIRS~VARNISH REQUIRED AT RAILING AT SECOND FLOOR MARKED WITH GREEN TAPE	MASTER ENSUITE BATH- SHOWER ENCLOSURE-REMOVE BLACK MARKS ON SHOWER BASEBOARD THROUGHOUT	EXTERIOR- NOTE:REMOVE NAILS AND GARBAGE FROM ROOF. CAN SEE FROM BEDROOM.	FAMILY ROOM- FLOORING-OVERCUT AT HARWOOD PLANK AT FIREPLACE	LIVING ROOM- WINDOWS~RUBBER SEAL ON WINDOWS LOOSE	Deficiency Description
River Valley Masonry Group LTD	Promark Aluminum LTD 169023	Zancor Construction/Labour Innisfil 169022	Perfect Touch Painting 167501	Zancor - Innisfil Warranty Service 166426	Zancor - Innisfil Warranty Service 166425	Bolton Railings Inc. 164581	Zancor Construction/Labour Innisfil 164579	Perfect Touch Painting 164578	Zancor Construction/Labour Innisfil 164567	Zancor Construction/Labour Innisfil 164561	First Canadian Hardwood 164558	<u>Newmar</u> 164548	Trade Assigned
Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add Trade
05Jan24	05Jan24	05Jan24	<u>05Jan24</u>	05Jan24	<u>05Jan24</u>	05Jan24	05Jan24	05Jan24	<u>05Jan24</u>	05Jan24	05Jan24	JAN O	Add Appointment
).	**************************************	Market and the state of the sta	,	no provinces		V.	<	months and a second sec			Item Completed
The state of the s		The same of the sa					The second secon		The Child		m	To recognish and continues a	Initial

07Dec23	07Dec23	07Dec23	07Dec23	07Dec23	07Dec23	07Dec23	07Dec23	07Dec23	
30-Day	30-Day	30-Дау	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	
13	12)—i	9	00	7	6	Cs.	4	
Exterior- General- Condition: Caulking poorly applied at sill,	Exterior- General- DOORS \ Exterior trim Condition: Caulking missing, deteriorated or loose Caulking cracked/defective at top right and bottom left corner of door. Location: Front Door As per item 13 on Home Inspection report	Exterior- General- EXTERIOR GLASS/WINDOWS \ Window wells. Left side basement window is nearly at grade level without a window well present. Location: Left side (facing home) As per Item 12 on home inspection report	Exterior- General- Condition: Master bathroom window is poorly caulked at connection to sill. Location: Master Bathroom As per item 10 of the Home Inspection report	Exterior- General- Condition: Left side basement window frame is damaged Location: Left side (facing home) As per item 9 on Home Inspection report- damaged vinyl	Exterior- General- Condition: Right side Kitchen window is poorly caulked at left side vertical connection to brick veneer. Hole is present at mortar joint. Location: Kitchen As per item 8 of Home Inspection report	Exterior- General- EXTERIOR GLASS/WINDOWS \ Exterior trim Condition: Living room window seal is ripped/loose at bottom of operable window. Location: Living Room As per item 7 of Home Inspection report	Exterior- General- EXTERIOR GLASS/WINDOWS \ Condition: Window sill missing caulking at joint. Location: Bedroom 3 As per item 6 on Home Inspection report- @joint at sill	Exterior- General- Condition: At gas entrance pipe into the home, several bricks are stained with paint. Location: Left side (facing home) As per item 5 on Home Inspection report-svc to remove paint at brick at gas line	damaged (left of hose bib) at weeping hole. Location: Back of home As per item 4 on home inspection report
CJ Caulking 169034	<u>CJ Caulking</u> 169033	<u>Val-Green</u> 169032	CI Caulking 169030	Zancor - Innisfil Warranty Service 169029	CJ Caulking 169028	<u>Newmar</u> 169027	CI Caulking 169026	Zancor - Innisfil Warranty Service 169025	
Add	Add	Add	Add	Add	Add	Add	Add	Add	
05Jan24	05Jan24	<u>05Jan24</u>	05Jan24	<u>05Jan24</u>	05Jan24	05Jan24	05Jan24	05Jan24	

Exterior- General- LANDSCAPING \ General notes	Zancor Construction/Labour Innisfil 169037 Zancor Construction/Labour Innisfil 169038 Foremont Drywall 169039 RE-TRAPE Abbey Overhead Doors Inc. 169041 Abbey Overhead Doors Inc. 169042 Abbey Overhead Doors Inc. 169042	Approximate and development and development approximate and development approximate and development approximate and development approximate and development and development approximate and development approximate and development approximate and development approximate and development and development approximate and development approximate and development approximate and development approximate and development and development approximate and development approximate and development approximate and development approximate and development and development approximate and development approximate and development approximate and development approximate and development and development approximate and development approximate and development approximate and development approximate and development and development approximate and development approximate and development approximate and development approximate and development and development approximate and development approximate and development approximate and development approximate and development and development approximate and developmen	<u>07Dec23</u> 30-Day 21	07Dec23 30-Day 20	07Dec23 30-Day 19	<u>07Dec23</u> 30-Day 18	07Dec23 30-Day 17	<u>07Dec23</u> 30-Day 16		<u>07Dec23</u> 30-Day 15
		bed believes the second of the	Basement- General- Condition: Notches or holes Above basement staircase wall the I joist has been illegally drilled through the bottom chord of the structural member. The hole was drilled to run electrical wiring. Location: Basement As per item 21 on home inspection re	Garage- General- Weather strip missing on 2nd garage door (furthest garage door from Front door) Part ordered by builder subcontractor Abbey Overhead Doors, waiting delivery/installation	Garage- General- GARAGE \ Vehicle doors Condition: Inner garage door panels on both doors to be switched out to all match and be consistent as per Abbey Overhead Doors builder subcontractor (Panels have been ordered by contractor and waiting delivery/install)	Garage- General- GARAGE \ Floor Condition: Floor is stained with mortar, dirt and paint. Location: Garage As per item 19 of home inspection report	Exterior- General- LANDSCAPING \ Driveway Condition: Driveway surface to be installed (weather permitting) Location: Driveway As per item 18 on home inspection report	Exterior- General- LANDSCAPING \ General notes Condition: Final grading and sod installation to be completed (weather permitting) Location: Exterior As per item 17 of home inspection report	The second secon	Exterior- General- PORCHES, DECKS, STAIRS, PATIOS AND BALCONIES \ Floors Condition: Slab is stained with mortar and dirt and damaged in various areas. Location: Front Porch Slab As per item 16 on home inspection report
Add 05Jan24 Add 05Jan24 Add 05Jan24 Add 05Jan24 Add 05Jan24 Add 05Jan24	Add 05Jan24 Add 05Jan24 Add 05Jan24 Add 05Jan24 Add 05Jan24	A SPECIAL DEPOSITION OF THE PROPERTY OF THE PR	Zancor - Innisfil Warranty Service 169043	Abbey Overhead Doors Inc. 169042		Foremont Drywall 169039 RE-TEADE	Zancor Construction/Labour Innisfil 169038			<u>River Valley.</u> <u>Masonry Group LTD</u> 169036
05Jan24 05Jan24 05Jan24	05Jan24 05Jan24 05Jan24 05Jan24 05Jan24		Add	Add	Add Apo	Add	Add	Add		Add
			05Jan24	Arching ra	DINJMENT.	05Jan24	<u>05Jan24</u>	05Jan24		05Jan24

			Baramant Canaral Candidan	The second secon	assess success	CONTRACTOR	
07Dec23	30-Day	23	Inadequate service size Main home service is undersized 100 amps instead of 200amps as per building code: 9.34.4.1 3a Item 23 on home inspection report-NA	Zancor - Innisfil Warranty Service 169046	Add	05Jan24	
07Dec23	30-Day	24	Exterior- General- Exterior receptacle boxes to be sealed around with caulking to prevent water and insect intrusion into electrical box. Location: Exterior As per item 25 of home inspection report-WE DO NOT CAULK THERE	Zonova I – fil	Add	05Jan24	
07Dec23	30-Day	26	Exterior- General- Condition: Exterior lights to be sealed around with caulking to prevent water and insect intrusion into electrical box. Location: Exterior As per item 28 on home inspection report-NA	Zancor Towns 51 Von 159049 CS	Add	05Jan24	
07Dec23	30-Day	دري	Family Room- General-Condition: Fireplace surround is damaged and painted in various areas. Location: Family Room As per item 34 of home inspection report-REMOVE PAINT AT FIREPLACE	Zancor - Innisfil Warranty, Service 169056	USSEL Add	OSJan24 PIREPLACE	
07Dec23	30-Day	32	Master Bedroom- General-ATTIC/ROOF \ Hatch/Door Condition: Not insulated Attic hatch insulated is not attached to the attic hatch.	169058 169058	Add	05Jan24	
07Dec23	30-Day	<i>ω</i>	Master Bedroom- General- Attic hatch is poorly painted. Location: Attic As per item 36 of home inspection report	Zancor - Innisfil Warranty Service 169059	A	05Jan24	
07Dec23	30-Day	34	Basement- General- Condition: Sump pump cover missing grommet for electrical cable. Location: Basement As per item 37 of home inspection report	Toronto Concrete & Drain 169060	Add	05Jan24	
07Dec23	30-Day	35	Main Bathroom- General-Condition: Severe lippage at rear left corner of bathtub tiles. Location: Second Floor Hallway Bathroom As per item 38 of home inspection report-MEASURE	AV Classic 169061		05Jan24	
07Dec23	30-Day	36	Main Bathroom- General-Condition: Gaps are present at threshold pieces throughout the master bathroom shower. Location: Master Bathroom As per item 39 of home inspection repo-CAULK JAMB	Zancor - Innisfil Warranty Service 169062	A dd	05Jan24	
571Jec223	J/Dec23 30-Day 37 Mail pool floo floo floo than water water water for the floor water for the floor fl	37	Main Bathroom- General-Tiles poorly cut around the shower floor drain. Additionally the floor drain is installed higher than the tiles which will cause water pooling. Location: Master	AV Classic 169063	Add	05Jan24	

	<u>07Dec23</u> 30-Day	07Dec23 30-Day	07Dec23 30-Day	07Dec23 30-Day	07Dec23 30-Day	07Dec23 30-Day	07Dec23 30-Day	07Dec23 30-Day	07Dec23 30-Day	<u>07Dec23</u> 30-Day
	54	ن نيا	49	45	43	42	-Da Journell	A	39	33
All the second sections of the second	Bedroom 2- General- Condition: Poor finish on closet doorway jamb. Rough/orange peel texture. Location: Master Bedroom Closet As per item 59 of home inspection report	Bedroom 2- General- Condition: Damage Door is minorly damaged or require minor paint touch ups: Master bedroom operable door Foyer linen closet Location: Master bedroom operable door, Foyer linen closet	Bedroom 2- General- Right side operable window is warped. Location: Bedroom 3 As per item 54 of home inspection	Family Room- General- Hardwood floor is overcut at fireplace Location: Family Room As per item 50 on home inspection report	Master Ensuite- General- Ceiling poorly finished above master bathroom shower top threshold piece. Location: Master Bathroom As per item 47 of home inspection report-	Tray celling has visible (evening time) drywall joints. Location: Master Bedroom As per item 46 of home inspection report	Other- General- Condition: Localized paint defects on walls, ceilings, and trim marked with green tape and/or yellow filler Location: Throughout As per item 45 of home inspection report	Stairs- General- Shelving is poorly installed at rear of closet, fasteners are sunken into the drywall. Location: Staircase landing Closet As per item 44 of home inspection report	Main Bathroom- General- Master bathroom doorstop incorrectly installed behind the bathtub. Location: Master Bathroom As per item 42 of home inspection report-NA	Bottom course of tiles in shower are stained with mortar. Location: Master Bathroom As per item 41 of home inspection report-GROUT
ecteroteteenes inprovenesentapolegosa teagrings.	Zancor - Innisfil Warranty Service 169089	Zancor - Innisfil Warranty Service 169087	<u>Newmar</u> 169080	First Canadian Hardwood 169075	Zancor - Innisfil Warranty Service 169071	Foremont Drywall 169070	Zancor - Innisfil Warranty Service 169068	WYECROFT TRIM 169067	Zancor - Innisfil Warranty Service 169065	AV Classic 169064
	Add	Àda	Add	Add	Add	Add	Add	Add	Add	Add
	05Jan24	05Jan24	05Jan24 JAN 1014	05Jan24	<u>05Jan24</u>	05Jan24	05Jan24	05Jan24	05Jan24	05Jan24
- Additional adversariation and adversariation of		*	1 2				<	<		
discourse eterotechemistrations and	m	Re		200	m	ordina na composición qualita qua acquada que acquada	Se .	m	m	an

07Dec23 30-Day	07Dec23 30-Day	07Dec23 30-Day	<u>07Dec23</u> 30-Day	07Dec23 30-Day	07Dec23 30-Day	<u>07Dec23</u> 30-Day	07Dec23 30-Day	07Dec23 30-Day	<u>07Dec23</u> 30-Day
69	65	64	63	62	61	60	59	<i>S</i> ₅	56
Family Room- General- Trim around fireplace is poorly finished at right side. Location: Family Room As per item 74 of home inspection report	Kitchen- General- Insufficient space between island and builder provided (upgraded) fridge. Less than 30" of space is present due to the fridge sticking out too far. The builder did not inform the seller of this issue with builder upgraded fridge. Item 70 of report-na	Kitchen- General- Top cabinet left of range hood left side door is damaged at left side. As per item 69 of home inspection report	Kitchen- General- Top cabinet left of fridge is minorly chipped on door and damaged at bottom panel. As per item 68 of home inspection report	Kitchen- General- Kitchen island (backside) has chip out along the bottom panel of the rear cabinet. As per item 67 of home inspection report - @BOTTOM GABLE	Kitchen- General- Island kick plate has leftover nail holes (backyard side) As per item 66 of home inspection report	Kitchen- General- Kitchen Island (stove side rear corner) panel is poorly finished. As per item 65 of home inspection report-REMOVE PLASTER INSIDE GABLE AT FLOORLINE	Main Bathroom- General-Cabinet doors x2 at left side sink are damaged/scratched in at least 4 areas. Location: Master Bathroom As per item 64 of home inspection report	Kitchen- General- Cabinet doors and/or drawers require to be adjusted so that all doors operate properly. In addition, further adjustments are desirable to achieve consistent spaces between the cupboard door fronts and drawers. As per item 63 of home inspection report	Garage- General- Condition: Threshold is poorly supported leaving half it floating in the air. Location: Garage Man Door As per item 61 of home inspection report- AS PER GRADE, MEASURE
Zancor - Innisfil Warranty Service 169109	Zancor - Innisfil Warranty Service 169105	New Image Kitchens 169104	New Image Kitchens 169103	New Image Kitchens 169102	New Image Kitchens 169101	New Image Kitchens 169100	New Image Kitchens 169099	New Image Kitchens 169098	Zancor - Innisfil Warranty Service 169094
Add	Add	Add	Add	Add	Add	Add	Add	Add	Add
05Jan24	05Jan24	05Jan24	05Jan24	05Jan24	05Jan24	05Jan24	<u>05Jan24</u>	05Jan24	05Jan24
<	a contraction of the contraction		<		*	<	<		<
d		Sup	the state of the s	M	m	m	me	m	m

HET SPERE BET BET BET BANK AND THE	And the second s	-	stance - was experienced and other control of the c	discount announce for the Company of)	:-//hetanne e
	05Jan24	Add	Bolton Railings Inc.	Stairs- General- Rough finish on handralling edge Location: Staircase to second floor As per item 84 of home inspection report- inspect edge at handrails	79	30-Day	17Dec23
	05Jan24	Add	Bolton Railings Inc. 169118	Manager 1997 - Common and a	78	30-Day)7Dec23
	05Jan24	Add	WYECROFT TRIM 169117	Stairs- General- Incorrect shoe moulding used at bottom stringer than connections to quarter round. Trim type is not consistent. Location: 2 Step staircase As per item 82 of home inspection report-shoe mold used in lieu of trim	77	30-Дау)7Dec23
	05Jan24	Add	Perfect Touch Painting 169116	Stairs- General- Shoc moulding is unfinished (no stain or varnish) Top landing First riser Location: Staircase to second floor As per item 81 of home inspection report	76	30-Day)7Dec23
	05Jan24	Add	Perfect Touch Painting 169115	Stairs- General- At top landing, newel post, tread and riser are unfinished (wood glue and sanding marks present) Location: Staircase to second floor As per item 80 of home inspection report-stain	75	30-Day	37Dec23
	05Jan24	Add	Perfect Touch Painting 169114	Stairs- General- Staircase risers at open end have left over wood glue on them or are opening up. Location: Staircase to second floor As per item 79 of home inspection report-stain required	74	30-Day	07Dec23
	05Jan24	Add	WYECROFT TRIM 169113	Stairs-General- First riser down from 2nd floor at open end, shoe moulding trim is poorly installed to newel post leaving a gap Location: Staircase to second floor As per item 78 of home inspection report	73	30-Day	07Dec23
	05Jan24	Add	Perfect Touch Painting 169112	Stairs- General- Newel post at top landing is unfinished at top (wood glue and sanding marks present) Location: Staircase to second floor As per item 77 of home inspection report	72	30-Day	07Dec23
	05Jan24	Add	Perfect Touch Painting 169111	Stairs- General- At top bull nosing, riser and newel post, excess wood glue is left over (incomplete) Location: Staircase to second floor As per item 76 of home inspection report-stain required	71	30-Day	07Dec23
	05Jan24	Add	Perfect Touch Painting 169110	Stairs- General- Shoe moulding at bottom riser is not painted (primed only) Location: 2 step Stair case As per item 75 of home inspection report	70	30-Day	07Dec23

home needs to be set closer to the foundation of home, tripping hazard currently Location: Left side of home near electrical conduit entrance Additional irem not on inspection report Stairs- General- Inconsistent trim picce at stairs on main floor going to 2nd floor Location: WYECROFTTRIM Main floor staircase Additional item not on inspection report Kitchen- General- Handle on 2nd drawer is scratched, previously had paint on it (Noted on PDI) and contractor trying to remove paint ended up scratching it instead Location: Kitchen Additional item not on inspection report Main Bathroom- General-Shower curb by shower door hinges painted incorrectly (not masked properly) Location: Main Bathroom Additional item not on inspection report Master Bathroom Additional item not on inspection report Main Bathroom Additional item not on inspection report Materially Service Additional item not on inspection report Material Serv	90)7Dec23 30-Day
home needs to be set closer to the foundation of home, tripping hazard currently Location: Left side of home near electrical conduit entrance Additional item not on inspection report Stairs- General- Inconsistent trim piece at stairs on main floor going to 2nd floor Location: Main floor staircase Additional item not on inspection report Kitchen- General- Handle on 2nd drawer is scratched, previously had paint on it (Noted on PDI) and contractor trying to remove paint ended up scratching it instead Location: Kitchen Additional item not on inspection report New Image Kitchens Additional item not on inspection report	89)7 <u>Dec23</u> 30-Day
home needs to be set closer to the foundation of home, tripping hazard currently Location: Left side of home near electrical conduit entrance Additional item not on inspection report Stairs- General- Inconsistent trim piece at stairs on main floor going to 2nd floor Location: Main floor staircase Additional item not on inspection report WYECROFT TRIM Add item not on inspection report	∞ ∞	07Dec23 30-Day
home needs to be set closer to the foundation of home, tripping hazard currently Location: Left side of home near electrical conduit entrance Additional item not on inspection report	87	07Dec23 30-Day
Exterior- General- Grounding conduit by electrical entrance to	86	07Dec23 30-Day
Exterior- General- Window wells in backyard are not centered with windows, additionally they are not level either (slanted or much higher than other wells) Location: Backyard (Facing back of home) Additional item not on home inspection report-na grading	85	07Dec23 30-Day
CI Caulking 169124 Add		07Dec23 30-
Dining Room- General- Dining room window screen is defective, threads starting to unravel in the middle Location: Dining room Additional item not on home inspection report Dining room Additional item not on home inspection report Dining Room- General- Dining room Additional item not on home inspection report Newmar 169123 Add 05Jan24 TAN 10		07Dec23 30.
Main Bathroom- General- Trim above stairs from entrance of family room is unfinished, and surrounding drywall needs to be painted Location: Entrance of family room looking up to stairs Additional item not on inspection report Main Bathroom- General- Trim Perfect Touch Painting Add 05Jan24	30-Day 82	<u>07Dec23</u> 30
Stairs- General- Spindles are stained with staircase stain or white paint drips/overspray throughout. Location: Staircase to second floor As per item 85 of home inspection report	30-Day 80	<u>07Dec23</u> 30

			Sibiliplicity of Control of the Particular P	DITTION	Carmanan	
		by shower door hinges Location: Master bathroom Additional item not on inspection rem	169130			121
		Master Ensuite- General- secure				
Interval	14	mirror, moves when being touched	Central Glass 170097	Add	NoAppoint	ah
Interval	15	Stairs- General- replace hardwood plank at newel post - homeowner not accepting repair	First Canadian Hardwood	Add	NoAppoint	dub
		U/S since pdi	\$600/1			etholocione (even un discrepagne spain pér

27Dec23

27Dec23

The		
Homeowner	Homeowner Signature	
acknowladge	Signature:	
1		
Homeowner acknowledges and	A second results	

initialled work has been completed in a workman like manner to their satisfaction.

Zancor Service Technician: