ZANCOR

Quality Control-WEB



Vendor / Builder # Enrollment #

Purchaser Name: Rajiv Khaira Legal Address: 19 Camino Real Drive

Phone Res: Zancor Homes (Caledon) Ltd.

Phone Bus: 6476253879 **Plan #:**

Inspector: Gisella Fiore Municiaplity:

Inspection Date: Date undefined, undefined

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- Bathtub sinks and toilets
- · Bathroom accessories if provided
- · Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- · Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors including garage overhead doors, door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- · Gas fireplaces, incl.circulation fans, if provided
- · Heat Recovery Ventilation system, if provided
- Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

EXTERIOR

NOTE:

Deficiency:

DAMAGE DOWNSPOUT LEFT SIDE OF GARAGE

Pictures



FOYER/HALL

STAIRS

Deficiency:

CRACKED TREAD AT RAILING BELOW NOSING AT MAIN FLOOR STAIRS LEFT OF KITCHEN STAIRS TO 1ST FLOOR

Pictures:



Deficiency:

SCRATCH ON RAILING LEFT OF NEWEL AT MAIN FLOOR

Pictures:



NOTE:

Deficiency:

ADJUST MAN DOOR NOT CLOSING PROPERLY

Deficiency:

MISSING STAIN AT SHORT RAILING AT KITCHEN

Pictures:



Deficiency:

DENTON OUTSIDE STRINGER AT STAIRS FROM MAIN TOO 1ST RIGHT OF POST. AND POST RIGHT OF STRINGER AT STAIRS TOO 3RD

Pictures:





Pictures:

No Pictures for this deficiency

MASTER ENSUITE BATH

FAUCETS/PLUMBING

Deficiency:

RE/RE CAULKING INSIDE SHOWER AT TOP



MASTER BEDROOM

FLOORING

Deficiency:

ADJUST CARPET SHIM AT ENTRANCE TO BATH AND TUCK CARPET IN MIDDLE

Pictures:





WINDOWS

Deficiency:

SCREEN DOOR MISSING AT DOOR.

Pictures:



UPPER HALL NOTE: **Deficiency:**UNABLE TO LOCATE CENTRAL VAC ROUGH IN Pictures: No Pictures for this deficiency **KITCHEN** WINDOWS **Deficiency:**MISSING SCREEN DOOR AT SLIDING DOOR. Pictures: **CABINETS** Deficiency: INSPECT BOTTOM LEFT CABINET AT EDGE PEELING Pictures: NOTE: **Deficiency:**REMOVE STAIN FROM ISLAND ABOVE GARBAGE DRAWER AT EDGE AND TOP. Pictures: **POWDER ROOM** NOTE: **Deficiency:**SECURE PLUMBING PIPE BELOW SINK MOVING Pictures:

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.

to the vendoribulater authorizing the designate to sign this form on their behalf.	
HA.	
Builder Representative	Purchaser
Designate's Name(please print)	Designate's Signature
I the homeowner, confirm that all repair work listed will be completed	
File .	
Purchaser	Date