Outstanding Deficiencies Caledon Club - Phase: 1B - Lot: 158B

Ren D	<u>Date</u> Reported	Туре	Number	Deficiency Description	Trade Assigned	Add	Appointment Date	Item Completed	Initial
09.		CONCILIATION	Ros 6	Exterior- General- The front entrance door paint must be finished from the interior and exterior at exterior around trim)	Perfect Touch - CALEDON 177579	Add	13Aug24	ļ	
09.	09Jul24	7	120K	Exterior- General- The front exterior doors are not aligned. Front door is not in center of the front wall	Zancor - Caledon 177581	Add	13Aug24		
160	09Jul24	CONCILIATION	∞	Exterior- General- The garage door trim is unfinished (SVC PATCH LEFT SIDE AND RE PAINT)	Zancor - Caledon 177582	Add	13Aug24		
09.1	09Jul24	CONCILIATION	11	Exterior- General- Exterior Brick/Mansory work is uneven near the foundation	River Valley Masonry Group LTD 177585	Add	13Aug24		
09J1	<u>09Jul24</u>	CONCILIATION ROUMEN	16	Foyer- General- A bulge is visible in the Hallway wall(SVC MEASURE TOLERANCE)	Zancor - Caledon 177590	Add	13Aug24		
09J1	<u>09Jul24</u>	CONCILIATION	17	Foyer- General- main doors- not aligned properly, dents and paint issues (PAINT COMPLETE) ALIGNMENT NOT	Zancor - Caledon 177591	Add	13Aug24	<	
<u>1760</u>	09Jul24	CONCILIATION	22	Foyer- General- Nail popping is visible in many places around the house.	Foremont Drywall 177596	Add	13Aug24	1	
09Jul24		CONCILIATION	24	Stairs- General- Poor paint finishing is observed around the Staircase trim.	Zancor - Caledon 177598	Add	13Aug24	<	
0911	<u>09Jul24</u>	CONCILIATION	25	Stairs- General- Unfinished spots are visible on the staircase and around the balusters	Perfect Touch - CALEDON 177599	Add	13Aug24		
<u>09Jı</u>	124	09Jul24 CONCILIATION	26	Bedroom 3- General- The third- bedroom and second-bedroom washroom showers are poorly caulked(SVC TO CAULK AT FACUET AND WALL)	Zancor - Caledon 177602	Add	13Ацд24		
0000		CONCILIATION	35	Attic- General- Stains are visible on the roof trusses in the Attic	Kingsview Carpentry 177637	Add	13Aug24		
0000		CONCILIATION	36	Attic- General- Less insulation is visible around the corner of the Attic- COMPLETE SIGNED	Foremont Drywall 177638	Add	13Aug24		
0000		CONCILIATION	42	Foyer- General- Main door is not centred in wall, left side wall to door trim distance is 11 cms where as right side wall to trim distance is 7 cms	Zancor - Caledon 177644	Add	13Aug24		
0000		CONCILIATION	43	Living Room- General- Hard wood floor is uneven and bumped up at joints at various places in living room area near patio door and window.	Zancor - Caledon 177645	Add	13Aug24		

18									
09Aug24	0000	0000	0000	0000	0000	0000	0000	0000	0000
Interval	CONCILIATION	CONCILIATION	CONCILIATION	CONCILIATION	CONCILIATION	CONCILIATION	CONCILIATION	CONCILIATION	CONCILIATION
7	55	54	S	52	51	49	46	4.5	44
Shared Bathroom- Generaldrywall skim / repair and paint	Master Bedroom- General- carpet in walk in closet was very dirty and with mud and dirt boot foot print behind the door of walk in closet in master bedroom at the time of PDI and promised to replace it with new carpet in walk in closet area but not done yet	Exterior- General- Over all many cosmetic as well as functional defects found which is very obvious and visible even layman can identify but builder is not able to correct before PDI and before closing date - very poor quality of work found. looks like rushed work.	Exterior- General- t Source Furnace system details, model number and warranty registration details not provide as well as Honeywell thermostats user manual and original packaging, warranty registration, model number etc. not provided	Exterior- General- grading, sodding, and cleaning is not done on any of the exterior items, garage doors walls, bricks, paint, soffits etc. lots of mud on porch floor, steps and drive way not completed bricks are un even and not in parity with foundation wall	Exterior- General-) grading, sodding, and cleaning is not done on any of the exterior items, garage doors walls, bricks, paint, soffits etc. lots of mud on porch floor, steps and drive way not completed	Exterior- General- grading, sodding, and cleaning is not done on any of the exterior items, garage doors walls, bricks, paint, soffits etc. lots of mud on porch floor, steps and drive way not completed	Living Room- General- Sub floor squeaking observed near window and bumped up flooring in living room area	Dining Room- General- hard wood floor is uneven and bumped up in dining room area at multiple places	Dining Room- General- 51, Hard wood floor is uneven and bumped up at joints at various places in living room area near patio door and window
Zancor - Caledon 178213	Quality Rugs Canada LTD. 177657	Zancor <u>-</u> Caledon 177656	<u>Zancor -</u> <u>Caledon</u> 177655	Zancor - Caledon 177654	Zancor - Caledon 177653	Zancor - Caledon 177651	Zancor - Caledon 177648	Zancor - Caledon 177647	Zancor - Caledon 177646
Add	Add	Add	Add	Add	Add	Add	Add	Add	Add
13Aug24	13Aug24	13Aug24	<u>13Aug24</u>	<u>13Aug24</u>	13Aug24	13Aug24	13Aug24	13Aug24	13Aug24
<							_		