Enrollment:

Purchaser Name: Katrina Ruttan-Grainger

Philip Grainger

Phone Res:

Phone Bus: (705) 539-0222 **Closing Date:** January 29, 2025

Inspector: Gisella Fiore

ZANCOR HOMES PDI Vendor / Builder:

Project: Zancor Homes (Wasaga River) Ltd

Lot / Phase: 260 / 1

Plan:

Address: 167 Rosanne Circle

Municiaplity:

Inspection Date: December 19, 2024

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

Page 1 of 3

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- · Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- · Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- · Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- · Faucets: Kitchen, bathroom, laundry room
- · Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- · Gas fireplaces, incl.circulation fans, if provided
- · Heat Recovery Ventilation system, if provided
- Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

MASTER ENSUITE BAT	Н	
NOTE:	ADJUST SHOWER GLASS DOOR.	
UPPER HALL		
NOTE:	AS PER HOMEOWNER REQUESTING TO HAVE ALL POT LIGHT WARM RATHER	
	THEN BRIGHT LED	
BEDROOM 2 ENSUITE		
NOTE:	SCRATCH INSIDE BOTTOM LEFT AND FACE CABINET AND FACE OF BOTTOM RIGHT CABINET BELOW SINK.	
	DAMAGED GABLE LEFT SIDE OF SINK AT TOLIET PAPER HOLIDER.	
EXTERIOR		
NOTE:	REMOVE NAILS AT FLAT ROOF.	
	ADJUST LEFT GARAGE DOOR LIGHT COMING THROUGH.	
-	BRUSH COAT LEFT OF FRONT PORCH, MESSY	
	POWER WASH REQUIRED MOTOR AT BRICK AND WINDOWS BASEMENT HAVE MOTAR	
	H.O REQUEST HIM TO HAVE MOTOR REMOVED FROM WINDOWS BELOW AGT TRIM AT ALL SILLS THROUGHOUT.SEE PHOTO FOR REFERENCE	
	DRILL HOLES IN MOTOR LEFT OF REAR WINDOW LEFT OF SLIDING DOOR	
	INSPECT BRICK RED THROUGH OUT HOME BELOW SILLS TO BE CONFIRMED	
	AS RED BRICK AS BE INSTALLED AND DOES NOT MATCH OTHER BRICK I	
	INSPECTOR ALUMINUM RIGHT OF PORCH IN BETWEEN WINDOWS AT SEAM DENTED/BOWED	
BEDROOM 3 ENSUITE		
VANITY CABINETS	SCRATCH AT KICK BELOW SINK / BOTTOM LEFT CABINET AND RIGHT GABLE AT	
	TOLIET PAPER.	
BEDROOM 4 ENSUITE		
VANITY CABINETS	SCRATCHES ON X4 CABINET BELOW SINK	

Enrollment:

Purchaser Name: Katrina Ruttan-Grainger

Philip Grainger

Phone Res:

Phone Bus: (705) 539-0222 **Closing Date:** January 29, 2025

Inspector: Gisella Fiore



Page 2 of 3

Vendor / Builder:

Project: Zancor Homes (Wasaga River) Ltd.

Lot / Phase: 260 / 1

Plan:

Address: 167 Rosanne Circle

Municiaplity:

Inspection Date: December 19, 2024

FOYER/HALL		
STAIRS	STAIN REQUIRED AT SHORT FLIGHT OF STAIRS LEFT SIDE AT MAIN TO LANDING TO 2ND FLOOR. FACING DINNING X5.	
	CRACK ON 5TH TREAD AT STAIRS FROM MAIN TO 2ND FLOOR	
	DAMAGED TRIM LEFT OF RISER FACING DINING REMOVE BELOW NOSING	
	DAMAGED AT 3RD TREAD AT STAIRS FROM MAIN TO LANDING TO 2ND FLOOR	
FLOORING	INSPECT 4TH PLANK LEFT OF STAIRS RAISED.	
NOTE:	HOMEOWNER UNHAPPY WITH STAYING AT SHORT FLIGHT OF STAIRS	
	BLOTCHY/ PAINT BRUSHES VISABLE- SAND AND RE STAIN.	
DINING ROOM		
FLOORING	X2 SCRATCH PLANK BELOW ARCHWAY AT ENTRANCE TO LIVING 4TH PLANK	
	FROM OUTSIDE STRINGER AND 7TH PLANK CHIPPED AT EDGE/RAISED	
	SERVICE TO CONDUCT STRING TEST BELOW ARCHWOOD ENTRANCE OF	
	LIVING ROOM HUMP	
KITCHEN		
CABINETS	REPAIR AT GARBAGE DRAWER TOUCHED UP CAN SEE WHERE REPAIR	
	COMPLETED AND AT GABLE LEFT SIDE FACING SINK	
	SCRATCH ON BOTTOM RIGHT CABINET RIGHT OF FRIDGE	
	ADJUST UPPER CABINET ABOVE HOODFAN.	
	DENT ON RIGHT GABLE RIGHT OF SINK	
	DENT ON UPPER LEFT CABINET LEFT OF HOODFAN AND TRIM AT GABLE TO BE SECURED X2 1) LEFT OF HOODFAN 1 RIGHT OF FRIDGE	
	HOMEOWNER REQUESTING TO HAVE DRAWERS INSPECTED RIGHT OF STOVED FOR WHITE FILM AT EDGES. 2) CHIP AT FIRST DRAWER RIGHT OF STOVE.	
	BOTTOM RIGHT CABINET RIGHT OF BANK OF DRAWER SCRATCHED AND BELOW SINK RIGHT DOOR.	
	SCRATCH AT BOTTOM LEFT CORNER FILLER LEFT OF SINK 2) SCRATCH AT BOTTOM RIGHT CABINET LEFT OF STOVE.	
	X2 CABINET BELOW SINK AT BASE NOT STAINED.	
BASEMENT		
NOTE:	BASEMENT WINDOW SCREENS NOT INSTALLED	

Enrollment:

Purchaser Name: Katrina Ruttan-Grainger

Philip Grainger

Phone Res:

Phone Bus: (705) 539-0222

Closing Date: January 29, 2025
Inspector: Gisella Fiore



Vendor / Builder:

Project: Zancor Homes (Wasaga River) Ltd.

Lot / Phase: 260 / 1

Plan:

Address: 167 Rosanne Circle

Municiaplity:

Inspection Date: December 19, 2024

Page 3 of 3

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

Katrina Ruttan-Grainger Philip Grainger

Purchaser's Name (print) Purchaser's Signature Purchaser's Name (print) Purchaser's Signature

Gisella Fiore

Designate's Name (print)

Designate's Signature

Inspector's Name (print)

Inspector's Signature

Date (YYYY/MM/DD) 2024/12/19 December 19, 2024