Raul & Cathy - June 11-2010
Time - 5 25 PM
We went to check # 2507
Vibration & noisy we found it
Before reach position H
when she is taking shower.

AMACON DEVELOPMENT

AMACON SERVICE REQUEST FORM

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5J 2G1

TEL: 416-368-3028 FAX: 416-365-0000 905-232-4637 (Former AMECON) CUSTOMER CARE
(905)882-4636

ATTENTION CUSTOMER CARE: 3515 KANIVA DR.

TEL: 905-848-2008 FAX: 905-848-2027

NAME: Annetta BAKSA SUITE #: 2507

DEVELOPMENT NAME: _____ ADDRESS: _____

RES.TEL: _____ BUS.TEL: _____ CELL: 647-400-1294

FAX: _____ EMAIL: _____

DATE OF REQUEST: _____

EVE

SERVICE REQUEST:

1. 1st washroom: Shower
2. is rattling when is
3. above H position in
4. the tap put on shower
5. and check.
6. Not SAVE CON
7. USE
8. same as Unit 2208
9. inspected June 14 — will monitor,
10. after dist repairs the problem.

Authorise suite entry