

AMACON

LIVE WELL

**Warranty Services
Work Order**

Phone: (905) 848-2069 Fax: (905) 848-2827

Location	Eve - Tower: 1 - Unit: 2806
Closing Date	2806 - 3515 Kariya
Date	0000
Contact Name(s)	05Feb09
Contact Telephone#	Adam Kowalik and Jolanta Kowalik
Company:	Amacon Service
Attention:	Carlos Bravo
Telephone:	
Fax:	(905) 848-2827
From:	Warranty Services Department - Head Office

Please complete the following items:		Appointment Date/Time	Notes
8722	FOYER / ENTRY- WALLS-DRYWALL DENTED left wall where taped	✓	
8723	FOYER / ENTRY- WALLS: 1-chip in baseboard by closet where taped	✓	
8724	FOYER / ENTRY- DOORS-reseal and repaint right side of entry door, see tape	✓	
8726	LIVING/DINING ROOM- WALLS-drywall seams showing, see tape	✓	
8728	LIVING/DINING ROOM- WALLS: 1-drywall, left wall not secure, moves when pushed	✓	
8730	LIVING/DINING ROOM- WALLS: 2-DRYWALL DENTED to left of master bedroom, see tape	✓	
8731	LIVING/DINING ROOM- WALLS: 3-DRYWALL DENTED to left of window, see tape	✓	
8732	LIVING/DINING ROOM- WALLS: 4-DRYWALL REPAIR WHERE NOTED to right of thermostat, see tape	✓	
8733	LIVING/DINING ROOM- WALLS: 5-customer requests left wall be repainted	✓	
8734	GUEST BEDROOM 1- WALLS-marks on walls, see tape	✓	
8735	GUEST BEDROOM 1- WALLS: 1-chips in baseBOARD, see tape	✓	
8736	GUEST BEDROOM 1- WALLS: 2-excessive gap along door, see tape	✓	
8737	GUEST BEDROOM 1- DOORS-chip on front of door, see tape	✓	
8738	GUEST BEDROOM 1- DOORS: 1-gap upper left interior corner of door frame, see tape	✓	
8739	GUEST BEDROOM 1- CLOSET-excessive gap upper corner of casing, see tape	✓	
8740	GUEST BEDROOM 1- WINDOWS-reseal j-mold upper top right window, see tape	✓	
8741	MASTER BEDROOM- WALLS-marks in drywall, see tape	✓	
8742	MASTER BEDROOM- WALLS: 1-gaps at corners of baseboard, see tape	✓	
8743	MASTER BEDROOM- WALLS: 2-uneven paint along top left window, see tape	✓	
8744	MASTER BEDROOM- WALLS: 3-small wall to right of balcony, paint patchy, see tape	✓	
8745	MASTER BEDROOM- DOORS-gap inside door frame, see tape	✓	
8746	MASTER BEDROOM- CEILING-AIR HOLES along wall above firealarm silencer	✓	
8749	MASTER BEDROOM- CLOSET-excessive gap outside door frame, see tape	✓	
8750	MASTER BEDROOM- WINDOWS- ALUMINUM marked lower left side of balcony door	✓	
8751	MAIN BATHROOM- ELECTRICAL/LIGHTING-BULBS BURNED OUT	✓	
8752	ENSUITE BATHROOM- WALLS-drywall scratched below light switch, see tape	✓	
8753	ENSUITE BATHROOM- WALLS: 1-marks on drywall above mirror, see tape	✓	
8754	ENSUITE BATHROOM- WALLS: 2-marks on drywall by towel holder, see tape	✓	
8755	ENSUITE BATHROOM- WALLS: 3-gap by tub tile, 3rd tile above tub, see tape	✓	
8756	ENSUITE BATHROOM- WALLS: 4-marks and hole in drywall to left of vanity, see tape	✓	
8757	ENSUITE BATHROOM- DOORS-excessive gap in door frame, see tape	✓	
8758	ENSUITE BATHROOM- DOORS: 1-lock does not work	✓	NO EXTEN HANDLES
8759	ENSUITE BATHROOM- ELECTRICAL/LIGHTING-BULBS BURNED OUT	✓	
8764	KITCHEN- CABINETS: 4-excessive gap under granite countertop	✓	
8765	KITCHEN- WALLS-mark o drywall by telephone jack, see tape	✓	
8766	KITCHEN- WALLS: 1-bulkhead for microwave not painted and screws showing, see tape	✓	

Date Completed: Feb 6, 09

Amacon Customer Care Signature: 

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Back - Forms
Menu
 ID#
 8722/8723/8724/8726/8728/8730/8731/8732/8733/8734/8735/8736/8737/8738/8739/8740/8741/8742/8743/8744/8745/8746/8749/8750/8751/8752/8753/8754/8755/8756/8757/8758/8759/8764/8765/8766
 Eve Ph 1 Lot 2806