

RECEIVED

AUG 24 2010

AMACON DEVELOPMENT

AMACON SERVICE REQUEST FORM

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5J3B1

TEL:416-369-9069 FAX: 416-369-9068

ATTENTION CUSTOMER CARE: 3515 KARIYA DR.

TEL:905-848-2069 FAX: 905-848-2827

NAME: Beater SUITE # 1208

DEVELOPMENT NAME: _____ ADDRESS: _____

RES.TEL: 416 886 5929 BUS.TEL: _____ CELL: _____

FAX: _____ EMAIL: _____

DATE OF REQUEST: _____

SERVICE REQUEST:

1. Floor has expanded and created
2. air pocket right by washroom
3. door
4. Please inspect immediately
5. Access allowed
6. _____
7. _____
8. _____
9. _____
10. _____

*exc 1208
Ed requested / Beater
Report from Ryan
W/Photo to ABC*

RECEIVED

AUG 23 2010

AMACON DEVELOPMENT

AMACON SERVICE REQUEST FORM

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5J3B1

TEL: 416-369-9069 FAX: 416-369-9068

ATTENTION CUSTOMER CARE: 3515 KARIYA DR.

TEL: 905-848-2069 FAX: 905-848-2827

NAME: Mehar Gihani SUITE # 1202DEVELOPMENT NAME: _____ ADDRESS: 3515 Kariya DrRES. TEL: 9052321289 BUS. TEL: _____ CELL: _____

FAX: _____ EMAIL: _____

DATE OF REQUEST: 22nd Aug 2010

SERVICE REQUEST:

1. Flush, leakage of water
2. Blockage of water at sink
3. _____
4. _____
5. _____
6. Access authorized in my absence.
7. Mehar Gihani
8. _____
9. _____
10. _____

UPLOADED TO MMS
602-1205