

Thursday July 1, 2009.

Dear PROPERTY MANAGEMENT:

I am the owner of suite 1510 & I would like to report that there is flooding in my unit. The plastic area of concern is the corner area of my wall in closet. The water seems to be coming from the floor & has soaked the carpet. I would appreciate it if this situation could be looked at & fixed as soon as possible.

Also the ~~the~~ drain in the bath tub seems to be blocked & the water drains slowly. If this could also be looked at.

As the owner of this unit, this is my first week in my new home & I would like to have these issues rectified.

Many Thanks
Susan Miller

9-781-4305

AMACON DEVELOPMENT

AMACON SERVICE REQUEST FORM

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5J3B1

TEL: 416-369-9069 FAX: 416-369-9068
OR (905) 882-4686

ATTENTION CUSTOMER CARE: 3515 KARIYA DR.

TEL: 905-848-2069 FAX: 905-848-2827

NAME: SUSAN HECERA

SUITE # 1510

DEVELOPMENT NAME: CVE

ADDRESS: 3515 KARIYA DR.

RES. TEL:

BUS. TEL:

9-1615-3300

CELL:

9-781-4305

FAX:

EMAIL:

DATE OF REQUEST:

July 1, 2009

SERVICE REQUEST:

1. leaking in Unit in Closet due July 3/2009
2. Blocked Drain in Bath TUB. due July 3/2009
3. _____
4. _____
5. Blocked Drain
6. _____
7. _____
8. _____
9. _____
10. _____

Suite Entry Permission: Need