

Revi,

- 1) pasteur a leade from the w/d reported in this unit
- 2) if no leade reported, I will

make an appointment for
customer service / Barwood to
investigate the floor

4/0
82/24/2011

AMACON DEVELOPMENT

AMACON SERVICE REQUEST FORM

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5J3B1

TEL: 416-369-9069 FAX: 416-369-9068

ATTENTION CUSTOMER CARE: 3515 KARIYA DR.

TEL: 905-848-2069 FAX: 905-848-2827
(905) 282-4636 (416) 369-9068

NAME: KARAN KHURANA

SUITE # 901

DEVELOPMENT NAME: EVE

ADDRESS: 3515 KARIYA DR

RES. TEL: 647-885-8639

BUS. TEL:

CELL: 647-885-8639

FAX:

EMAIL: khuranak@gmail.com

DATE OF REQUEST: Feb 9, 2010

Feb 9/2011

SERVICE REQUEST:

1. Hardwood Floor coming apart, gaps in the floor - Authorizing
2. (near the bedroom door) Entrance to unit
3. - noted flooring damaged
4. along the wall of washer
5. & dryer to bedroom
6. entrance - inspected Feb 10/2011
7. with Fries & Tom
- 8.
- 9.
- 10.

Floor by bedroom rising and has

gap

possible water damage

Fires Nov 10 2009