

cc: Customer Service
PMS system upload

SECOND WAIT/ATTN/ ON 2/10/11 10045

Eve: 3501

REC'D
JAN 17/11
S/S CU

AMACON DEVELOPMENT

AMACON SERVICE REQUEST FORM

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5J3B1

TEL: 416-369-9069 FAX: 416-369-9068

ATTENTION CUSTOMER CARE: 3515 KARIYA DR.

TEL: 905-848-2869 FAX: 905-848-2827
(905) 332-4636 (416) 369-9068

NAME: KOSOVSKI, 2 x N SUITE # 3501

DEVELOPMENT NAME: 905 949 4782 ADDRESS: 3515 KARIYA DR

RES. TEL: 905 949 4782 BUS. TEL: CELL:

FAX: EMAIL:

DATE OF REQUEST: 17 Jan 2011

SERVICE REQUEST:

1. ENTERING DOOR NEED SPONGE TAPE
2. DUE TO EXTREME AIR FLOW BETWEEN
3. DOOR FRAME AND DOOR
4.
5.
6.
7. J Kosvelli, N Allow you to enter
8. exit at any time N allow
9.
10. door not square to frame

needs to be padding or weather stripping
added fixed Jan 17 2011 4:00 PM

Previous
Customer Service will inspect the
door and make their assessment
I will double check to see if
this door (security) was
listed on the common area fire/
technical audit list.

CPW 02/24/2011

THANKS