

AMACON DEVELOPMENT

AMACON SERVICE REQUEST FORM

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5B 2B1

TEL: 905-368-9003 FAX: 416-368-9886
905-232-4636

ATTENTION: CUSTOMER CARE: 3515 KARIYA DR.

905-232-4637 (For no Amaccon)
CUSTOMER CARE

TEL: 905-368-2003 FAX: 905-368-2027

NAME Rich Enright

DEVELOPMENT NAME CVB

SUITE # 3601

ADDRESS # 3515

ADDRESS

RE: (880) 232-8779 BLS TEL: (416) 834-9323 Dnline

FAX:

EMAIL:

CELL: (416) 834-9323

DATE OF REQUEST:

April 5, 2010

SERVICE REQUEST:

1. To fix the (hole) ceiling in the master
2. bedroom bathroom,

3. _____
4. _____
5. Allowing Mr. Enright to enter the
6. Suite 3601

7. _____
8. Michael Enright
9. _____
10. _____

AMACON DEVELOPMENT

AMACON SERVICE REQUEST FORM

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5B 1B1

TEL: 905-363-2323 FAX: 416-363-2985

905-232-4637

(Formerly Ameca)
CUSTOMER CARE

ATTENTION: CUSTOMER CARE: 3515 KENYA DRIVE

TEL: 905-363-2323 FAX: 905-442-2827

NAME:

Dick Emigius

DEVELOPMENT NAME:

CE/E

SUITE #

3601

ADDRESS:

3515 Kenya Drive

POSTAL:

(289) 232-3779

BUS. TEL:

(416) 722-9219

CELL:

(647) 8357323

FAX:

EMAIL:

DATE OF REQUEST:

April 19, 2010

SERVICE REQUEST:

1. _____
2. We would like to inform you that
3. scheduled 5 times to fix the windows
4. and never was happened. We move the
5. furniture out from the area and put it back.
6. It is irritating to do this five times.
7. Since you have no reliable phone it working
8. we have no communication. Please leave us the
9. message or letter through (289) 232-3779 / (416) 835
10. 9323. When this procedure can be done, again

You are asked to confirm the suite.

Antibion Group Suite 3601