

AMACON SERVICE REQUEST FORM  
PLEASE MAIL, FAX OR SUBMIT ON-LINE  
AMACON CONSTRUCTION LTD. ATTENTION: CUSTOMER CARE  
37 BAY STREET, SUITE 400 (4TH FLOOR), TORONTO, ON M5J 3B2  
TEL: 416-369-9069 FAX: 416-369-9068  
WWW.AMACON.COM

NAME:

DAVE FRANKS

dk  
305

DEVELOPMENT NAME:

ELLE

ADDRESS:

3525 KENNEDY DR. SUITE # 305

RES.TEL:

416 936-5131

BUS.TEL:

CELL:

FAX:

DATE OF REQUEST:

DEC. 10, 2010

A copy of your request form will be given to and reviewed by an Amacon Customer Care Representative. Your request and any follow up that may be required will be co-ordinated by one of our Customer Care Representatives to ensure that your concerns are addressed.

Service Request:

1. HEAT FOR LIVING AND DINING AREA IS NOT WORKING.
2. BURNING SMELL COMING FROM UNIT.
3. GEORGE HARRINGTON WAS SUPPOSE TO RETURN TO FIX UNIT ON DEC. 09, 2010 (HE DID NOT COME BACK).
- 4.

AMACON SERVICE REQUEST FORM  
PLEASE MAIL, FAX OR SUBMIT ON-LINE  
AMACON CONSTRUCTION LTD. ATTENTION: CUSTOMER CARE  
37 BAY STREET, SUITE 400 (4TH FLOOR), TORONTO, ON M5J 3B2  
TEL: 416-369-9069 FAX: 416-369-9068  
WWW.AMACON.CO.UK

NAME: VAVE RAMSARAN

DEVELOPMENT NAME: ELLE

ADDRESS: 305-3525 KARIVA DR MISS

RES.TEL: (416) 936-5131

BUS.TEL: \_\_\_\_\_

CELL: \_\_\_\_\_

FAX: \_\_\_\_\_

DATE OF REQUEST: DEC 9/10

A copy of your request form will be given to and reviewed by an Amacon Customer Care Representative. Your request and any follow up that may be required will be co-ordinated by one of our Customer Care Representatives to ensure that your concerns are addressed.

Service Request:

1. CHIPS IN TUB - NOT ALL WERE FILLED IN

CAN ENTER IF TENANTS ARE NOT IN R

2. WAS COMPLETED BY GERT 24/10/10

3. Canadian WDW/Pool Services

4. \_\_\_\_\_

AMACON

L I V E W E L L

Warranty Services  
Work Order  
Phone: (905) 232-4636 Fax: (905) 232-4637

Location

Elle - Tower: Elle - Unit: 305  
81 SULTAN POOL DRIVE FT OBERON

Closing Date

0000

Date

19Jul10

Contact Name(s)

DAVE RAMSARAN and RUPINDER RYAT

Contact Telephone#

Res: (416) 749-4124 Bus: (416) 936-5178

Company:

Tile Source

Attention:

Matthew Paric

Telephone:

9 (05-) 660-773

Fax:

9 (05-) 660-7949

From:

Warranty Services Department - Head Office

Please complete the following items:

Deficiency Issue  
Number

18908 LAUNDRY CLOSET- NOTE- files marked at

entrance

Appointment  
Date/Time

✓  
06/24/10


Notes

RECEIVED  
10/17/2010

Date Completed:

July 13/10

Amakon Customer Care Signature:



Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.  
Failure to comply with this request will give Amakon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Back - Form A100

ID# 18908 Elle Ph Elle Lot 305

Mail

Grahme Walsh

W/Condo to Mrs  
Elle 305

**From:** Christina [Christina@lismechanical.com]  
**To:** Tuesday, December 07, 2010 3:27 PM  
Grahme Walsh  
**Cc:** parvikaur@verumest.ca; SGERMAN@TEMSPEC.COM; Robert Difazio; Robert Lisi SR  
**Subject:** Elle Condo #305  
**Attachments:** IMG00008-20101207-1421.jpg

Sept,

As per site inspection by Joe Ciampaglia.

There is a drain tail piece on the tray that is completely broken. It actually looks like it was not soldered properly. We received a call for no heat and during the flushing it caused a leak and water damages. See attached picture. Please advise when someone will be on site to make the repairs and the damages will be forwarded by the Property Management to Temspec.

Sincerely,

**Christina Franco**



**LSI MECHANICAL**  
**CONTRACTORS LTD.**

Lisi Mechanical Contractors Limited  
160 Disco Road  
Etobicoke, ON, M9W 1M4  
click for map

(416) 674-8333 x132 Office  
(416) 674-5399 Fax  
(888) 238-7318 Toll Free

(416) 674-5309 Direct Fax

[www.LSIMMECHANICAL.COM](http://www.LSIMMECHANICAL.COM)


**Sent:** Tue 5/10/2011 6:59 AM

McCarte Mrs  
Elle-305  
Completed Book

60

33  
05  
20


order  
pin  
051



37 Bay Street, Suite 400,  
Toronto, ON, M5J 3B2  
Tel. 416.369.9069  
Fax 416.369.0068



This e-mail is intended only for the named recipient(s) and may contain information that is privileged, confidential and/or exempt from disclosure under applicable law. No waiver of privilege, confidence or otherwise is intended by virtue of communication via the internet. Any unauthorized use, dissemination or copying is strictly prohibited. If you have received this e-mail in error, or are not named as a recipient, please immediately notify the sender and destroy all copies of this e-mail. Please be aware that internet communications are subject to the risk of data corruption and other transmission errors. For information of extraordinary sensitivity, we recommend that our clients use encryption software when they communicate with us by e-mail.



# AMACON CONSTRUCTION SERVICE REQUEST FORM

PLEASE FAX TO 416 369-9068

NAME: Dave Frommann

SUITE:

306

TEL: (416) 936-5131

BUS. TEL

Cell:

e-mail:

Project:

Address:

DATE OF REQUEST: June 22, 2011

Permission to enter:

YES	NO
<input checked="" type="checkbox"/>	<input type="checkbox"/>

Once received by an Amacon Customer Care Representative, this form becomes property of Amacon. Your request must be based on the Taron Warranty guidelines - scratches, nicks, dents are not warrantable, unless noted at time of the PDI (Pre-Delivery Inspection). Your request will be reviewed and addressed by an Amacon Representative as soon as a possible. If this is an Emergency please contact your concierge immediately at 369-521-1313 24 / hours. If your concern falls under the Common Area Element Warranty Guidelines, please see Property Management to address your concerns or call at 369-521-1194

ITEM#	ROOM/LOCATION	DESCRIPTION
	LIVING ROOM	- FLOORS SQUEAKING.
		-
		- FLOOR BARRIS TO BE REPLACED
		WERE THERE WAS A WHOLE
		LEAK.
		checked - gears to be
		replaced - and squeaks to column
		contracted - to make a column
		of corner door
		containing in leak already
		repaired.

HOMEOWNER SIGNATURE

[Signature]

DATE:

June 22, 2011

in

leak repaired.

to be

repaired.

repaired.

repaired.

repaired.

repaired.

repaired.

repaired.

repaired.

repaired.

repaired.

repaired.

repaired.

repaired.

repaired.

repaired.

repaired.

repaired.

repaired.

repaired.

repaired.

repaired.

repaired.

repaired.

repaired.

repaired.

repaired.

repaired.

repaired.

repaired.

repaired.

repaired.

repaired.

repaired.

repaired.

repaired.

repaired.

repaired.

repaired.

repaired.

repaired.

repaired.