



CONSTRUCTION SUMMARY

300 - 2 - The Barossa 1 (38-1) Elev B

Extras at Time of Sale

CEILINGS

Inv.188	1 - 9 FOOT CEILINGS IN BASEMENT
Line2562	Note:
16Jul15 / 4Oct15	
Inv.188	1 - SMOOTH CEILINGS - MAIN FLOOR
Line2563	Note:
16Jul15 / 4Oct15	

HARDWOOD FLOORING

Inv.188	1 - HARDWOOD FLOORING - STANDARD SERIES - 2 1/4 MERCIER SOLID OAK - UPPER HALL
Line2564	Note:
16Jul15 / 4Oct15	
Inv.188	1 - HARDWOOD FLOORING - STANDARD SERIES - 2 1/4 MERCIER SOLID OAK - LANDING
Line2565	Note:
16Jul15 / 4Oct15	


STAIRS AND RAILING

Inv.315	1 - UPGRADE RAILING - UPGRADE 2 - LEVEL 2 - WROUGHT IRON- BLACK
Line3198	Note:
13Sep15 / 4Oct15	

WINDOWS - BASEMENT

Inv.188	2 - BASEMENT WINDOW - 30 X 30
Line3196	Note:
16Jul15 / 4Oct15	
Inv.188	2 - BASEMENT WINDOW - 47 X 36 - EGRESS WINDOW
Line3197	Note: Permit Pending
16Jul15 / 4Oct15	

Lot #300




Ground Floor
Elevation A



LOW HEADROOM


UNEXCAVATED

Lot # 300




Second Floor
Elevation A







Ground Floor
Elevation A



Basement
Elevation A



Basement
Elevation B



Basement
Elevation C

The
cons
of flc
floor