

## **Quality Control-WEB**



Vendor / Builder # Enrollment #

Purchaser Name: Yong Mei Li Legal Address:

Phone Res: 18687626955 Project: Winlock Towns

Phone Bus: Plan #:

**Closing Date:** 1900-01-00 **Lot / Phase #:** 29 / 1

Inspector: PDI Company Municiaplity: North York

Inspection Date: May 05, 2022

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

## DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- · Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

## **OPERATING CONDITION**

- Windows, interior and exterior doors including garage overhead doors, door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- · Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- · Air conditioning system, if provided and if conditions permit

## GENERAL COMMENTS

NO	TE	:

Deficiency:

TOUCH UPS REQUIRED THROUGH OUT AS INDICATED

Pictures:

No Pictures for this deficiency

Deficiency

WINDOW SCREENS AND SLIDING SCREEN DOORS NOT INSTALLED THROUGHOUT

Pictures:

No Pictures for this deficiency

SIAINS
--------

NOTE:

Deficiency:

FINAL FINISH NOT COMPLETE

Pictures:

No Pictures for this deficiency

MASTER ENSUITE BATH			
SHOWER ENCLOSURE			
Deficiency: GLASS SHOWER DOOR NOT INSTALLED	Deficiency: FILL GAP SURROUNDING SHOWER ENCLOSURE		
Pictures: No Pictures for this deficiency	Pictures: No Pictures for this deficiency		
ELECTRICAL/LIGHTING			
Deficiency: LIGHTS NOT OPERATING			
Pictures: No Pictures for this deficiency			
· · · · · · · · · · · · · · · · · · ·			
BEDROOM 2			
WALLS/DOORS			
Deficiency: RIGHT SIDE BALCONY DOOR CASING DAMAGED AT BOTTOM			
Pictures: No Pictures for this deficiency			
LIBRARY/DEN			
WALLS/DOORS			
Deficiency: SLIDING DOORS FOR MECHANICAL ROOM NOT INSTALLED			
Pictures: No Pictures for this deficiency			
NOTE:			
<b>Deficiency:</b> SLIDING DOORS FOR MECHANICAL ROOM BLOCKING FURNACE FILTER			
Pictures: No Pictures for this deficiency			
MAIN BATHROOM			
SHOWER ENCLOSURE			
<b>Deficiency:</b> BASEMENT — SHOWER HEAD NOT INSTALLED			
Pictures: No Pictures for this deficiency			
NOTE:			
Deficiency: BASEMENT — EXHAUST FAN NOT OPERATING	Deficiency: BASEMENT — EXHAUST FAN COVER NOT INSTALLED		
Pictures: No Pictures for this deficiency	Pictures: No Pictures for this deficiency		

TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS		
* Purchasers or owners who intend to design to the vendor/builder authorizing the designa	nate someone to conduct the PDI in their place should ensure they provide written authority attention their behalf.	
lon		
Builder Representative	Purchaser	
Designate's Name(please print)	Designate's Signature	
I the homeowner, confirm that all repair work	listed will be completed	

Date

Purchaser

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER