



Soil Engineers Ltd.

CONSULTING ENGINEERS

GEOTECHNICAL • ENVIRONMENTAL • HYDROGEOLOGICAL • BUILDING SCIENCE

100 NUGGET AVENUE, TORONTO, ONTARIO M1S 3A7 • TEL: (416) 754-8515 • FAX: (416) 754-8516

BARRIE TEL: (705) 721-7863
FAX: (705) 721-7864

MISSISSAUGA TEL: (905) 542-7605
FAX: (905) 542-2769

OSHAWA TEL: (905) 440-2040
FAX: (905) 725-1315

NEWMARKET TEL: (905) 853-0847
FAX: (416) 754-8516

GRAVENHURST TEL: (705) 684-4242
FAX: (705) 684-8522

PETERBOROUGH TEL: (905) 440-2040
FAX: (905) 725-1315

HAMILTON TEL: (905) 777-7956
FAX: (905) 542-2769

Inspection No. 34

Gold Park Homes Inc.

Attention: Mr. Michael Cipriano

Lot 68 – Cranbrook Crescent

REFERENCE NO. 1608-C052

- Two 15-mm steel reinforcing bars have been placed continuously in the upper section of the foundation walls.

DATE: October 24, 2016

PROJECT:

Residential Subdivision
Gold Park Homes at Kleinburg Glen
Baron Street and Algoma Drive
City of Vaughan

JOB DESCRIPTION:

Steel Reinforcing Bar Inspection

DATE OF INSPECTION: September 20, 2016

INSPECTOR: Jalal Fahimi, C.E.T.

DESIGNED SOIL PRESSURE:

RECOMMENDED MAXIMUM ALLOWABLE
SOIL PRESSURE FOR INSPECTED SUBGRADE:

AS-BUILT ELEVATION:

WATER CONDITION:

DESCRIPTION OF INSPECTED SUBGRADE:

METHOD OF INSPECTION:

Visual


SUBGRADE:

GIVEN TO:

Bruno

1 kPa = 20.89 psf

The footings and foundation walls must be protected against frost action at all times. (05/91)



Dennis Lai, P. Eng.
DL:dd

