

## Soil Engineers Ltd.

CONSULTING ENGINEERS

## GEOTECHNICAL • ENVIRONMENTAL • HYDROGEOLOGICAL • BUILDING SCIENCE


100 NUGGET AVENUE, TORONTO, ONTARIO M1S 3A7 • TEL: (416) 754-8515 • FAX: (416) 754-8516

BARRIE TEL: (705) 721-7863 FAX: (705) 721-7864 MISSISSAUGA TEL: (905) 542-7605 FAX: (905) 542-2769 OSHAWA TEL: (905) 440-2040 FAX: (905) 725-1315 NEWMARKET TEL: (905) 853-0647 FAX: (416) 754-8516 GRAVENHURST TEL: (705) 684-4242 FAX: (705) 684-8522 PETERBOROUGH TEL: (905) 440-2040 FAX: (905) 725-1315 HAMILTON TEL: (905) 777-7956 FAX: (905) 542-2769

Inspection No. 49

Lot 28 (Left) – Zenith Avenue Lot 65 – Cranbrook Crescent

- Two 15-mm steel reinforcing bars have been placed continuously in the upper section of the foundation walls.



Gold Park Homes Inc.

Attention: Mr. Michael Cipriano

REFERENCE NO. 1608-C052

<u>DATE</u>: October 24, 2016

PROJECT:

Residential Subdivision Gold Park Homes at Kleinburg Glen Baron Street and Algoma Drive City of Vaughan

JOB DESCRIPTION:

Steel Reinforcing Bar Inspection

DATE OF INSPECTION: October 11, 2016

INSPECTOR: Jalal Fahimi, C.E.T.

**DESIGNED SOIL PRESSURE:** 

RECOMMENDED MAXIMUM ALLOWABLE SOIL PRESSURE FOR INSPECTED SUBGRADE:

**AS-BUILT ELEVATION:** 

**WATER CONDITION:** 

**DESCRIPTION OF INSPECTED SUBGRADE:** 

**METHOD OF INSPECTION:** 

Visual

**SUBGRADE:** 

GIVEN TO:

Bruno

1 kPa = 20.89 psf
The footings and foundation walls must be protected against frost action at all times. (05/91)



## Soil Engineers Ltd.

CONSULTING ENGINEERS

## GEOTECHNICAL • ENVIRONMENTAL • HYDROGEOLOGICAL • BUILDING SCIENCE


100 NUGGET AVENUE, TORONTO, ONTARIO M1S 3A7 • TEL: (416) 754-8515 • FAX: (416) 754-8516

BARRIE TEL: (705) 721-7863 FAX: (705) 721-7864 MISSISSAUGA TEL: (905) 542-7605 FAX: (905) 542-2769 OSHAWA TEL: (905) 440-2040 FAX: (905) 725-1315 NEWMARKET TEL: (905) 853-0647 FAX: (416) 754-8516 GRAVENHURST TEL: (705) 684-4242 FAX: (705) 684-8522 PETERBOROUGH TEL: (905) 440-2040 FAX: (905) 725-1315 HAMILTON TEL: (905) 777-7956 FAX: (905) 542-2769

Inspection No. 49

Lot 28 (Left) – Zenith Avenue Lot 65 – Cranbrook Crescent

- Two 15-mm steel reinforcing bars have been placed continuously in the upper section of the foundation walls.



Gold Park Homes Inc.

Attention: Mr. Michael Cipriano

REFERENCE NO. 1608-C052

<u>DATE</u>: October 24, 2016

PROJECT:

Residential Subdivision Gold Park Homes at Kleinburg Glen Baron Street and Algoma Drive City of Vaughan

JOB DESCRIPTION:

Steel Reinforcing Bar Inspection

DATE OF INSPECTION: October 11, 2016

INSPECTOR: Jalal Fahimi, C.E.T.

**DESIGNED SOIL PRESSURE:** 

RECOMMENDED MAXIMUM ALLOWABLE SOIL PRESSURE FOR INSPECTED SUBGRADE:

**AS-BUILT ELEVATION:** 

**WATER CONDITION:** 

**DESCRIPTION OF INSPECTED SUBGRADE:** 

**METHOD OF INSPECTION:** 

Visual

**SUBGRADE:** 

GIVEN TO:

Bruno

1 kPa = 20.89 psf
The footings and foundation walls must be protected against frost action at all times. (05/91)