Jason Brown 28 William Paddison Dr. Barrie on Lym 063 416 579-3864

TO Whom It MAY CONCERN,

This fax is being sent to address some issues that have risen after the 30 day form was sent in.

I wanted to address these problems in writing even though I was advised by the sales office to Keep a list and submit the form at "Years End".

I would have normally waited for the Years end form to be submitted but since the construction has started beside us there are some issues that need to be noted.

The following complaints are not on the 30 day list.

I have made the sales office aware of the shaky stairs leading to the front door but since the construction has started the machinery has further shaken the top "patio-stone" and developed a crack on the stone under neath.

A new incident has occured by one of the operators of the bulldozer. Someone has accidently clipped the side of the foundation with either the bulldozer or its load as there is a small crack forming from the site of impact.

2/



There are black "circles" that have been Knocked off the foundation barrier.

3/

The garage door has not been set properly as it raddles during windy days and the other panel mentioned in our 30 day list still has a small Crack in it.

4/

Now that we have purchased all of our small appliances we have noticed that the countertop is slagging. It has agused the cupboard doors below to rub while opening.

This o'course is due to faulty workmanship. There is no centre support in order for the counter top not to sag. The rubbing has caused chips in the cupboards.

5/

All doors are either rubbing or will not close due to swelling from humitiaty. This is causing wood chips and paint being scrapped off.

5 b/ We do not wish to have the outside trivi exposed all winter long as it is only cheap pine and untreated.

50/ Garage Floor has several cracks forming and recently we have noticed when it rains water is coming up from the cracks.



Jason Brown 28 William Paddison Pr Barrie ON LHM 063

.6/

Another problem mentioned to the sales office was in regard to a fear in the vinyl flooring in the basement washroom.

11

A crack about YH- 12 inch has developed in the master bathroom since the construction started. Its in the morter between the tub tiles.

We have another issue that greatly concerns us. Were aware that the lot on the other side of us has not been sold. It may not be sold or even if sold shortly may not be touched until spring. That means we will have problems again due to construction well after the "Year End" form has been sent in.

What will be done regarding any problems caused by further construction?

Please reply regarding concerns and give confermatic regarding repairs.

Thank you.

Jason Brown

FRI, Oct/2010 just before the longweekend (Thanksgiving) we had your handyman come and sand a few spots one was just above the Kitchen sink at the light fixture the other place was the hall railing. What a poor job that was done. He couldn't even take the time to un-screw (2) screws to take the light off In order to do a proper job. The hall railing needless to say, I could have done a better job. I also mention to him again, that the basement window were the leak is, looks like it is getting worse. Nothing was done, other then caulk the outside frame witch should have been done in the first place. However, that dosen't tell me if there is moisture. And his so-called aption about the Kitchen tile. I will state again - that tile has been like that since we moved in Please have the tite personis). come view that and some concerns with the hard-wor Flooring and the corpct which makes sounds as if their is plastic or something left under noth. Please send professionals for thetile and Flooring.
handy man that came here and repaired the copbours

doors, He done an excellent job. Send him to

investigate the basement windows before winter sets in. Thanks,