rage i oi i



PDI Page 1 of 1



Veador/Bailder#

Parchaser Name:

Phone Res : Phone Bus:

Justin Zimmerman and Taryn Doughty (905) 868-5029

Closing Date:

2012-01-20

Bruno Tidd

Enrollment#

Legal Address: Project: Lot / Pha

Municiapility:

JA 8 652

Pratt Hansen Group 39104 / Building39

Inspection Date: 16 Jan 2012

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- Bathtub sinks and toilets

COUNTERTOPS

- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- · Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- · Interior finished and trim carpentry

OPERATING CONDITION

- Windows, interior and exterior doors including garage overhead doors, door locks
- Faucets: Kitchen, bathroom, laundry room
 Exhaust fans (kitchen, bathrooms) if provided
- Electrical outlets and fixtures
- Gas fireplaces, incl. circulation fans, if provided
 Heat Recovery Ventilation system, if provided
- Heating system
 Hot water beater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit


Hot water hearer, if provided (not rental)
 Exterior finished, driveways, walkways, decks and landscaping

Also list here anything that can't be assessed because for example is dirty or inaccessible.

SERIND SINK.

GENERAL COMMENTS INSPECTION START TIME INSPECTION STARTED AT 8:00 PM. TOUCH UPS REQUIRED THROUGH OUT AS INDICATED. SCREENS NOTE: AND CRANKS MISSING ON WINDOWS. CABLE COVER PLATES NOT INSTALLED. FIRE ALARMS NOT AFFIXED TO WALLS. FORMACE NOT WORKING. MAIN BATHROOM CERAMIC TILE HAS BEEK REMOVED AND ENTIRE SURROUND TO SHOWER ENGLOSURE BE REPLACED. COUNTERTOPS SINK HOLE TOO BIG, GAP SHOWING AT RIGHT REAR. VANITY CABINETS KICK PLATE EDGE NOT COLOURED. CERAMIC GROUT GAP AT BASE OF DOOR TRIM RIGHT SIDE. SMALL TILE FIECE CROOKED. AT ENTRY DOOR GROUT PLOORING KITCHEN FLOORING CERAMIC GROOT HAS HOLES THROUGHOUT KITCHEN. CHIPPED TOP LEFT TOP GRAWER. GAP AT FILLER AND WALL CABINETS TO LEFT OF FRIDGE OPPER.

CAULKING NOT COMPLETED. REFORCH EDGE OVERHANG AT WALL



THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RE POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE V * Purchasers or owners who intend to designate someone to conduct the l authorizing the designate to sign this form on their behalf.	WARRANTY REQUESTS	
Builder Representative	Tour Documents	
Designate's Name(please print) I the homeowner, confirm that all repair work listed has been completed	Designate's Signature	
	Purubaser	Date

31001-PDIF-01.01