

PDI Page 1 of 2



Veador/Builder#

34234

Purchaser Name: Phone Res :

Phone Bus: Closing Date:

Inspector:

(705) 796-4462

Doug Trumbic

Eurolbnent#

Legal Address: Project: Plan #: Lot / Phase #:

Municiaplity:

1709227

DES[19] Pratt Hansen Group

2041 / MWI

Inspection Date: 27 May 2016

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition.

Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

Windows, side lights and other glazing. Window and door screens

Bathtub sinks and toilets.

Bathroom accessories if provided
 Mirrors, counter tops and cabinetry
 Flooring (bardwood, vinyl, ocramic tiles, carpeting)

Interior finished and trim curpentry

Hot water heater, if provided (not rental)
 Exterior finished, driveways, walkways, docks and landscaping

OPERATING CONDITION

· Windows, interior and exterior doors including garage overhead doors, door

Fancets: Kitchen, bathroom, laundry room
 Exhaust fans (kitchen, bathrooms) if provided
 Electrical outlets and fixtures

Gas fireplaces, incl.circulation fans, if provided Heat Recovery Ventilation system, if provided

Heating system

Hot water heater, if provided (not rental)
 Air conditioning system, if provided and if conditions permit

Also list here anything that can't be assessed because for example is dirty or inaccessible.

GENERAL COMMENTS INSPECTION START TIME INSPECTION STARTED AT 1 15pm TOUCH UPS REQUIRED THROUGH OUT AS INDICATED diwall- repairs needed throughout- tape peeling in NOTE: bedroom two in two places in bedroom 2 and upper haliway. MASTER BEDROOM cable plate not straight. No Deficiencies in this SHARED ENSUITE MIRROR mirrorto be removed- as per aps NOTE doorway to master not latching BEDROOM #2 9ROKEN-_right side. WINDOWS LIVING ROOM HARDWOOD CHIPPED - as marked One peice FLOORING crakcked/broken One peice slightly raised Gap between but joint - peice not out straight. KITCHEN Customer concerned about deviation between ceramics WALLS and hardwood transition. NOTE: ceiling rough in areas BASEMENT refling loose at bottom. WINDOWS window fell out of frame-EXTERIOR Coach light needs caulkingaove door to exterior from Downspout elbow short- high above roof- unlike the gest of them on the block BRICKS crooked brick at steppingby slider. GARAGE DOORS caulking/fill needed around casing. NOTE: walley/trough metal dented and not tight to roof. 1st riser of walkway broken/cracked mortar on block wall in garage- several locations. caulking not completed on coach lightabove man door to exremior from garage. power vent missing screen/elbow slider at rear broken at base- and interior handle scratched. nails in mortax at rear corner EXTERIOR SEASONAL grading, sod, paved driveway incomplete. patio stones andsteps incompleted.

RECEIVED MAY 3 1 2010 MWI-2041

31001-PDIF-01.01

5/27/2010

PDI Print Form