
Lage 1 Of 1



## PDI Page 1 of 1



Vendor/Builder#

Purchaser Name:

Khaled Ismail and Jamal Ismail

Phone Res : Phone Bus: Closing Date: (705) 730-0625

2013-02-28 Bruno Tidd Enrollment#

Legal Address: Project: Plan #: Lot / Phase #:

Municleplity:

DLS[19] H Hansen Development Inc.

SWD-00032 / 1

Inspection Date: 26 Feb 2013

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition.

Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Furchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

Windows, side lights and other glazing. Window and door screens

- Bathtub sinks and toilets

- Butimoon accessories if provided
   Mirrors, counter tops and cabinetry
   Flooring (hardwood, vinyl, caramic tiles, carpeting)
- Interior finished and trim carpentry

- Hot water heater, if provided (not rental)
   Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

· Windows, interior and exterior doors including garage overhead doors, door locks.

- · Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
   Electrical outlets and fixtures

- · Gas fireplaces, incl. circulation fans, if provided · Heat Recovery Ventilation system, if provided
- Heating system
   Hot water heater, if provided (not rental)
- · Air conditioning system, if provided and if conditions permit

Also list here anything that can't be assessed because for example is dirty or inaccessible.

GENERAL COMMENTS			
INSPECTION START TIME NOTE:	INSPECTION STARTED AT 3:00 F.M. PAINT THROUGHOUT VERY THIN AND SOME AREAS NOT PAINTED AT ALL. TOUCH UPS REQUIRED THROUGH OUT AS INDICATED. KO SCREENS INSTALLED.		
NEW TELEPHONE NUMBER	705-730-0625		
LIVING ROOM			
ELECTRICAL/LIGHTING	CABLE CUTLET HAS NO OUTLET NEAR IT. MOVE CABLE OUTLET CLOSER TO PLUG IN CORNER,	<del></del>	
KITCHEN			
CABINETS	CPPER CABINET OPFER LEFT FAR SIDE OF STOVE MYSSING. FILL SCREW HOLES ON EITHER SIDE OF STOVE END GABLE.		
LAUNDRY ROOM			
FLOORING	BASEBCARD CERAMIC DOES NOT GO ALL THE WAY TO THE TRIM.		
NOTE:	LINT TRAP ON EXHAUST IS BENT AT RIGHT SIDE OF SLOT AND IS DIFFICULT TO REMOVE TO CLEAN,		
FINISHED BASEMENT			
NOTE:	MIRRORS MISSING. REMOVE TOWEL BAR OVER TOTLET,		



THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RI POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE! * Purchasers or owners who intend to designate someons to conduct the authorizing the designate to sign this form on their behalf.	WARRANTY REQUESTS	
Builder Representative	Purchaser	
Designate's Name(please print) I the homeowner, confirm that all repair work listed has been completed	Designate's Signature	
	Purchaser	Date

31001-PDIF-01.01