

lot 193
(WPI)
1225 LAURAND ST



APR 2nd 2009

Pre-Delivery Inspection Form

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any "substitutions" of items referred to in, or to be selected under, the Agreement of Purchase and Sale (APS). Please initial all changes and deletions. As a minimum check the following:

DAMAGED, INCOMPLETE OR MISSING	OPERATING CONDITION
<ul style="list-style-type: none">• Windows, side lights and other glazing. Window and door screens• Bathtubs, sinks and toilets• Bathroom accessories, if provided• Mirrors, countertops and cabinetry• Flooring (hardwood, vinyl, ceramic tiles, carpeting)• Interior finishes and trim carpentry• Furnace• Hot water heater, if provided (not a rental)• Exterior finishes, driveways, walkways, decks and landscaping are complete	<ul style="list-style-type: none">• Windows, interior and exterior doors (including garage overhead door). Door locks• Faucets: kitchen, bathroom, laundry room• Exhaust fans (kitchen, bathrooms), if provided• Electrical outlets and fixtures• Gas fireplaces, incl. circulation fans, if provided• Heat Recovery Ventilation system, if provided• Heating system• Hot water heater, if provided (not a rental)• Air conditioning system, if provided and if conditions permit

Comments COLLINS REMODEL (Aug 1).

Item #	Room/Location	Description
1	EXTERIOR	GRADING, SOD, PAVED DRIVeway, MOWn TOUCH-UPS, PAINTING, PORCH LEDGE
2	INTERIOR	TOUCH-UPS THROUGH-OUT. NOT COMPLETE.
3	EXTERIOR	ETAVESTROUGH NAIL TO BE SUNK (WEST SIDE).
4	EXTERIOR	CAULKING NOT COMPLETE ON 2 nd FLOOR.
5	EXTERIOR	CUSTOMER CONCERNED ABOUT FOUNDATION @ BASE OF GARAGE DOOR (LEFT SIDE).
6	EXTERIOR	CUSTOMER CONCERNED ABOUT EXCESS WIRE AND FINISH LOOK OF AIR CONDITIONER.
7	EXTERIOR	WINDOW SCREENS & CRANKS NOT INSTALLED
8	MASTER BEDROOM	CARPET DISLOCATED ON WEST WALL.
9	ENSUITE	CAULKING AROUND VANITY.
10	ENSUITE SHOWER	SHOWER HEAD PIPE/HOLE COVER NOT FLUSH TO WALL.
11	ENSUITE	VANITY NOT FLUSH TO WALL.
12	ATTIC VENT	NEEDS PAINTING
13	INTERIOR	WINDOW FRAMES THROUGHOUT
14	BASMENT	NORTH EAST WINDOW WILL NOT CLOSE (BOTH SIDES).
15	BASMENT	BRIDGING/SUPPORTING NOT SECURE IN CENTRE CLOSE TO HOT WATER TANK.
16	BASMENT	INSULATION MISSING IN UTILITY ROOM / 1 BK.
17	BASMENT	BASE PLATE TO BE REMOVED FROM ENTRANCE INTO FRONT ROOM.
18	FURNACE	FILTER TO BE CHANGED COVER TO BE MOUNTED. BRAND LOGO NOT INSTALLED.
19	EXTERIOR	PANEL NOT LABELLED
20	LAUNDRY DOWN	DRAIN HOLE VERY ROUGH.
21	DOOR SLIDER	BOTTOM STOPPER BROKEN
22	KITCHEN	HANDLES INCORRECT
23	KITCHEN	FAUCET MISSING Aerator
24	POWDER ROOM	FLOOR VENT NOT FLUSH TO FLOOR.
25	FIREPLACE	COVER NOT SET UP TO OPERATE.