

2 Queen Elizabeth Boulevard Toronto, Ontario M8Z 1L8 Tel: 416-253-6909 Fax: 416-253-2125

SERVICE WORK ORDER

1100 Ellesmere Road - 1 - Common Areas

August 10, 2018

Trade:

Queenscorp Group

2 Queen Elizabeth Boulevard

Toronto, ON M8Z 1L8

Contact: Customer Care

Phone: (416) 253-6909

Fax: (416) 253-2125

Cell:

Email: customercare@queenscorp.com

Contact: Common Area

Property Location:

Phone:

Email: Contact:

Phone:

Email:

Please complete the following service work detailed below:

Miscellaneous Install baseboards in mechanical room [Quality Control] Complete missing sidewalk expansion joint caulking - caulking colour: Smoke Grey - Dow Corning 795 [Quality Control]	Control	Date/Time	
Complete missing sidewalk expansion joint caulking - caulking colour: Smoke Grey - Dow Corning 795 [Quality Control]			
expansion joint caulking - caulking colour: Smoke Grey - Dow Corning 795 [Quality Control]			
colour: Smoke Grey - Dow Corning 795 [Quality Control]			
[Quality Control]			
	l		
·			
			12
•			
		ļ	
			A
	0.	0.10	olone.
		Trucy	1
		//	
			2.
, ,			
			-
prevent vehicles from hitting top coping			
blocks. [Quality Control]			
Create saw cut grooves in concrete	PL.	Aug 11	o lone.
		ladder bolts to provide double nut to secure ladder standoff of wall in mechanical room Mechanical Room 11/29/2016 [Quality Control] Roof - Install bolts on upper roof ladders [Quality Control] Replace dead plant material - as per attached drawing. [Quality Control] Install new, wider aluminum threshold to Unit #5 complete with caulking. [Quality Control] Correct caulking to new aluminum threshold at suite entry door of unit #6. [Quality Control] Parge and patch concrete foundation north wall along drive thru lane. Remove formwork and install river rocks in gap between wall and curb. [Quality Control] Add additional river rocks if required below gas meters. [Quality Control] Repair retaining wall cap blocks. [Quality Control] Remove – lower retaining walls to prevent vehicles from hitting top coping blocks. [Quality Control]	ladder bolts to provide double nut to secure ladder standoff of wall in mechanical room Mechanical Room 11/29/2016 [Quality Control] Roof - Install bolts on upper roof ladders [Quality Control] Replace dead plant material - as per attached drawing. [Quality Control] Install new, wider aluminum threshold to Unit #5 complete with caulking. [Quality Control] Correct caulking to new aluminum threshold at suite entry door of unit #6. [Quality Control] Parge and patch concrete foundation north wall along drive thru lane. Remove formwork and install river rocks in gap between wall and curb. [Quality Control] Add additional river rocks if required below gas meters. [Quality Control] Repair retaining wall cap blocks. [Quality Control] Remove – lower retaining walls to prevent vehicles from hitting top coping blocks. [Quality Control]

SMOKE GREY CAUKING