



**Zancor Homes Stayner Limited**  
**Warranty Services**  
**Phone: (905) 738-7010**  
**Fax: (905) 738-5948**

**Work Order**

**Closing Date:** 24Oct19

**Address:** 220 Lia Drive

Stayner, Ontario

**Location:** Villages in Stayner - Phase: 2 - Lot: 29

**Today's Date:** 04Jan21

**Contact(s):** Nelson, Mota Melao - Cell: (416) 433-8202

**Email:** nelsun@rogers.com

**Company:** Medi Group

**Attention:**

**Telephone:** (416) 741-2737

**Fax:** (416) 741-1593

**Please Complete the following items:**

DAI	Type	Issue	Appt. Date/Time	Notes
140836	✓ Year	Exterior- General- I've recently noticed a cracked brick above the front door and the concrete around the brick and down the side seems darker like its damp.		Remove + install 1 brick at soldier course - water getting in from porch roof. - Needs inspection by siding company.

**Date Completed:** \_\_\_\_\_

**Homeowner Signature:** \_\_\_\_\_

The Homeowner acknowledges and accepts all work has been completed in a workman like manner.


**Date Completed:** 4Jan16, 2021 **Trade &/or Service Tech.**

**Signature:** \_\_\_\_\_

**Print Name:** \_\_\_\_\_

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

**Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be**



# MEDI GROUP Service

WO Number : **W-075668**

WO Date : **06-Apr-2021**

Issued To : **ROBERT ULJASZ**

Builder : Zancor  
Project : ZANCOR-STAYNER-8-18

Lot No : 29  
Model : 50-7 (B)

## Directions : Stayner

Main Intersection: Road 91 and Road 42  
(south of 91 and west of 42). From road

Address :  
Contact :

RECEIVED APR 07 2021

Main Brick : Royal Gray

Main Stone :

Accent Brick :

Accent Stone :

INIT	Item	Work Description	PO	Builder Ref #
✓	1	CRACKED BRICK ABOVE FRONT DOOR AND THE CONCRETE AROUND THE BRICK AND DOWN THE SIDE SEEMS DARKER - LIKE ITS DAMP		01M143624 S-059648

Remove & install 1 brick at soldier course  
Water pitting from grade roof  
(Need inspect by siding company)  
06 April/21

Homeowner Signature

Date Completed

April 6/21

Site Super Signature

Date Completed

Special Notes :

Scanned

APR 13 2021

Completed  
Processed By: