

## **Service Completion Status Report**

**Date :** Jun 3, 2021

Fax:

## **Zancor**

Phone:

ZAN08 - ZANCOR HOMES (COOKSTOWN) LTD.		Report To: Site	
Work Description	Status Status Date	Builder Ref #	
DRYER VENT SUPPOSED TO BE 5" VENTS - THEY	Completed	10M133201	
BOTH NEED TO BE CUT 5"	06/03/2021	S-059386	
29 MISSING MORTAR - INSPECT ENTIRE HOUSE	Completed	142154	
	06/03/2021	S-059930	
CHIPPED BRICK AT REAR, LEFT OF SLIDING DOOR	Completed	142831	
AND CHIPPED BRICKS AT FRONT PORTICO notes: front needs tint - back brick has been changed.	06/03/2021	S-060190	
	DRYER VENT SUPPOSED TO BE 5" VENTS - THEY BOTH NEED TO BE CUT 5"  MISSING MORTAR - INSPECT ENTIRE HOUSE  CHIPPED BRICK AT REAR, LEFT OF SLIDING DOOR AND CHIPPED BRICKS AT FRONT PORTICO	Work Description  DRYER VENT SUPPOSED TO BE 5" VENTS - THEY BOTH NEED TO BE CUT 5"  MISSING MORTAR - INSPECT ENTIRE HOUSE  Completed 06/03/2021  CHIPPED BRICK AT REAR, LEFT OF SLIDING DOOR AND CHIPPED BRICKS AT FRONT PORTICO  Status Date  Completed 06/03/2021	