## Outstanding Deficiencies Villages in Stayner - Phase: 2 - Lot: 16

<u>Date</u> Reported	Type	Number	Deficiency Description	Trade Assigned	Add Trade	Appointment Date	Item Completed	Initial
20Apr21	1 Year	6	Main Hall- General- Large lump in floor from 30 day tarion Additional lump in floor at entry of hallway near the first closet HUMP AT ARCH INTO KITCHEN; MY RECORDS DO NOT SHOW THIS ON THE 30 DAY REPORT; I HAVE ISSUED A WORK ORDER TO THE FLOORING CONTRACTOR AND MY SERVICE PERSON FOR THIS ITEM; HUMP AT 2ND CLOSET IS MINOR, WE WILL INSPECT TO SEE IF IT WOULD BE WARRANTED	Stayner Zancor Warranty Service 143490	<u>Add</u>	29Jun21	/_	94
20Apr21	1 Year	6	Main Hall- General- Large lump in floor from 30 day tarion Additional lump in floor at entry of hallway near the first closet HUMP AT ARCH INTO KITCHEN; MY RECORDS DO NOT SHOW THIS ON THE 30 DAY REPORT; I HAVE ISSUED A WORK ORDER TO THE FLOORING CONTRACTOR AND MY SERVICE PERSON FOR THIS ITEM; HUMP AT 2ND CLOSET IS MINOR, WE WILL INSPECT TO SEE IF IT WOULD BE WARRANTED	First Canadian Hardwood 143511		29Jun21	1	90
20Apr21	1 Year	·	Main Hall- General- Large lump in floor from 30 day tarion Additional lump in floor at entry of hallway near the first closet HUMP AT ARCH INTO KITCHEN; MY RECORDS DO NOT SHOW THIS ON THE 30 DAY REPORT; I HAVE ISSUED A WORK ORDER TO THE FLOORING CONTRACTOR AND MY SERVICE PERSON FOR THIS ITEM; HUMP AT 2ND CLOSET IS MINOR, WE WILL INSPECT TO SEE IF IT WOULD BE WARRANTED	Kingsview Carpentry 144064		<u>29Jun21</u>	1	80
20Apr21	1 Year	8	Powder Room- General- Tiles installed slanted on both ends AS PER INSPECTION 1 RAISED TILE AT THE ENTRANCE ROOM TO POWDER; RIGHT CORNER- AV CONFIRMED TILE NOT RAISED SERVICE CHECK IF WALL STRAIGHT	Stayner Zancor Warranty Service 143492	Add	29Jun21	/ <	8
20Apr21	1 Year	23	Exterior- General- Siding bent across whole house. Not seen on other houses SIDING IS BULKED AT THE SIDE AND REAR OF THE HOME; DAY OF INSPECTION IT WAS 10-15 DEGREES; THIS IS NOT DUE TO WEATHER	Giancola Aluminum 143508	Add	NoAppoint.		

Homeowner Signature:

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Zancor Service Technician:



Zancor Homes Stayner Limited Warranty Services Phone: (905) 738-7010 Fax: (905) 738-5948

Work Order

Closing Date:
Address:

Location:
Today's Date:
Contact(s):

03Apr20
201 Roy Drive
Stayner, Ontario
Villages in Stayner - Phase: 2 - Lot: 16
25Jun21
James Jackson - Cell: (519) 217-6637
Sarah, Elizabeth Ellery - Cell: (519) 217-6637
ellery/2468@gmail.com

Email:

Company Attention: Telephone: Stayner Zancor Warranty Service Site Super.

(705) 423-1136

## Please Complete the following items:

143490	1 Year	Main Hall- General- Large lump in floor
		from 30 day tarion Additional lump in floor
		at entry of hallway near the first closet
		HUMP AT ARCH
		INTO KITCHEN; MY
		RECORDS DO NOT
		30 DAY REPORT;
		HAVE ISSUED A
		WORK ORDER TO
		THE FLOORING
		MY SERVICE
		PERSON FOR THIS
		ITEM; HUMP AT 2ND
		CLOSET IS MINOR,
		WE WILL INSPECT
		TO SEE IF IT WOULD BE WARRANTED
143492	1 Year	Powder Room- General- Tiles

both ends AS PER INSPECTION 1 RAISED TILE AT THE ENTRANCE ROOM TO POWDER; RIGHT CORNER- AV CONFIRMED TILE NOT RAISED SERVICE CHECK IF WALL STRAIGHT	INSPECTION 1 RAISED TILE AT THE ENTRANCE ROOM TO POWDER: RIGHT CORNER- AV CONFIRMED TILE NOT RAISED SERVICE CHECK IF WALL STRAIGHT	
		anatalied statiled of

Date Completed: UNE 29 2021

has been completed in a workman like manner.

Date Completed: Jauk 29 201 Trade & for Service Tech.

Signature:

Print Name: ATTHAN SMAS

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and applied to the Company listed above. it's group of companies) the right to carry out any and all repairs. All costs incurred will be