

NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6 TEL (905) 672-1233 FAX (905) 672-1076

WO # W138860

Service Date: Aug 03, 2021

电极 化量 电电压电路

Priority:	Normal	Status:	SCHEDULED	
BUILDER				0
Customer:	611313	City:	INNISFIL	Received: Jul 06, 2021
Name:	ZANCOR BELLE AIRE SHORES	Service Phone(s):		Time:
Service Fax:		Site Phone:		Order: D361811-1
Site Fax:		Lot#:	37N	Phase:
RESIDENT	INFORMATION			
Home Owner	Name: N/A	Address:	N/A	
Home Phone	(s): 705-828-3421	Work Pho	one(s):	
Cell Phone(s)	:	Email(s):		
LINKED OR	DER INFORMATION			
Customer:	611313 ZANCOR BELLE AIRE SHORES		Lot #: 37N	
Model:	50-07 DELTA ST+OP GF(LOFT)/SW		Phase:	. 2 - 0 - 4
SERVICE IN	ISTRUCTIONS			
ROUMEN WE CAULKING IN THIS OFF TH	WNER IS REALLY UPSET WITH THE PIECENT TO INSPECT AND CONFIRMED THIS NSTEAD WHICH WE WILL NOT BE ABLE THE LIST UNTIL IT PROPERLY INSTALLED ASE LET ME KNOW WHEN WE CAN BOO	IS UNACCEPTABL TO PAINT OVER. TH RIGHT. PLEASE HA	E. WOOD FILLER WASN HE HOMEOWNER ASKE	'T EVEN USED. THEY ADDED D FOR ME TO NOT REMOVE
PARTS REC	QUIRED			
LN Item Desc	ription Location	Specification	Size Optio	ns Qty
Wood he	E DOOR FRAME FRT/GAR eader only 8 x 7 4 5/8 4 1/2 rickmould	FRAME ONLY	98.75 X 85.375 558	1
Problem Desc	cription:)//0 *		
☐ Warranty ☐ CHARGEABLES				
Material \$ Material \$				
Labour \$		Labour \$		
		P.O.#:		
Cause:			50 L 50 W	<u> </u>
Solution:	Hode Pemple the cai	olking and	put woodfille	r, boildo
Date Comp	leted: Aug 3 202	Аррг	roved:	
	Time:	Service Sign		ALEX



Service Department <servicedept@newmar.com>

Fwd: Lot 37N-Innisifl-Newmar

1 message

Melissa Green <mgreen@newmar.com>

To: Service Department <servicedept@newmar.com>

Tue, Jul 6, 2021 at 10:58 AM

08.03.2021 alex

----- Forwarded message ------

From: Gisella Fiore < Gisella@zancorhomes.com>

Date: Tue, Jul 6, 2021 at 8:47 AM Subject: Lot 37N-Innisifl-Newmar

To: service@newmar.com <service@newmar.com>, Melissa Green <mgreen@newmar.com>

Good Morning,

The homeowner is really upset with the piece of garage trim that was installed. My serviceman Roumen went to inspect and confirmed this is unacceptable. Wood filler wasn't even used. They added caulking instead which we will not be able to paint over. The homeowner asked for me to not remove this off the list until it properly installed right. Please have this replaced I have resent a work order. Please let me know when we can book this for.

Service Manager



Giselia Flore

Gisella@zancorhomes.com

P: 905.738.7010 F: 905.738.5948

221 North Rivermede Road- Concord, ON L4K 3N7

CONFIDENTIALITY NOTICE: This email message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential and privileged information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the Intended recipient, please reply to the sender by email and destroy all copies of the original message.

Please note that our response lead time is longer than before due to backlogs which we have in this pandemic. Thank you for your understanding and patience

Thank you 😈



Melissa Green **Customer Service Facilitator**



IMG_3684.heic 1283K