Work Order



Zancor Homes (Cookstown) Ltd. Warranty Services Phone: (905) 738-7010 Fax: (905) 738-5948

02Nov20

Closing Date:
Address:
Location:
Today's Date:
Contact(s):

Cookstown - Phase: 1 - Lot: 5
04Nov21
Thanapalan Rohan - Cell: (416) 627-3899 - (rohankaven@gmail.com)
Shanthiri Rohan
rohankaven@gmail.com

Email:

Zancor-Cookstown Service

Company:
Attention:
Telephone:
Fax:

146142 Interval Kitchen- General- SVC TO PATCH TRIM AT MUD ROOM DOOR FROM VIA TRIM REPAIR  146170 Interval Other- General- INSPECT AND COMPLETE IF REQUIRED-FRAMING DEFICIENCIES FROM INSPECTION RED-FROM INSPECTION REPORT DATED MAY 26, 2020. 1.  REMOVE ALL INSULATION BLANKET WRAP FROM AROUND STEEL BEAMS AND SOLID FILL, LEAVE EXPOSED FOR INSPECTION. 2.  JOIST HANGERS REQUIRED AT FIRST LANDING TO BASEMENT. ADVISE	DAI Type Issue	Type	Issue		Appt. Date/Time	Notes
Interval Other- General- INSPECT AND COMPLETE IF REQUI REDFRAMING DEFICIENCIES FROM INSPECTION REPORT DATED MAY 26, 2020. 1. REMOVE ALL INSULATION BLANKET WRAP FROM AROUND STEEL BEAMS AND SOLID FILL, LEAVE EXPOSED FOR INSPECTION. 2. JOIST HANGERS REQUIRED AT FIRST LANDING TO BASEMENT. ADVISE	146142	Interval	Kitchen- General- SVC TO PATCH TRIM AT MUD ROOM DOOR FROM VIA TRIM	<	280ct21 /am	
INSPECT AND COMPLETE IF REQUI REDFRAMING DEFICIENCIES FROM INSPECTION REPORT DATED MAY 26, 2020. 1. REMOVE ALL INSULATION BLANKET WRAP FROM AROUND STEEL BEAMS AND SOLID FILL, LEAVE EXPOSED FOR INSPECTION. 2. JOIST HANGERS REQUIRED AT FIRST LANDING TO BASEMENT. ADVISE	1/6170	Interval	Other- General-		05Nov21	Arrival 12-1:30pm
DEFICIENCIES FROM INSPECTION REPORT DATED MAY 26, 2020. 1. REMOVE ALL INSULATION BLANKET WRAP FROM AROUND STEEL BEAMS AND SOLID FILL, LEAVE EXPOSED FOR INSPECTION. 2. JOIST HANGERS REQUIRED AT FIRST LANDING TO BASEMENT. ADVISE	146170	Interval	Other- General- INSPECT AND COMPLETE IF REQUI		/pm	Willed IZ
MAY 26, 2020. 1.  REMOVE ALL INSULATION BLANKET WRAP FROM AROUND STEEL BEAMS AND SOLID FILL, LEAVE EXPOSED FOR INSPECTION. 2. JOIST HANGERS REQUIRED AT FIRST LANDING TO BASEMENT. ADVISE			PERICIENCIES FROM INSPECTION			
BLANKET WRAP FROM AROUND STEEL BEAMS AND SOLID FILL, LEAVE EXPOSED FOR INSPECTION. 2. JOIST HANGERS REQUIRED AT FIRST LANDING TO BASEMENT. ADVISE			MAY 26, 2020. 1.		1	
FROM AROUND STEEL BEAMS AND SOLID FILL, LEAVE EXPOSED FOR INSPECTION. 2. JOIST HANGERS REQUIRED AT FIRST LANDING TO BASEMENT. ADVISE			INSULATION BI ANKET WRAP	<		
EXPOSED FOR INSPECTION. 2. JOIST HANGERS REQUIRED AT FIRST LANDING TO BASEMENT. ADVISE			FROM AROUND STEEL BEAMS AND SOLID FILL, LEAVE			
REQUIRED AT FIRST LANDING TO BASEMENT. ADVISE			INSPECTION. 2.			
			REQUIRED AT FIRST LANDING TO BASEMENT. ADVISE			

MS PECTION page 1/2

Date Completed: 05/11/2/	Date Completed: 25/11/2521	ONCE COMPLETE SO INSPECTION WITH TOWN CAN BE CALLED IN. AS PER ANTHONY
 Trade &/or Service Tech. Signature:	Homeowner Signature: The Homeowner acknowledges and accepts all work has been completed in a workman like manner.	

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.