



Zancor North Inc. **Warranty Services** Phone: (905) 738-7010 Fax: (905) 738-5948

Item #6- bedroom

above the garage is very hot in the summer and very cold in the

winter either needs more insulation or a wall separating part of the garage from the outer roof-INFRARED READING

Work Order

PIOSING DEL	e: U10ct2									
Address:	44 Blar	ica Crescent								
		a Beach								
Location:	The Village of Trillium Forest - Phase: 3 - Lot: Block 135 Unit 4									
Today's Dat										
Contact(s):										
Email: poncho967@hotmail.com										
Сотрапу:	Wasaga	a Zancor Warranty Service	140 1 200							
Attention:										
Telephone:		28-6483								
Fax:	(705) 42	(705) 428-6484								
Please Com	plete the foll	lowing items:								
DAI	Туре	Issue	Appt. Date/Time	Notes						
146123	1 Year	Bedroom 4- General-	16Nov21	AIR BALMENTS						

U16/2021 Date Completed:

Homeowner Signature: 🌋

The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

NEWDS TO BE

NATIONAL DA

Trade &/or Service Tech.

Signature:

Print Name:

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form

page 1/2

signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

page 2/2

Outstanding Deficiencies The Village of Trillium Forest - Phase: 3 - Lot: Block 135 Unit 4

180ct21 Year	180ct21 1 Year	180c121 1 Year	180ct21 1 Year	18 <u>Oct21</u> 1 Year	180ct21 Year	Reported Type
16	15	14	13	12	=	Numbe
Bedroom 4- General-Item #6- bedroom above the garage is very hot in the summer and very cold in the winter either needs more insulation or a wall separating part of the garage from the outer roof-INFRARED READING	Main Hall- General- Item #5- hardwood floor is buckled in one area up stairs all and area in living room-N.A	Main Bathroom- General- Item #4-fan in two piece bathroom rubs and is very noisy have taken cover off many times and wiggled it good bit a little bit then makes noise	Master Ensuite- General- Item #3- ensuite bathroom shower panels have come loose and need to be clipped and caulked	Basement- General- Item #2- Basement adjusted very tight to close	Garage- General- item #1- garage door into house is warped or needs adjustment	Number Deficiency Description
<u> </u>	First Canadian Hardwood 146122	Mykon Electric North Ltd 146121	Central Glass 146120	WYECROFT TRIM 146119	<u>Newmar</u> 146118	Trade Assigned
Add	Add	Add	Add	Add	Add	Add Trade
16Nov21	16Nov21	16Nov21	16Nov21	16Nov21	16Nov21	Add Appointment Trade Date
<				1		Item Completed
10,1			ř	A DA	definition then.	Initial

Homeowner Signature:

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Zancor Service Technician: (Courses 4 2) ANN

https://bstapps.com/zancor/data/builderforms/ZanHSReportDeficiencyCheckList.php?&var_selected_app=PASS&var_Centre=The%20Village%20of%20Trillium%20Forc... 2021-11-12