Outstanding Deficiencies Shoreline Point - Phase: 1 - Lot: 1

<u>Date</u> <u>Reported</u>	<u>Туре</u>	Number	Deficiency Description	Trade Assigned		Appointment Date	Item Completed	Initial
31Mar22	PDI	1	FOYER/HALL- NOTE:~EXPOSED NAIL AT RISER BELOW NOSING AT STAIRS TO BASEMENT	Stairfab 147052	Add	NoAppoint.		218
31Mar22	PDI	2	FOYER/HALL- STAIRS~DENTS ON FIRST TREAD AT STAIRS TO MAIN FLOOR	Stairfab 147053	Add	NoAppoint.		78
31Mar22	PDI	3	MASTER ENSUITE BATH- VANITY CABINETS~SMALL CHIP INSIDE LOWER DRAWER AT VANITY	New Image Kitchens 147054	Add	NoAppoint.	V	83
31Mar22	PDI	4	MASTER ENSUITE BATH- ELECTRICAL/LIGHTING~LIGHT FIXTURES ABOVE SINK TO BE REMOVED AS PER UPGRADES. ROUGH IN ONLY IN BOTH WASHROOMS	Mykon Electric North Ltd 147055	Add	NoAppoint.	/	J.
31Mar22	PDI	5	EXTERIOR~EXTERIOR PAINTING NOT COMPLETE	Perfect Touch Painting 147056	Add	NoAppoint.	X	
31Mar22	PDI	h	EXTERIOR- NOTE:~GARAGE SLAB NOT COMPLETE	Toronto Concrete & Drain 147058	Add	NoAppoint.		8/2
31Mar22	PDI		EXTERIOR- NOTE:~GARAGE DOORS NOT INSTALLED	Abbey Overhead Doors Inc. 147057	Add	NoAppoint.	/	8

Homeowner Signature:	
The Homeowner acknowled initialled work has been commanner to their satisfaction.	
Date: _ Zancor Service Technician: _	APR 20/02